

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20101212 MANATA KEK 12					
inspection date	2019	12	12	Report Number	20191212-WMATA-KEK-13					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	ATC	Sub- Department		Yard ATC Crews		
	Name			Email	Office Phone		Mobile Phone			
Rail Agency Department Contact Information										
Contact Information										
Inspection Location	E99 Greenbelt Yard – TCR (Y-145) - 5801 Sunnyside Ave, College Park, MD 20740									

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-OBS-RM					
Inspection Units	6 gate arms					
Inspection Subunits	0					
Defects (Number)	5					
Recommended Finding	5					
Remedial Action Required ¹	YES					
Recommended Reinspection	YES					

Activity Summaries

Inspection Activity #	1 Ir	spection Sub	ject	Monthly	/ Crossing Inspection – ATC Test 1014-A			Activity Code		STC		OBS	RM	
Job Briefing Employee Name/Title	WMATA RWIC –				mpanied ector?	YES	Out Brief Conducted	YES	Time	2230	pm	Outside Shift	YES	
Related Reports	N/A				Related CAPS / Findings N/A									
	Ref Rule or S			SOP Standard			Other / Title			Checklist Reference				
Related Rules, SOPs, Standards, or Other	Radio Communication					ATC - 1000					Form 1014			
Standards, or other				0 & M										
Inspection Location	Main Track	Yard	Stati	on C	СС	RTA Facility	WMSC Office Track Type		At-grade Tunnel		Elevated		N/A	
inspection Location		х						паск туре	х					
Line/o)	Green-Line Track Number				Chain Ma		ker		From			То		
Line(s)			er				ation(s)	Yard Tracks			Yard Tracks		S	
	Head Car Number		١	Number of Cars										
Vehicles	N/A			N/A E		Equip	ment	N/A						
Description	Test could not be performed due to crossing failure. East gate down. Logic failure. Number of Defects						s			#				

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY E. KENDRICK		12. 12. 2019
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	Washington Metrorail Safety Commission	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form


Form WMSC-IR-1

Washington Metrorail Safety Commission

	Will reschedule 30 days. Allowing WMATA to obtain appropriate parts needed to	Recommended Finding?	YES				
	bring crossing up to industry standards. Began inspections approximately 1031am. Left yard to have ATC department to	Remedial Action Required?	YES				
	restore crossing to proper working order approximately 1430pm. Observations to note; 1. WMATA needs to order new gate arms immediately. Please see pics. 2. No replacement parts; gate arms or lights for gates. (Replacements ordered 2 months ago, reportedly.) 3. Lights on gate arms of old crossing gates steady lite, making them out of standard. Should be corrected immediately to oscillate in sequence with rondels. 4. No plans at crossing. Plans at ATC location 500ft away 5. Prints of crossing layout should be placed in crossing case with changes marked appropriately with contractors' changes	Recommended Reinspection?	YES				
Remedial Action	required for inspecting, maintaining and testing rail grade crossing warning grade crossing warning system. Plans shall be stored in a waterproof and and contain no more than one set of field revisions. 3. APTA RT-RGC-S-001-02 – Section - 2.12 Records retention Records shall I Safety Oversight Policy. 4. APTA RT-RGC-S-001-02 – Section - 4.7 Gate arm lights and light cable Each specifically for use on a gate arm and maintained in such condition to be or LED units and required wire shall be properly secured to the gate arm 5. APTA RT-RGC-S-004-03, Rev. 2 -Section - 2.2.4 Processor-based systems processor-based systems, or where highway-rail grade crossing equipmed control system, rail transit properties should consider guidance provided	Reinspection crossing within 30 days. APTA Guidelines for WMATA APTA RT-RGC-S-001-02, Rev. 22 Plans Detailed circuit and layout plans depicting the current "as-in-service" condition a required for inspecting, maintaining and testing rail grade crossing warning systems. Plans shall be kept at each highway grade crossing warning system. Plans shall be stored in a waterproof and secure container. Plans shall be legible and corr and contain no more than one set of field revisions. APTA RT-RGC-S-001-02 — Section - 2.12 Records retention Records shall be maintained as determined by the RTS and States Safety Oversight Policy. APTA RT-RGC-S-001-02 — Section - 4.7 Gate arm lights and light cable Each gate arm light or LED unit shall be designed specifically for use on a gate arm and maintained in such condition to be properly visible to approaching highway users. Lor LED units and required wire shall be properly secured to the gate arm. APTA RT-RGC-S-004-03, Rev. 2 - Section - 2.2.4 Processor-based systems Where new or novel technology is being used wi processor-based systems, or where highway-rail grade crossing equipment provides safety-critical data to a signal or train control system, rail transit properties should consider guidance provided by 49 CFR 234.275 APTA RT-RGC-S-004-03, Rev. 2 – Section - 2.2.8 Flashing light units Flashing light units must conform to AREMA					

Photos:..





Form WMSC-IR-1 Version date: 10/5/18

2



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission







Form WMSC-IR-1 Version date: 10/5/18

3