

Inspection Form

Washington Metrorail Safety Commission

Form WMSC-IR-1

Agency/Department Information

Inspection Date	YYYY	MM	DD	Revent Number					
	2020	09	20	Report Number	20200920-WMATA-KEK-24				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Signals & ATC	Sub- Department ATCIN		ATCIN	
Rail Agency Department Contact Information		Name		Email Office Phone Mob			obile Phone		
Inspection Location	Signals/ATC and Communications								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-RR-QAI					
Inspection Units	09					
Inspection Subunits	13					
Defects (Number)	22					
Recommended Finding	NO					
Remedial Action Required ¹	NO					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1	Insp	ection Subj	ect	Records Review – Q&A					Activity Co	ode	STC COMM		RR	QAI
Job Briefing Employee Name/Title	N/A				Accompanied Inspector?		N/A	Out Brief Conducted	PENDIN	Time	2:00)(p)	Outside Shift	NO	
Related Reports	RTU 90 day				Relat	Related CAPS / Findings WMATA Syste			em Safety Program Plan 2019						
	Ref Rule or S			SOP		Standard		Other / Title			Checklist Reference				
Related Rules, SOPs, Standards, or Other	WMATA SSPP APT			APTA-TI	R-S-CS-0	27-03			REAM						
orandaras, or orner		ATPA-RT			-S-024-03										
Inspection Location	Mai Trac		Yard	Stati	on OCC		RTA Facility	WMSC Office	Track Type	At-grade	e Tur	nnel	Elev	ated	Interlock
	x		x	х					таск туре	x	:	x)	x	x
	All-Lines Track				Mainline Chain Ma and/or St		Chain Marker		From	From		То			
Line(s)			Number				wani	Station(s)	ation(s) System		Syste		m		
	N/A			N/A											
	Reliability review of ATC & Signal, and Communications Department failures.								Number	Number of Defects 22			22		
Description	PURPOSE:									Recommended Finding?					YES
										Redial A	ction Req	uired?		Р	ending

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature KEMMERY ELAENE KENDRICK		Date 09/20/2020
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	WASHINGTON METRO SAFETY COMMISION (WMSC) - SIGNALS & AUTOMATIC TRAIN CONTROL	SUBJECT MATTER EXPERT



Inspection Form

Washington Metrorail Safety Commission

	 Inspection generated due to WMSC concern of recent frequency of switch and RTU failures. A report was generated by the Department Reliability Engineering & Asset Management for assistance. GOVERNING COMPLIANCE STANDARD: WMATA System Safety Plan (SSPP)-2019, page 84. Investigation of Repetitive Events, which states that Engineering, Statistical Review, and SAFE Managers reviews SMS, MAXIMO and other data which includes searching for repetitive events that might have safety implications. WMATA SSPP, page 200 - Investigation of Repetitive Events states; "The ATC & Signals Department has built in integrated, designed procedures, people and all other elements of a transit system using the principles of fail safety and system safety in such a manner that equipment failures or personnel errors, or combinations of both, must not result in an increased hazard level." WMATA SSPP page 200. In accordance with WMATAS SSPP-2019-page 54; Engineers review computerized reports after each rush hour and investigate "every" anomaly they identify, and ATC then takes immediate actions to correct them. In some cases, the problem can't be corrected quickly, while other take more time. In the instances where repairs are lengthy, ATC may temporarily take a track circuit out of service to work on a repair. When a track circuit is disabled or deactivated for repair, trains are slowed to 15 mph through the affected area. Train operators maintain radio contact with controllers in the ROCC. NOTABLE ITEMS; June 2020 – August 2020 Reliability Report: The highest RTU failures are of concern are at J01-Quarker Lane, with at least 2 RTU anomalies. Investigation pending on manufacture type. Informed by the ATC & Signals Manager that the RTU Failures are a Communications Department item and discussion should focus repetitive reports to that department on their equipment. RTU Failures component malfunctions are attached i	Recommended Reinspection?	YES
Remedial Action	 My recommendation would be to forward report to the <u>Department of I</u> that department is responsible for driving improvement Authority-wide, objectives, addressing corrective actions. ATC Branch Maintenance Control Policy – State of Good repair states "It maintain systems within a state of good repair give the limitations of logi authorized budget." Page #30. Awaiting instructions from WMSC Management with remedial actions. 	and assures departments are fulfillin is the policy of the Automatic Train C	g business Control Branch to