

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY	YYYY MM		Report Number	20210322-WMATA-LBW-2				
Inspection Date	2021	03	19	Report Number	20210322-WWATA-LBW-2				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Operations Sub- Departme		nent	Vehicles	
	1	Name		Email	Office Phone		Mobile Phone		
Rail Agency Department Contact Information									
Inspection Location	Greenbelt '	Yard							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	RTRA-GEN-OBS					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	8					
Recommended Finding	No					
Remedial Action Required ¹	Yes					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1 Inspection Radio				lio Comm	Communications – Greenbelt Yard				Activity Code		RT	RA	GEN	OBS	
Job Briefing Employee Name/Title	Greenbelt Interlocking Operator and S/I Supervisor					Accompanied Inspector?		NA	Out Brief Conducted	Yes Time		11	30	Outside Shift	Yes	
Related Reports	N/A Related CAPS / Findings															
Related Rules,	Ref				Rule	or SOP			Standard		Other /	Title		Checklist Reference		
SOPs, Standards,	ds,															
or Other																
Inspection Location	Mai Trac		Yard	Stat	tion	осс		RTA WMSC Facility Office		Track Type	At-grad	e Tu	nnel	Ele	vated	N/A
Location			X								X					
Line(s)	E-99		Track				Chain Marker F			rom			То			
Line(s)	E-99		Numb	oer			ar	nd/or St	ation(s)	NA	NA					
Vehicles	Head	d Car I	Number	1	Numb	er of Car	S	Equipment								
vernicles								Equip	ment							
Description	Yard.	This	inspection	on res	sulted		o SA	AFE inci	dent repor	eenbelt Rail ts E20350					8	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	oran Salety Commission		
	E20350 is a red signal overrun in the Greenbelt Yard on September 15, 2020. A Train Operator assigned to move rail incorrectly repeated back instructions from the Interlocking Operator and followed those incorrect	Recommended Finding?	No
	instructions rather than the instructions provided. The Interlocking Operator attempted to correct the mistaken repeat back, but the train operator did not acknowledge that correction. Both the Train Operator and the Interlocking Operator stated that there are known radio communications issues in the Greenbelt Yard that have not been	Remedial Action Required?	No
	E20280 involves a derailment in the Greenbelt Rail Yard on July 30th, 2020. The interlocking operator, who is responsible for yard operations, only learned of the derailment approximately 26 minutes after it occurred when a ROCC Assistant Superintendent called to ask for more information. The Interlocking Operator attempted to contact PM58 via radio two different times at 23:38:43 and 23:39:38 and was unsuccessful. The interlocking operator did not reach the work crew on the radio, so the interlocking operator had to leave the tower to determine what happened		
	The radio inspection was accomplished by performing radio checks with the Greenbelt interlocking operator from various locations throughout the rail storage yard. The inspector also monitored radio communications of the interlocking operator and WMATA personnel in the performance of their duties. Prior to beginning the inspection, the WMSC inspector conducted a briefing with the Greenbelt Yard interlocking operator to discuss the inspection activities. The WMSC inspector also conducted a second briefing with the shop supervisor prior to beginning the radio inspection within the service and inspection facility.		
	An exit briefing was conducted with the interlocking operator and the Greenbelt Yard operations superintendent.	Recommended Reinspection?	Yes
	Radio Check Locations E99-190 outside the paint shop Lead tracks 25 South Lead tracks 7 North Lead tracks 4 North Lead tracks 1 North (Car Wash) Lead tracks 2 South Lead tracks 5 South Bump post track 16 (Communication inconsistent) E99-132 track 16 from car 3159 Lead tracks 18 North (Communication inconsistent) Lead tracks 19 North (Communication inconsistent) Bump post track 7 (Communication inconsistent) Bump post track 3 Track 3 walking through listening (Communication inconsistent) Track 3 open end at E99-106 (Communication inconsistent) Car 2058/9 lead track to Door 26 (Operator could not hear I/O) E99-44 and E99-48 (Operator could not hear I/O) I/O requested multiple radio repeat conformations Inside S&I Shop 3 South (Communication inconsistent) 5 South (blow pit) (Failed radio check)		

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Remedial Action	N/A	
	4 South (blow pit) (Failed radio check) As clear and effective communications within the Greenbelt Rail Yard are vital for the safety of personnel and equipment, the WMSC inspector is recommending additional inspections. The lack of consistent radio communications at the Greenbelt Yard needs to be addressed immediately.	
	4 South (blow pit) (Failed radio check)	

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date 03/22/21
Inspector in Charge – Name Bruce Walker	Inspection Team Bruce Walker	

Form WMSC-IR-1 Version date: 10/5/18