

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY/MM/DD	Report Number	20210823-WMATA-KEK-29			
Inspection Date	2021/08/27	Report Number	20210052-MINIATA-VEV-53			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	WMATA	Contact Information				
Inspection Location	Greenbelt Station Signals & ATC TCR					

Inspection Summary

Inspection Activity #	1
Activity Code	STC/QAI/OBS
Inspection Units	1
Inspection Subunits	3
Defects (Number)	5
Recommended Finding	No
Remedial Action Required ¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1 Inspection Sub			eject E10 HF track Circuit Testing & Verification				Activity Code			STC/QAI/OBS				
Job Briefing Employee Name/Title				Accompanied Inspector?		Yes	Out Brief Conducted	Time		09:00 AM		Outside Shift	No		
Related Reports				Related CAPS / Findings					•		•	•			
Related Rules,	Ref R			Rule or SOP			Standard		Other / Title			Checklist Reference			
SOPs, Standards, or Other	WMATA ASP, PTASP											1012A - Rev 4.0, and 1018P - Rev 4.0 forms			
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office	Track Type	At-grade	Tunn	el	Eleva	ted	N/A	
	Х		Х						Х						
Line(s) & Track	Greenbelt Station Signals & ATC TCR			CR	Chain Ma	rker and/	or Station(s)		From		То				
Number						549 +/- 46			668 +/- 00						
Vehicles	Head Car Number N			Number of Cars Equipme		ent		Module, Test Jumpers, .06 ohm shunt strap, Multi-Mete					er		
	N/A N/A 1.1 (DMM)-Fluke 123 (Cal Dat									22)					
	WMATA Greenbelt Station Signals and Automatic Train Control Ro (1) Testing train detection carrier frequency Tx/Rx signal levels a						•	, ,	Number of Defects					5	
	(proper freq		Recommended Finding?					No							
	the vital inp		Remedial Action Required?			Yes									
	(track circui														
	peak. 3-point inspection (power in/out) Noted Items: 1. Five (5) track circuits were found to be outside the 10 percent, plus, minus tolerances due to purposely placed obstructions														
Description	on and about the tracks, within the Greenbelt Station, still under construction with ETO in														
	place. Track Circuit E1-668 has been adjusted. The remaining Track Circuits found outside														
	the tolerance levels left as found with a CM ticket created for correction by the morning Supervisor. Visual track inspection during shutdown performed by team for possible Recommended Reinspection?											Ye	es		
	cause for anomalies are noted as; disconnected SSR cables (E1-657+30 – RX bond for E1-														
	650), as well as a shunt dropped for shutdown work zone setup. 2. Radio communications														
		within TCR poor. Supervisor had to stand outside the TCR door to communicate to													
	roadway workers dropping shunts. Supervisor stated that he would put in a ticket to the Comm Department to troubleshoot. 3. All employees had appropriate PPE for testing.														
	When ETO is removed and all track connections are reintroduced into the section of territory the inspection for Track Circuit Verification must be repeated before systems														
Remedial Action	are returned to service.														

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2021/08/27
Inspector in Charge's Name Kemmery Kendrick	Inspection Team N/A	

Form WMSC-IR-1 Version date: 1/17/2022