

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	20220622-WMATA-LBW-01			
	2022/06/22	Report Number				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	Roadway Worker Protection	Contact Information				
Inspection Location	Roadway inbound of Minnesota Avenue Station					

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	8
Recommended Finding	Yes
Remedial Action Required ¹	No
Recommended Reinspection	

Activity Summaries

Inspection Activity #	1	Insp	ection Subj	ect	Track and Structures Audit				Activity (
Job Briefing Employee Name/Title	Not completed by the Roadway Worker in Charge as required.			Accompanied Inspector?		Yes	Out Brief Conducted	Yes Time		ΠΧ-ΠΟ ΔΙΜ		Outside Shift	Yes		
Related Reports				Related CA	PS / Findin	ıgs									
	Ref Ru			or SOP			Standard		Other / -	Title			Checklist Reference		
Related Rules, SOPs, Standards, or Other				5.5 Roadway Job Safety Briefing (RJSB) 5.11 Personal Protective Equipment (PPE) Standard for On-Track Safety 5.2.1 RWP Cardinal Rules 5.10.7 Watchman/Lookout Policy instruction 10.3/5 â¿¿ Electronic Device Policy 5.12.2 Safety Equipment and Warning Devices											
Inspection Location	Main Track X	Yard	Station	OCC	RTA F	acility	WMSC Office	Track Type	At-grade		Tunne	:I	Elevated N/A		N/A
Line(s) & Track		hound of *	linnoca+-	Avonus						X			X		
Number	Roadway inbound of Minnes Station			Chain Marker and/o			or Station(s)		FIOIII	From			То		
Vehicles	Head Car	Number	N	umber of C	ars	Equipm	ent								
				ducted a scheduled Track Audit inspection of thermite			Number of Defects				8	8			
	wielding on the D Line track 2. An overview meeting was held at the New Carrolton yard field office where instructions were provided to regroup at Minnesota Avenue Station								Recommended Finding?				Ye	Yes	
Description	field office where instructions were provided to regroup at Minnesota Avenue Station. As this was an audit activity, the inspection team noted all rules violations but did not intercede. The scheduled work activity was within the Metrorail authorized construction site (ACS). An ACS in a protected area where traction power is removed and there with no WMATA vehicle movement. The ACS allows contractors to work on Metrorail's right of way without Roadway Worker Protection (RWP). During the audit activity, Metrorail did not follow its own RWP procedures to protect its workers. The following violation were observed during the course of the audit. 1. No Roadway Job Safety Briefing (RSJB) was provided before entering the roadway from Minnesota Avenue station to the work location and beginning work and audit activities. 2. After entering the WMATA roadway at Minnesota Avenue Station, multiple employees were observed walking on the roadway both before and while vehicles were moving wearing a backpack covering the required High Visibility Safety Apparel. 3. A heavy equipment operator of a prime mover was observed operating and moving equipment and supplies with the crane above and around their body without wearing head protection. 4. Employees were observed performing thermite welding and the removal of hot waste material utilizing only mechanic work gloves. 5. Personnel were walking in the work area with vehicle movement in their direction from behind with a no clearance area to the left and the center walkway being used to store construction debris. There was no watchman lookou for this vehicle movement or while the prime mover was being moved around the work crew. 6. A roadway worker was observed talking on a cell phone while walking between the running rails within the working limits while a vehicle was in approach to their back 7. During the work activities a Warning Strobe Alarm Device (WSAD) was present and adjacent to the running rails but not installed. 8. During the work activity of Thermite Welding, a fire ext							I construction d there with prail's right of letrorail did plation were (RSJB) was ne work ATA roadway on the covering the prime mover ne above and served ng only hicle eft and the chman lookout and the work king between a to their back. resent and f Thermite					N	JO.	



Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission


Remedial Action




Washington Metrorail Safety Commission

Photos:

20220<u>622_082048.jpg</u>









20220622_094111.jpg



20220622_095544.jpg





Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission

20220622_101319.jpg



1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action. Closeout of Kemedian Actions may also be subject to origining wivisc verification inspections to ensure corrections are sufficient and effective.							
Inspector in Charge's Signature	Date 2022/06/22						
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team Jermayne Walker Tiffany Minor						