

#### WMSC Commissioner Brief: W-0235 – Evacuation for Life Safety Reasons at Clarendon Station – March 7, 2023

Prepared for Washington Metrorail Safety Commission meeting on August 8, 2023

#### Safety event summary:

On March 7, 2022, Clarendon Station was evacuated due to the report of smoke in the station.

A rider exiting Clarendon Station reported smoke on the platform to the Station Manager. The Station Manager went to the platform and confirmed there was smoke entering the station. The Station Manager returned to the station kiosk and notified the Rail Operations Information Center at 8:08 a.m. that smoke was entering the station from the tunnel on Track 1, that it was restricting the view of Train Operators, and that they were evacuating the station. The station was evacuated.

A Metro Transit Police Department (MTPD) Liaison in the Rail Operations Control Center contacted the Security Operations Control Center (SOCC) to request MTPD respond. An MTPD Dispatcher called Arlington County for a fire department response.

The Fan Desk activated emergency ventilation fans at 8:20 a.m., and smoke subsequently dissipated.

The Radio Rail Traffic Controller instructed the Train Operator of an out-of-service train to perform a track inspection. That Train Operator and a secondary inspection by Metrorail's Emergency Response Team did not identify additional smoke or fire.

There were no injuries or infrastructure damage identified and no rail cars were identified to have mechanical issues such as a stuck brake that might have caused the event.

#### Probable Cause:

The probable cause of this event was smoke in the tunnel from an unknown source.



# Washington Metropolitan Area Transit Authority Department of Safety (SAFE) Office of Safety Investigations (OSI)

# FINAL REPORT OF INVESTIGATION A&I E23155

Date of Event:	March 7, 2023
Type of Event:	Evacuation for Life Safety Reasons – Smoke
Incident Time:	08:08 hours
Location:	Clarendon Station, track 1
Time and how received by SAFE:	09:21 hours
	Mission Assurance Coordinator (MAC)
WMSC Notification Time:	09:21 hours
Responding Safety Officers:	WMATA: None
	WMSC: None
	Other: None
Rail Vehicle:	None
Injuries:	None
Damage:	None
Emergency Responders:	Arlington County Fire Department (ACFD),
	Metro Transit Police (MTPD)
SMS I/A Incident Number:	20230308#106705

#### **Clarendon Station**

# March 7, 2023

# **Table of Contents**

Abbreviations and Acronyms	3
Executive Summary	
Incident Site	5
Field Sketch/Schematics	5
Purpose and Scope	
Investigation Methods	5
Investigation	
Chronological ARS Timeline	7
Interview Findings	
Station Manager (Informal Interview)	9
RTRA Supervisor (Written Incident Report)	9
Weather	9
Advanced Information Management System (AIMS)	-10
Human Factors	-10
Evidence of Fatigue	-10
Post-Incident Toxicology Testing	-10
Findings	
Immediate Mitigation to Prevent Recurrence	-11
Probable Cause Statement	
Recommended Corrective Actions	
	-12
Appendix A – Interview Summary	
Appendix B – RTRA Supervisor's Incident Report	
Appendix C – ROCC Incident Report	
Appendix D - MTPD Incident Report	-18
Appendix E - RTRA Supervisor Written Statement	
Appendix F – PLNT Emergency Tunnel Fan Operation Form	-21

#### **Abbreviations and Acronyms**

ACFD	Arlington County Fire Department
САР	Corrective Action Plan
ссти	Closed-Circuit Television
ERT	Emergency Response Team
MTPD	Metro Transit Police Department
MSRPH	Metrorail Safety Rules and Procedures Handbook
NOAA	National Oceanic and Atmospheric Administration
RTRA	Office of Rail Transportation
ROCC	Rail Operations Control Center
ROIC	Rail Operations Information Center
RTC	Rail Traffic Controller
SAFE	Department of Safety
SMS	Safety Measurement System
WMATA	Washington Metropolitan Area Transit Authority
WMSC	Washington Metrorail Safety Commission

#### **Executive Summary**

\*Note that all times listed are approximate and may contain minor variations due to differences between systems of record. \*

On Tuesday, March 7, 2023, at 08:08 hours, an Office of Rail Transportation (RTRA) Station Manager located at Clarendon Station reported to the Rail Operations Information Center (ROIC) that there was smoke entering the station from the tunnel on track one. The Station Manager reported that the smoke was producing limited sightlines for the incoming train traffic, and they were evacuating the station. The Rail Operations Control Center (ROCC) Radio Rail Traffic Controller (RTC) requested an RTRA Rail Supervisor to respond to Clarendon Station and requested tunnel fan activation.

At 08:10 hours, the Metro Transit Police Department (MTPD) Liasion located within ROCC advised MTPD Dispatch that smoke was reported at Clarendon Station. The MTPD Dispatch requested units to respond. MTPD contacted and requested the Arlington County Fire Department (ACFD) to respond. At 08:15 hours, an MTPD Unit reported they were located at Clarendon Station. At 08:16 hours, the ACFD arrived and established the Incident Command Post at the entrance to Clarendon Station.

At 8:22 hours, the Radio RTC instructed non-revenue Train ID 902 to perform a track inspection. There was no source of smoke or any fire found. The smoke dissipated with assistance from the tunnel fans.

No rail cars were identified with potentially associated mechanical issues (e.g., stuck brake) within three days of the event. At 08:31 hours, ACFD deemed the station clear and no further inspections were necessary. The scene was turned over to MTPD.


At 08:41 hours, an MTPD Unit gave the all-clear following secondary track inspections by Emergency Response Team (ERT) personnel. Emergency Response Team (ERT) reported negative findings of smoke or burning odor. The MTPD Unit reported no fire found and turned the scene over to RTRA. At 09:03 hours, revenue service resumed.

The probable cause for the evacuation for life safety reasons event was light, odorless smoke from an unknown source that was drawn into the station by a train entering. There were no significant findings related to the response and recovery from this event.

# Incident Site

Clarendon Station, track 1

# **Field Sketch/Schematics**



\*Locations are approximate. Not to scale.

## Purpose and Scope

The purpose of this incident investigation and candid self-evaluation is to collect and analyze available facts, determine the probable cause(s) of the incident, identify contributing factors, and make recommendations to prevent a recurrence.

#### Investigation Methods

Upon receiving notification of the Evacuation for Life Safety Reasons event at the Clarendon Station on March 7, 2023, SAFE dispatched a cross-functional team to assess the scene and conduct the subsequent investigation. SAFE team members worked with relevant WMATA subject matter experts to review the incident's facts and data.

The investigative methodologies included the following:

- Site assessment through video and document review
- Informal Interviews Collected through conversations with individuals during the investigation to provide background and supporting information. Written statements were reviewed by personnel present during the event.
  - Supervisor's Incident Report
  - Station Manager Incident Report
- Documentation Review A collection of relevant work history information and process documentation contained in Metro systems of record. These records include:
  - Metrorail Safety Rules and Procedures Handbook (MSRPH)
  - National Oceanic and Atmospheric Administration (NOAA)
  - Rail Operations Control Center (ROCC) Incident Report

- System Data Recording Review A collection of information contained in Metro Data Recording Systems. This data includes:
  - Audio Recording System (ARS) playback, including OPS 3 Radio
  - Closed-Circuit Television (CCTV)
  - ROCS SPOT Report
  - MTPD Incident Report
  - Open MHZ system
  - Advanced Information Management System (AIMS)

# **Investigation**

On Tuesday, March 7, 2023, at 08:08 hours, an RTRA Station Manager located at Clarendon Station reported an emergency to the ROIC of smoke entering the station from the tunnel on track one. The Station Manager reported that the smoke produced limited sightlines for the incoming train traffic, and they were evacuating the station. The ROCC Radio Rail Traffic Controller requested an RTRA Rail Supervisor to respond to Clarendon Station and requested tunnel fan activation.



Figure 1 Light Haze of smoke observed -Platform level.



Figure 2 Inbound Train on the Platform -smoke emitting from the tunnel

Incident Date: 3/7/2023 Time: 08:08 hours Final Report – Evacuation for Life Safety Reasons E23155 Drafted By: SAFE 706 – 05/02/2023 Reviewed By: SAFE 71 – 05/08/2023 Approved By: SAFE 71 – 05/08/2023



Figure 3 Train exiting station-smokes continues to enter the station.

At 08:10 hours, the MTPD Liasion located within ROCC advised MTPD Dispatch that smoke was reported at Clarendon Station. The MTPD Dispatch requested Units to respond. At 08:15 hours, an MTPD Unit reported they were located at Clarendon Station. At 08:16 hours, the ACFD arrived and established the Incident Command Post at the entrance to Clarendon Station.

At 08:22 hours, the Radio RTC instructed Train ID 902 to perform a track inspection, and no fire was reported. The haze dissipated with the assistance of the tunnel fans. At 08:31 hours, ACFD deemed the station clear, and no further inspections were necessary. The scene was turned over to MTPD.

At 08:41 hours, an MTPD Unit gave the all-clear based on the secondary track inspections by ERT personnel. The MTPD Unit reported no fire found, ERT reported no burning odor and turned the scene over to RTRA. At 09:03 hours, revenue service resumed.

# **Chronological ARS Timeline**

A review of ARS playback, i.e., phone and radio communications, revealed the following timeline:

Time	Description
08:08:34 hours	Station Manager: Reported smoke condition in the station. They report limited sightlines and notified the ROCC that they are evacuating the station.
	Information Controller: Acknowledged and repeated. [Radio OPS 5]
08:09:19 hours	<u>Operations Manager</u> : Inquired about the evacuation, instructed the AOM to offload trains at Court House Station and utilize them as inspection trains. <u>Assistant Operations Manager</u> : Acknowledged and repeated. [Phone]
08:10:38 hours	<u>MTPD Dispatcher</u> : ROCC 1 reported smoke in the tunnel at Clarendon Station, and there were no trains in the tunnels. Requested MTPD units to respond to Clarendon and Court House Stations. [MTPD 1X]
08:10:40 hours	Radio RTC: Train 902 offloaded customers at Court House Station. "We have a report of smoke at Clarendon. Turn off EV and advise when offloaded." <u>Train 902</u> : Acknowledged and repeated. [Radio OPS 2]
08:12:00 hours	ACFD arrived on scene. [CCTV]
08:12:13 hours	Radio RTC: Announced to Train Operators to make announcements of a smoke condition at Clarendon Station, delays expected. [Radio OPS 2]
08:12:32 hours	ACFD: Reported smoke condition at Clarendon Train Station. [Open MHZ]

Time	Description
8:13:55 hours	<u>RTC Radio</u> : Requested Train ID 902 [now ID 702] to conduct a track inspection on track 2. Instructed the Train Operator to turn off the EV. <u>Train ID 902</u> : Acknowledged and repeated. [Radio OPS 2]
08:15:29 hours	<u>MTPD Unit</u> : Arrived at Clarendon Station and requested the Fire Department. Reported moderate smoke coming from the tunnels. [MTPD 1X]
08:16:25 hours	<u>ROCC1</u> : Inquired if [Unit#1] was designated as the Incident Commander. [Radio MTPD1X]
08:16:36 hours	<u>ACFD</u> : Established Incident Command Post at the top side of Clarendon Station. [Open MHZ]
08:17:16 hours	ACFD: Reported a light haze and that the station was evacuated. [Open MHZ]
08:17:37 hours	<u>MTPD Unit</u> : Reported light smoke in the station, and the station was evacuated. [MTPD 1X]
08:19:02 hours	<u>ROCC 1:</u> Asked If an Incident Command was established. Updated that a track inspection was being performed. [Radio MTPD1X]
08:20:08 hours	Emergency Fans are activated in the area of Clarendon Station [AIMS]
08:20:32 hours	<u>MTPD Unit</u> : Reported that the Command Post was established at the top side of Clarendon with Arlington Fire Department and the Station Manager. [MTPD 1X]
08:21:32 hours	<u>MTPD Unit</u> : Reported the tunnel inspection was completed from Clarendon to Court House with negative results on fire conditions; smoke and haze in the tunnel was dissipating. [MTPD 1X]
08:22:02 hours	<u>Train ID 902</u> : Train Operator reported the all-clear for the track inspection. The train operator said that they smelled something but did not observe any track obstructions. [Radio OPS 2]
08:22:01 hours	ROCC#1 reports that fans are operational. [Open MHZ]
08:22:57 hours	<u>MTPD Unit</u> : Reported that ACFD is clearing, and the inspection was completed. [Radio MTPD 2X]
08:23:10 hours	Assistant Operations Manager updated the Operations Manager that track inspections were clear, and no fire or smoke condition (brake dust) were found. [Phone]
08:23:58	ACFD reported good track inspections; smoke had dissipated. [OpenMHZ]
08:26:35 hours	MTPD: Reported that ERT was on the scene. [MTPD 2X]
08:26:46 hours	<u>MTPD</u> : Reported a good track inspection. Tunnels clear of smoke. [MTPD 2X]
08:27:53 hours	Operations Manager confirmed the shuttle bus service and instructed to close the station until the scene was released. [RAIL#1]
08:31:50 hours	ACFD reported all clear, and no further inspections were needed.
08:35:46 hours	Operations Managers updated Assistant Operation Manager that ACFD cleared to resume normal operations. MTPD requested a secondary inspection. [Radio Rail1]
08:41:10 hours	<u>MTPD</u> : Reported all clear at Clarendon Command Post after a secondary track inspection. Noted that no fire was found. [MTPD 2X]
08:41:27 hours	Incident Command Post released the channel and instructed all units were instructed to go back in service. [MTPD 2X]
09:03:00 hours	Normal Service resumed. [Radio Ops2]
**Note: Times abou	re may vary from other systems' timelines based on clock settings and reporting sources

\*\*Note: Times above may vary from other systems' timelines based on clock settings and reporting sources

# **Interview Findings**

As part of the investigation launched into the event, SAFE interviewed one employee. The interview identified the following key findings associated with this event. The findings detailed below include reported information from involved personnel and may conflict with other data sources contained in the report.

#### Station Manager (Informal Interview)

- The Station Manager stated that the train entered the station on the track 1 side and received notification from an exiting customer of a smoke condition on the platform.
- The Station Manager stated that they began their investigation and walked to the platform, where they observed an "extreme smoke condition" coming from the tunnel on the track 1 side.
- The Station Manager stated that they returned to the Kiosk and notified the ROCC of the current situation and began the evacuation process for safety reasons.
- The Station Manager further stated that the entire platform and tunnels were billowing smoke which produced limited sightlines for train operation and customer safety.
- The station manager stated that the smoke condition began to dissipate with the operation of the tunnel fans and ventilation efforts from the ACFD.


#### RTRA Supervisor (Written Incident Report)

- The RTRA Supervisor stated that they were contacted by the ROCC to respond and assist with an Evacuation for Life Safety Reasons that occurred at Clarendon Station.
- The RTRA Supervisor stated that they responded to Virginia Square Station and assisted in the offloading of customers on Train ID 604 and utilized Train ID 604 as an inspection train.
- The RTRA supervisor said they conducted a track inspection from Virginia Square to Clarendon Station, where they observed light smoke.
- The RTRA Supervisor stated that after a unified investigation, it was concluded that the smoke dissipated, and the station resumed revenue service.

#### Weather

On March 7, 2023, at the time of the incident, NOAA recorded the temperature as  $52^{\circ}$ F, with clear skies. The weather did not contribute to this incident (Weather source: NOAA) – Location: Arlington, VA.

#### Advanced Information Management System (AIMS)



08:20:08.749 03/07/23	<mark>Clarendon</mark>	UPE IB Fan Exhaust COMMANDED Supply BY 015175 AT ctwkspower9pp
08:20:08.749 03/07/23	<mark>Clarendon</mark>	UPE IB Fan On COMMANDED Emergency On BY 015175 AT ctwkspower9pp
08:20:09.905 03/07/23	<mark>Clarendon</mark>	UPE IB Fan Status COMMANDED CHANGE = Emergency On
08:20:09.905 03/07/23	Clarendon	UPE IB Fan Orientation COMMANDED CHANGE = Supply
08:20:10.796 03/07/23	Shaw/Howard U	FE3 Fan Shaft Damper CURRENT STATE = Abnormal ALARM FINAL ACK. BY SYSTEM AT ctsc-hostapva
08:20:11.874 03/07/23	Clarendon	UPE OB Fan Exhaust COMMANDED Supply BY 015175 AT ctwkspower9pp
08:20:11.874 03/07/23	<mark>Clarendon</mark>	UPE OB Fan On COMMANDED Emergency On BY 015175 AT ctwkspower9pp
08:20:13.032 03/07/23	SYSTEM	A work Crew(7913) is added on Track E06-E1-276 By 004984 At ctwksyg-wkstpp
08:20:13.298 03/07/23	Clarendon	UPE OB Fan Status COMMANDED CHANGE = Emergency On
08:20:13.298 03/07/23	<mark>Clarendon</mark>	UPE OB Fan Orientation COMMANDED CHANGE = Supply
08:20:13.298 03/07/23	<mark>Clarendon</mark>	UPE OB Fan Orientation CURRENT STATE = Supply
08:20:19.579 03/07/23	Glenmont	TRAIN U12 ENTERED MONITORED TERRITORY AT TRACK CIRCUIT: B11-B2-733
08:20:20.689 03/07/23	Greenbelt	TRAIN 503 TURNBACK ON TRACK E10-E1-662
08:20:20.689 03/07/23	Greenbelt	TRAIN 503 TWC DESTINATION CODE 43 ACCEPTED FROM FIELD
08:20:22.019 03/07/23	Clarendon	FK2 Fan Exhaust COMMANDED Supply BY 015175 AT ctwkspower9pp
08:20:22.019 03/07/23	<mark>Clarendon</mark>	FK2 Fan On COMMANDED Emergency On BY 015175 AT ctwkspower9pp
08:20:22.863 03/07/23	Glenmont	TRAIN 115 TURNBACK ON TRACK B11-B2-719
08:20:23.566 03/07/23	Clarendon	FK2 Fan Status COMMANDED CHANGE = Emergency On
08:20:23.566 03/07/23	<mark>Clarendon</mark>	FK2 Fan Orientation COMMANDED CHANGE = Supply
08:20:23.973 03/07/23	Glenmont	TRAIN U12 EXITED FROM TRACK B11-B2-733
08:20:25.176 03/07/23	Court House	UPE IB Fan Exhaust COMMANDED Supply BY 015175 AT ctwkspower9pp
08:20:25.176 03/07/23	Court House	UPE IB Fan On COMMANDED Emergency On BY 015175 AT ctwkspower9pp
08:20:27.973 03/07/23	Court House	UPE OB Fan Exhaust COMMANDED Supply BY 015175 AT ctwkspower9pp
08:20:27.973 03/07/23	Court House	UPE OB Fan On COMMANDED Emergency On BY 015175 AT ctwkspower9pp
08:20:34.866 03/07/23	Clarendon	K02-2 Fresh Air AHU Fan CURRENT STATE = Normal ALARM FINAL ACK. BY SYSTEM AT ctsc-hostapva
08:20:43.619 03/07/23	Pentagon	C07-1 Battery Room Ventilation Fan CURRENT STATE = No ALARM FINAL ACK. BY SYSTEM AT ctsc-hostapva
08:20:45.806 03/07/23	Court House	UPE IB Fan Orientation CONTROL FAILURE = Supply TIMEOUT
08:20:47.713 03/07/23	<mark>Clarendon</mark>	K02-1 Fresh Air AHU Fan CURRENT STATE = Normal
08:20:47.713 03/07/23	<mark>Clarendon</mark>	K02-2 Fresh Air AHU Fan CURRENT STATE = Abnormal
Figure 5 - AIMS Eve	ent Log indicatin	a Fan Activation
I Iguic C AINO LVC	in Log malcalin	g r an Adivation

#### Human Factors

#### Evidence of Fatigue

The biomathematical fatigue modeling application (SAFTE-FAST Web SFC) was not applied for this event.

#### Post-Incident Toxicology Testing

This incident did not meet the criteria for WMATA's Drug and Alcohol Policy and Testing Program 7.7.3/6

#### <u>Findings</u>

• Smoke condition was identified by a customer, which was relayed to ROIC by the Station Manager immediately.

- Riding track inspections on Tracks 1 and 2 and walking inspections performed by ERT did not identify the source of the smoke. No infrastructure damage was found.
- SOP 1A protocols were implemented during the event.
- Reopening of the station was decided in coordination with the Fire Department.

# Immediate Mitigation to Prevent Recurrence

- Clarendon Station was closed to customers.
- Station exhaust fans were activated to dispel the smoke.
- Track inspections were conducted to ensure track safety.
- ACFD responded to the station and deemed the station safe in coordination with WMATA personnel.
- An After-Action Review meeting was held to review the event and resolve any command issues.

# Probable Cause Statement

The probable cause for the evacuation for life safety reasons event was light, odorless smoke from an unknown source that was drawn into the station by a train entering. There were no significant findings related to the response and recovery from this event.

# **Recommended Corrective Actions**

No corrective actions were identified for this event.

# **Appendices**

## Appendix A – Interview Summary

The below narratives summarize the incident and represent the statements made by the involved individual. As such, times and details may present a conflict with the data contained in systems of record.

#### Station Manager (Informal Interview)

The Station Manager is a WMATA employee with twenty-two years of service and ten years of experience as a Station Manager. The Station Manager holds a Roadway Worker Protection (RWP) Level 2 certification that expires in February 2024.

The Station Manager stated that the train entered the station on track#1 side and received notification from an exiting customer of a smoke condition on the platform. The Station Manager stated that they began their investigation and walked to the platform where they observed an extreme smoke condition coming from the tunnel on the track 1 side. The Station Manager stated that they returned to the kiosk and notified the ROCC of the current situation and began the evacuation process for safety reasons. The Station Manager further stated that the entire platform and tunnels were billowing smoke which produced limited sightlines for train operation and customer safety. The station manager stated that the smoke condition began to dissipate with the operation of the tunnel fans and ventilation efforts from the ACFD.

## RTRA Supervisor (Written Incident Report)

The RTRA Supervisor reported that they were contacted by the ROCC to respond and assist with an Evacuation for Life Safety Reasons that occurred at Clarendon Station. The RTRA Supervisor stated that they responded to Virginia Square Station and assisted in the offloading of customers on Train ID 604 and utilized Train ID 604 as an inspection train. The RTRA supervisor stated that they conducted a track inspection from Virginia Square to Clarendon Station where they observed light smoke. The RTRA Supervisor stated that after a unified investigation, it was concluded that the smoke dissipated, and the station resumed revenue service.

M			A SUPERVISOR			
Date 3/7/2023	Incident Time 8:15 AM		ation (Station Mez arendon / Mezz 97			lezzanine # ks 1 & 2
Equipment Numb	er (Train ID & Car I	Numbers; Escala	ator/Elevator #) N/A			
Incident Descripti	on		Smoke reported in	station		
W/MATA Perc	onnel Involved	Employee		plation?	Home Division	Post Incident
		Cinpioyee	N		WFC	No
Customer	Information (De	to the data for the				11 12 11
Name	Information (De		ation must be re	corded on	Station Manager In	
N	Ά	Address	N	/A.		Injury? N/A
Name		Address				Injury?
Name		Address				Injury?
				ding (Use S	supplemental sheet	if necessary)
Arrival Time	Unit Number	F	Person In Charge			marks
8:05 AM	Engine 104					N/A
						A/A
rack inspection 3:19 AM - I arriv	at Clarendon. ved at Clarendo	t with offload n track 1 on t	train 604 and sa	Virginia S aw light sn	quare so that 604	could be used fo
8:15 AM - ROC rack inspection 8:19 AM - Larriv 8:21 AM - Myse	at Clarendon. ved at Clarendo	t with offload n track 1 on t Dept. personr	ing train 604 at train 604 and sa nel concluded th	Virginia S aw light sn nat the sm	quare so that 604 noke. oke had dissipated	could be used fo
8:15 AM - ROC rack inspection 8:19 AM - Larriv 8:21 AM - Myse	at Clarendon. ved at Clarendo If and the Fire [	t with offload n track 1 on t Dept. personr	ing train 604 at train 604 and sa nel concluded th	Virginia S aw light sn nat the sm	quare so that 604 noke. oke had dissipated	could be used fo
8:15 AM - ROC rack inspection 8:19 AM - Larriv 8:21 AM - Myse	at Clarendon. ved at Clarendo If and the Fire [	t with offload n track 1 on t Dept. personr	ing train 604 at train 604 and sa nel concluded th	Virginia S aw light sn nat the sm	quare so that 604 noke. oke had dissipated	could be used fo
8:15 AM - ROC rack inspection 8:19 AM - Larriv 8:21 AM - Myse 8:42 AM - After	at Clarendon. ved at Clarendo If and the Fire I several track in	it with offload in track 1 on t Dept. personr ispections, no	ing train 604 at train 604 and sa nel concluded th ormal train servi	Virginia S aw light sn nat the sm ice resume	quare so that 604 noke. oke had dissipated	could be used fo
8:15 AM - ROC rack inspection 8:19 AM - Larriv 8:21 AM - Myse 8:42 AM - After	(Note time for e ival Time: 8:19 Al	it with offload in track 1 on t Dept. personr ispections, no ach entry; Inclu	ing train 604 at train 604 and sa nel concluded th ormal train servi	Virginia S aw light sn hat the sm ice resume	quare so that 604 noke. oke had dissipated ed. Witness at conclusion	could be used fo
8:15 AM - ROC rack inspection 8:19 AM - Larriv 8:21 AM - Myse 8:42 AM - After	At Clarendon. ved at Clarendo off and the Fire I several track in (Note time for e <u>ival Time: 8:19 Al</u> ubmitting Report	it with offload in track 1 on t Dept. personr ispections, no ispections, no ach entry; Inclu M	ing train 604 at train 604 and sa nel concluded th ormal train servi	Virginia S aw light sm nat the sm ice resume resume Repo	quare so that 604 noke. oke had dissipated ad. Witness at conclusion)	could be used fo

Figure 6 RTRA's Supervisors Incident Report PG-1

RTRA Supervisor Report Continuation Page		Page 2 d
Key Fi	ndings (Detail Below)	
Supervisor Submitting Report (Initials)	Report Review By (Initials)	

Figure 7 RTRA's Supervisors Incident Report PG-2

		INCIDENT ID: 2023	066SILVER	2		
DATE 2023-03-07	<b>TIM</b> 0807		LINE Silver		ITEM 2	
LOCATION (S Clarendon (KD	STATION/YARD) 2)	LOCATION/CHA Applicable)	IN MARKER	(If	REPORTED BY ROIC	
TRAIN ID 604	DIRECTION I/B	TRACK NUMBE		erbridge Alert/		
CAR NUMBER	RS (XXXX-XXXX)					
	-				-	
Caused Issue	c	aused issue 🗆	Caused	Issue 🗆	Caused Iss	ue 🗆
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI	OT ENT ske In The Station	ESP CODE TH d RTRA Supervisor and E	RT			
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio	O ENT ke In The Station N on, Officad, Dispatche	TH d RTRA Supervisor and E DELAYS IN MI	INUTES			
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio	O ENT ke In The Station N on, Officad, Dispatche I	d RTRA Supervisor and E DELAYS IN MI NCIDENT			OTAL DURATION	
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio	O ENT ke In The Station N on, Officad, Dispatche	d RTRA Supervisor and E DELAYS IN MI NCIDENT 33	TRAIN	4 T	OTAL DURATION	
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectik	O In The Station Non, Official, Dispatche 33	TH d RTRA Supervisor and E DELAYS IN MI NCIDENT 33 TRIPS MODI	TRAIN	4	0	
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectik	O ENT ke In The Station N on, Officad, Dispatche I	d RTRA Supervisor and E DELAYS IN MI NCIDENT 33	TRAIN		0 OFFLOAD	s
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectik	O In The Station Non, Official, Dispatche 33	TH d RTRA Supervisor and E DELAYS IN MI NCIDENT 33 TRIPS MODI	TRAIN	4 NOT	0 OFFLOAD	5
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio	or Non, Offload, Dispatche 33 GAP TRAIN 0	TH d RTRA Supervisor and E DELAYS IN MI NCIDENT 33 TRIPS MODI LATE DISPATCHES	TRAIN TRAIN IFIED REROUTED	4 NOT DISPATCHE 0	0 OFFLOAD	5
OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio LINE PARTIAL	or Non, Offload, Dispatche 33 GAP TRAIN 0	TH d RTRA Supervisor and E DELAYS IN MI NCIDENT 33 TRIPS MODI LATE DISPATCHES 0 VE PRIMARY CONSOL ALL DOORS CL	TRAIN TRAIN IFIED REROUTED 0 .E INDICATI	4 NOT DISPATCHE 0 IONS TO\MANUAL LUMINATED	0 OFFLOAD ED 4	s
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio LINE PARTIAL 8	OT INT Internet Station Non, Official, Dispatche 33 GAP TRAIN 0 FI BRAKES ON	TH d RTRA Supervisor and E DELAYS IN MI NCIDENT 33 TRIPS MODI LATE DISPATCHES 0 VE PRIMARY CONSOL ALL DOORS CL	TRAIN TRAIN IFIED REROUTED 0 .E INDICATI	4 DISPATCHE 0 IONS TO\MANUAL	0 OFFLOAD ED 4	s S
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio LINE PARTIAL 8	OT INT Internet Station Non, Official, Dispatche 33 GAP TRAIN 0 FI BRAKES ON	TH d RTRA Supervisor and E DELAYS IN MI NCIDENT 33 TRIPS MODI LATE DISPATCHES 0 VE PRIMARY CONSOL ALL DOORS CL	IFIED REROUTED 0 LE INDICATI OSED AU	4 NOT DISPATCHE 0 IONS TO\MANUAL LUMINATED	0 OFFLOAD ED 4	s
SMKW-SMOKE OBSERVED ON THE WAYSIDE TYPE INCIDE Report Of Smo ACTION PLAI Track Inspectio LINE PARTIAL 8	OT INT Internet Station Non, Official, Dispatche 33 GAP TRAIN 0 FI BRAKES ON	d RTRA Supervisor and E DELAYS IN MI NCIDENT 33 TRIPS MODI LATE DISPATCHES 0 VE PRIMARY CONSOL ALL DOORS CL ILLUMINATED	IFIED REROUTED 0 LE INDICATI OSED AU	4 NOT DISPATCHE 0 IONS TO\MANUAL LUMINATED	0 OFFLOAD ED 4	S

Figure 8 ROCC Incident Report PG-1

#### View Approved Incident Report

0816			Approved Incident Report
	604 was ins		tomers with the assistance of United States and Train a track inspection track one from Virginia Square to Court House e EV off.
0819			oad the train track 2 Court House and verify clear of all customer ourt House to Virginia Square.
0823	Clarendon. one.		604 reported light fog but no smell of smoke track one structed to continue on with the inspection to Court House track
0826			ce track two Ballston towards Vienna and reported no sign or t back in service at Court House track 1 towards Downtown Largo
0830	implemente service at B back at Arli announcem	d, Orange and Silver allston. Orange and ngton Cemetery. Tra	leased the scene at Clarendon, Service adjustment has been r line trains coming from Vienna and Ashburn will turn back for silver line trains coming from New Carrolton and Largo will turn ain ID 908 track one Ballston was instructed to make good vers offload their train and clear the interlocking for service back to requested.
1833			nstructed to offload their train and continue on to clear the ery for service back to New Carrolton.
0838		e FLO reported all fir A and normal service	re department personnel are clear they have turned the scene te can resume.
0836		e good announcemer	was instructed to offload their train and verify clear of customers ints for customers to utilize Line bus service or to standby for
0839	Train ID 90	9 was first to go nom	mal track one Ballston servicing all stations.
0845		5 serviced Train 604 customers delay.	customers Ballston track one in the direction of Downtown Large
0849		rived on the scene a gina Square and Cla	and requesting to do a riding inspection tracks one and two prendon Station.
0903	ERT#699 re	ported a clear track	inspection both tracks.
MAXIMO TI 8656998	ICKET#		
REPORT PR	EPARED BY	NAME	CLICK TO SIGN
RADIO CON	TROLLER 1		×
BUTTON CO	NTROLLER 1		*
RADIO CON	TROLLER 2		
BUTTON CO	ONTROLLER 2		
		SUPERINTENDE	ENTS OR ASSISTANTS SECTION
S		P CORRECTIVE	
	R REMARKS		
ACTIONS O	R REMARKS	ON OBTAINED FR	ом
ACTIONS O FOLLOW-U SUPPORT D	R REMARKS	ON OBTAINED FR	0M #1/CE0 □ #2/DGM &BELOW ■

Figure 9 ROCCS Incident Report PG-2

APPROVED BY	NAME	CLICK TO SIGN
REPORT APPROVED BY SUPT. OR AS	ST	SJGn ✓
SUPT.	© 2014 - Washingto	n Metropolitan Area Transit Authority

## Appendix D - MTPD Incident Report

Con his is		Event Re	port	
S. MAR	Metro Transit Police Depa			I-DCMTP00
A State	Type of Report Closed	MTPD CCN 2023-01921	Local Jurisdiction Arlington, VA	
Event Locatio	n			
Street		City, State		
3100 Wilson		ARLINGTON, VA 22201		
From	Date and Time of Event To		Date and Time Reported	
	7/2023 8:14:00 AM	:	3/7/2023 8:11:33 AM	
Reporting officer (Pr	vet) Badge #	Second Officer (Print)	Badge #	
Supervisor's Name (	Electronically Approved)			
Incidents				
Incident:		Location Type:		
Fire/Smoke Incident Detail:	Local Alarm	Rail Station		
modent becar.				
Involved Part	y			
<b>—</b>				
Age:			Place of Birth:	
		of Employment:	Place of Birth:	
Occupation: Work/School Addre	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/School Addre Wmata300 7		of Employment:	Place of Birth:	
Occupation: Work/School Addre	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/School Addre Wmata300 7	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/School Addre Wmata300 7	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/School Addre Wmata300 7	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/School Addre Wmata300 7	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/School Addre Wmata300 7	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/Scheol Adde	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/Scheol Adde Wmata300 2	ss – Addl. Contact Info:	of Employment:	Place of Birth:	
Occupation: Work/Scheol Adde Wmata300 7	ss - Addl. Contact Info: Pth ST SW, DC	of Employment:	Place of Birth:	

Figure 11 MTPD Incident Report PG-1

		1
Narrative Information	and MTDD annual of with mathing found Da	tential backs duct
Report of smoke or fire at CLRN. ACPD,ACFD,	and MTPD responded with nothing found. Po	tential brake dust.
If second CCN is available, insert here:	Additional Narrative on Supplemental Report	
MTPD CCN: ORI-DCMTP0000	Event Report	Page 2 of 3

Figure 12 MTPD Incident Report PG-2

# Appendix E - RTRA Supervisor Written Statement

		and the second se	eted for all incident			
Dates /n /pg	Incident Time	In Time	Reported: 05	Reported by: Customer  Employee		
Logation	8	75	0 A	ROCC D Othe	، <u>ا</u>	
Station r	Mezzar	nine # a L .	Track #/Destination/	Chain Marker/	Signal Number	
TADENSON	THO LEG	97	TRK#1.4	198		
TYPE OF INCIDENT		• /	1//50-1-20	1-1-		
Property Damage	Smoke		🗀 Fire	🗆 Custor	ner Complaint	
Customer injury	Customer	r Illness	Employee Injury	0.0000000000000000000000000000000000000	vee Illness	
Criminal Activity	Elevator E		Rail Vehicle Inci		Explain in description of incide	
WEATHER			DITIONS (natural lig		'ING (artificial lighting)	
Clear Rain C Snow Sleet/Ice C		Dawn/Dusk	Vaylight/2	1935.00	Lights On ALights Off	
STATION INCIDENTS	- Always inclu					
Elevator/Escalator#:	- mayo more	AFC	and a second	Room Number	/Location:	
NA			NA		NA	
Failure Number(s):			1			
		N	A			
Parking Lot D Paid Area				ay∉⊡ Platfo	rm 🗆 Ancillary Room 🗆	
Injury/Illness reported ab			OADWAY			
Name of Responding Sup	ervisor:	Nam	e/Department of PLNT/A	EC or other WMATA	esponder	
TO ALL INCLOSING						
TRAIN INCIDENTS	Destinction	1 10 .	lumbar link - P	1	land One /	
A//A	Destination	Car M	lumbers(list all cars in /	onsist):	Lead Car:	
Name of Responding Sup	envisor	14	Name/Denartment of	f CMNT/DST or oth	er WMATA responder	
	W/A		manney pepartunidht o	A A	a www.meshonger	
DESCRIBE THE INCI	DENT: Include	what you did	to correct the prob		notified and when.	
the second	operty damage a		and the second se	100		
A. 1						
A LAVAR FI	Im AF	Smoke (	WAS filler	ing throu	ch Tunnele	
accurge 11		I wre (	1 11	Sulf	116	
DN TRACK #	1- LAYGO	- NEW /	arrollton	Platlerm.	Notifiel RO	
/	11	- 5	1	1	6	
EVALUATED S	YELION,	File Py	of WAS Nol.	fiel through	F ROIC, MIT	
	-	An	lanua Ci	0.05	in which me	
		AFD	AND(UNED (Q)	6 A ENG	INTE 104- ERT,	
- 1 ·	6,0.30.	Q.1	1 uns De	Januar -	the se sea	
DZI MAANING	0 8 4	. Syste	m WAS Kield	PENED 10	ME AS OSC	
RST ANRIVED	1/	URIES				
a) 845 m	1 / 1/5	URRS				
231 Anni VED	VO INS					
2) 8 <sup>45</sup> Am. /	10 - ANJ				6.00	
231 ANRIVED ) 845 Am. 1	Vo INS					
231 ANRIVED () 8 <sup>455</sup> Am. 1	Vo - <i>t-NS</i>					
2) 8 <sup>45</sup> Am. 1	10 - <i>INS</i>					
2) 845 Am. 1	10 <i>IN</i> S					
2) 845 Am. 1	VoNS					
2) 8 <sup>45</sup> Am.						
2) 8 <sup>45</sup> Am.			0.0			
2) 8 <sup>45</sup> Am. /			0.0.0			
2) 8 <sup>45</sup> Am.		Run # 24	0.0.0			

Figure 13 RTRA's Supervisor Incident Report PG-1

#### Appendix F – PLNT Emergency Tunnel Fan Operation Form

110-ROCC-ALL-04-00 PLNT Desk Emergency Tunnel Fan Operation Form WASHINGTON METROPOLITAN AREA TRANSIT AUTHORITY Incident Description: Arcing Insulator / Trash Fire / etc. Nearest Station: Metro Center A01 aveno Chainmarker: xxx + xx Track #: Train ID: Proposed Evacuation Route: (towards which station) arendos Playbook/Page Reference: 9 рa Incident Zone(s) Approved 06/24/2021 \*Maintenance Lead will archive this form for record keeping purposes. 51.931 11/21

Figure 14 Plant Emergency Tunnel Fan Operation Form PG-1

Incident Date: 3/7/2023 Time: 08:08 hours Final Report – Evacuation for Life Safety Reasons E23155 Drafted By: SAFE 706 – 05/02/2023 Reviewed By: SAFE 71 – 05/08/2023 Approved By: SAFE 71 – 05/08/2023