

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Daniel Million have	20230906-WMSC-MAL-1				
	2023/09/11	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	CMNT	Contact Information					
Inspection Location	New Carrollton S&I Shop - Railyard D99 4300 Garden City Dr Hyattsville, MD 20785						

Inspection Summary

Inspection Activity #	1
Activity Code	VM-WI-PI
Inspection Units	1
Inspection Subunits	1
Defects (Number)	1
Recommended Finding	Yes
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	Insp	Inspection Subject			Shop / Yard Inspection Observation				Activity Code			VM-WI-PI			
Job Briefing Employee Name/Title	WMATA Inspection			Accompanied Inspector?			Yes	Out Brief Conducted	Yes	Yes Time		08:00 AM		Outside Shift	No	
Related Reports	N/A			Related CA	APS / Findin	ngs		N/A								
	Ref			Rule or SOP			Standard		Other /	Other / Title				Checklist Reference		
Related Rules, SOPs, Standards, or Other	s, Standards, or and Procedures		N/A	A			N/A	N/A		N/A			N/A			
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office	Track Type	At-grade Tunne		el	Elevated		N/A		
		Х													Х	
Line(s) & Track Number	New Carroll 4300 Garder			Railyard D99 Chain Marker and/or					From				То			
Number		, ,	,				N/A				N/A					
Vehicles		ad Car Number Number of Cars N/A N/A Equipment N/A						N/A								
	WMSC Inspectors conducted a rules compliance inspection of the New Carrollton S&I Shop and Yard for compliance with the Metrorail Safety Rules and Procedures Handbook (MSRPH), including Preventive Maintenance Inspections (PMI) activities. General Information: WMSC personnel participated in a demonstration of the 2K3K railcars marker antenna, ATP coil, and auto doors testing process at the New Carrollton S&I shop.						Number of Defects Recommended Finding? Remedial Action Required?					1 Yes No				
Description Remedial Action	CMNT and CENV personnel were conducting ATP coil testing per MSI 180320, ATP Coil Frequency Response, marker antenna testing per MSI 180328, Marker Coil Test, and auto doors testing per SBB 606, Preparation for Auto Doors. The following observations were noted. WMSC met at the New Carrollton Inspection Office and received a safety briefing. ATP coil testing was performed on railcars 2052/53. The left-side and right-side ATP coils failed the test on both railcars. The ATP coils were not marked or tagged as failed. See Attachment #1 and #2. Failed ATP coils will need to be replaced. CMNT and CENV personnel stated that railcars with failed ATP will not be restricted from revenue service if they pass the DST test. CENV stated that ATP frequency data from failed ATP coils is still being evaluated. Marker antenna testing was performed on railcars 2052/53 by placing a test device at the specified distance under marker antenna and by attaching different capacitors to the test device to send frequencies from F1 to F10 to the marker antenna and a second person will call out the frequency received from the operator's console. Two frequencies are not being used. Railcars 2052/53 passed the marker antenna test. CMNT personnel stated that they have not had any marker antennas failures. See Attachment #3.							nspection?			N	lo				

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

riction. Croscout of nemedia rictions may also	be subject to originity withse verification inspections to ensure corrections are sufficient and effective.	
Inspector in Charge's Signature		Date 2023/09/11
Inspector in Charge's Name Manuel Lopez	Inspection Team John DeRenzo	