

WMSC Commissioner Brief: W-0268 – Improper Rail Vehicle Movement – Federal Triangle Station – January 6, 2023

Prepared for Washington Metrorail Safety Commission meeting on April 9, 2024

Safety event summary:

During delays on the Blue, Orange and Silver Lines due to a person on the roadway on January 6, 2023, a Rail Traffic Controller attempted to contact the Train Operator of Train 452 approaching Federal Triangle Station, but did not receive a response. The Rail Traffic Controller planned to direct the Train Operator to hold at Federal Triangle Station. The Rail Traffic Controllers then utilized a "turnback" feature in Metrorail's signaling system that can prevent trains from receiving speed commands, the indications of the maximum allowable speed. However, the Train Operator then moved the train toward Metro Center despite the train showing a zero speed command, without the permission from the Rail Traffic Controller that Metrorail rules require for such movement with zero speed commands.

The Rail Traffic Controllers detected this improper movement, and communicated with the Train Operator at 11:02 a.m. The Train Operator reported to the Radio Rail Traffic Controller that the train had not lost speed commands. A Rail Supervisor boarded the train at Rosslyn Station and spoke to the Train Operator.

However, Metrorail did not remove the Train Operator from service for post-event testing until 1:09 p.m. and did not remove the train from service for event downloads until 1:56 p.m. Metrorail personnel stated they were gathering additional information.

The vehicle data shows the train did show zero speed commands, and that the Train Operator, contrary to Metrorail rules and procedures, closed the train doors when the train had zero speed commands.

The Train Operator then activated Stop and Proceed Mode to bypass the zero speed commands after servicing Federal Triangle Station. The Train Operator entered the acknowledgement code that the system requires to move with zero speed commands twice, at 10:59:05 a.m. and 10:59:24 a.m. Stop and Proceed Mode permits movement at up to 15 mph with zero speed commands. Metrorail requires this mode to be used only in those situations where movement with zero speed commands is permitted by a control point such as a Rail Traffic Controller and a protective block has been established.

The Train Operator improperly moved the train to Metro Center Station, passing the turnback location at 13 mph. After passing the turnback, the regulated speed changed to 29 mph, and the Train Operator increased speed as the train moved toward Metro Center Station.

Turnback locations are marked on the Metrorail system with a green sign. In some locations, the turnback marks the point that the lead car of an eight-car train must reach in order for the rear end of the train to be clear of a switch or interlocking so that the train can safely be moved back in the opposite direction, crossing to the adjacent track if needed. At other locations, such as this one, the turnback is farther from the interlocking. This turnback is approximately the equivalent distance to the length of a six-car train beyond the Federal Triangle Station platform.

Probable Cause:

The probable cause of this event was that the train operator activated stop and proceed mode two times without the permission of the control center and moved their train with passengers without permission.



Office: 202-384-1520 • Website: www.wmsc.gov

Corrective Actions:

Metrorail provided refresher training to the train operator.

Example of other related open CAPs

• C-0181 addresses the Rail Operations Audit finding that elements of Metrorail have a culture that accepts noncompliance with written operational rules, instructions, and manuals. (Completion of final actionable item scheduled October 2024)

WMSC staff observations:

The data review demonstrated that there was a lack of communication between the vehicle friction brake system and the vehicle monitoring system. This did not affect this investigation due to the circumstances of this event, but was corrected by Metrorail's Car Maintenance personnel prior to placing the railcars back into service.

The WMSC commends the Rail Traffic Controllers for identifying this improper movement.

Rail Traffic Controllers do not have physical characteristics training to understand the exact locations where turnbacks hold trains. At some locations, Advanced Information Management (AIM) system displays suggest a turnback holds trains at a platform, however the speed commands actually drop to zero beyond the platform.



Washington Metropolitan Area Transit Authority Department of Safety (SAFE) Office of Safety Investigations (OSI) FINAL REPORT OF INVESTIGATION A&I E23016

01/06/2023
Improper Rail Vehicle Movement
10:59 hours
Federal Triangle Station, Track 2
13:02 hours via MAC
14:44 hours
WMATA SAFE: No
WMSC: No
Other: No
Train ID 452
[L3050-3051.3076-3077.3242-3243T]
None
None
None
20230106#105333

Federal Triangle Station – Improper Rail Vehicle Movement January 6, 2023

Table of Contents

Abbreviations and Acronyms	3
Executive Summary	4
Incident Site	4
Field Sketch/Schematics	4
Purpose and Scope	5
Investigative Methods	5
Investigation	5
Chronological ARS Timeline	6
Advanced Information Management System (AIMS)	7
Office of Chief Mechanical Officer (CMOR) / Incident Investigation Team (IIT)	- 10
Closed Circuit Television (CCTV) Playback	- 13
Office of Car Maintenance (CMNT)	- 14
Office of Rail Transportation (RTRA)	- 15
Interview Findings	- 15
Weather	- 15
Human Factors Fatigue Post-Incident Toxicology Testing Work History Certifications	15 16 16
Immediate Mitigation to Prevent Recurrence	- 16
Related Rules and Procedures	- 16
Findings	- 17
Probable Cause Statement	- 17
Recommended Corrective Actions	- 17
Appendices	- 18
Appendix A – Interview Summary	- 18
Appendix B – Maximo Inspection Report	- 19
Appendix C – Train Operator and RTRA Supervisor Investigative Documents (Abridged)	- 20
Appendix D – Rail Operations Control Center Incident Report (Abridged)	- 24
Appendix E – Root Cause Analysis	- 26

Abbreviations and Acronyms

AIMS	Advanced Information Management System
ARS	Audio Recording System
САР	Corrective Action Plan
ССТV	Closed-Circuit Television
CMOR	Office of Chief Mechanical Officer
CMNT	Office of Car Maintenance
I/A	Incidents/Accidents
ΙΙΤ	Incident Investigation Team
MAC	Mission Assurance Coordinator
MSRPH	Metrorail Safety Rules and Procedures Handbook
ΝΟΑΑ	National Oceanic and Atmospheric Administration
RC	Root Cause
RC ROCC	Root Cause Rail Operations Control Center
ROCC	Rail Operations Control Center
ROCC	Rail Operations Control Center Rail Operations Control System
ROCC ROCS RTC	Rail Operations Control Center Rail Operations Control System Rail Traffic Controller
ROCC ROCS RTC RTRA	Rail Operations Control Center Rail Operations Control System Rail Traffic Controller Office of Rail Transportation
ROCC ROCS RTC RTRA SAFE	Rail Operations Control Center Rail Operations Control System Rail Traffic Controller Office of Rail Transportation Department of Safety
ROCC ROCS RTC RTRA SAFE SMS	Rail Operations Control Center Rail Operations Control System Rail Traffic Controller Office of Rail Transportation Department of Safety Safety Measurement System
ROCC ROCS RTC RTRA SAFE SMS SRC	Rail Operations Control Center Rail Operations Control System Rail Traffic Controller Office of Rail Transportation Department of Safety Safety Measurement System Safety Risk Coordinator

Washington Metropolitan Area Transit Authority (WMATA) Department of Safety (SAFE) – Office of Safety Investigations

Note that all times listed are approximate and may contain minor variations due to differences between systems of record.

Executive Summary


On Friday, January 6, 2023, at 10:59 hours, an Alexandria Division Train Operator operating inbound revenue Train ID 452 [L3050-3051.3076-3077.3242-3243T] operated their rail vehicle without having speed commands and permission from the Rail Operations Control Center (ROCC) after the Train Operator serviced Federal Triangle Station on Track 2. The ROCC Radio Rail Traffic Controller (RTC) contacted the Train Operator to discover if the Train Operator had speed commands after they departed Federal Triangle Station en route to Metro Center Station. Upon further review from ROCC, it was determined that the Train Operator operating Train ID 452 did not have speed commands after servicing Federal Triangle Station. The Radio RTC dispatched an Office of Rail Transportation (RTRA) Supervisor to assist with the incident, and the Train Operator was removed from service for post-incident testing. There were no injuries or damages reported as a result of this incident.

The probable cause of the event was a human factors error of inattention that resulted in the Train Operator bringing the train to a point of power without having speed commands and excluding permission from ROCC.

Incident Site

Federal Triangle Station, Track 2

Field Sketch/Schematics



Purpose and Scope

The purpose of this incident investigation and candid self-evaluation is to collect and analyze available facts, determine the probable cause(s) of the incident, identify contributing factors, and make recommendations to prevent a recurrence.

Investigative Methods

The investigative methodologies included the following:

- Formal Interview SAFE interviewed one individual as part of this investigation. Interviews
 include persons present at, during, and after the incident, those directly involved in the
 response process. Representatives from the Washington Metrorail Safety Commission
 (WMSC) were present during the interview. SAFE interviewed the following personnel:
 - Train Operator
- Documentation Review A collection of relevant work history information and process documentation contained in Metro systems of record. These records include:
 - Train Operator Incident Statement
 - Train Operator Training Record
 - Train Operator 30-day Work History
 - Management Incident Report
 - Metrorail Safety Rules and Procedures Handbook (MSRPH)
 - National Oceanic and Atmospheric Administration (NOAA)
 - Rail Operations Control System (ROCS) SPOTS Report
 - Rail Operations Control Center (ROCC) Incident Report
- System Data Recording Review A collection of information contained in Metro Data Recording Systems. This data includes:
 - Audio Recording System (ARS) playback
 - Closed Circuit Television (CCTV)
 - Office of Chief Mechanical Officer (CMOR) Incident Investigation Team (IIT) Vehicle Monitoring System (VMS)
 - Advanced Information Management System (AIMS) playback

Investigation

On Friday, January 6, 2023, at 10:59 hours, an Alexandria Division Train Operator operating inbound revenue Train ID 452 [L3050-3051.3076-3077.3242-3243T] operated their rail vehicle while not having speed commands and without permission from the ROCC. The Train Operator completed the train service at Federal Triangle Station on Track 2. Data from the CMOR IIT Report revealed that the Train Operator entered Stop and Proceed Mode with speed readouts at 0 MPH at 10:59 hours. The Radio RTC contacted the Train Operator at 11:02 hours and asked the Train Operator if they had speed readouts upon departing Federal Triangle Station en route to Metro Center Station.

Utilizing Operations Channel 2, the Train Operator responded to ROCC and reported that they did not lose their speed commands. The Radio RTC observed, via AIMS playback, the turnback in front of the Train Operator of Train ID 452 had been taken after the train serviced Federal Triangle Station.

The RTC took the turnback which would give the train zero-speed commands. The RTC can do this action in an emergency or if the train operator has not responded to radio transmissions. In this case, it was due to traffic control after an emergency (person on the roadway) at another station. The RTC attempted to contact the train two times at 10:57 hours and 11:02 hours, to instruct them to hold (this was to prevent train congestion and crowded platforms).


Based on the ROCC Incident Report, at 11:09 hours, the Radio RTC dispatched an RTRA Supervisor to assist, and they boarded Train ID 452 at Rosslyn Station on Track 2 to investigate. The Train Operator was removed from service at New Carrollton Station at 13:00 hours. The ROCC reported using subsequent trains to verify that the turnback was operating normally. The train was removed from service at Huntington Station and transported to the Alexandria Yard for VMS download and further investigation by the Office of Car Maintenance (CMNT). There were no reported injuries or damages during this incident. Additional analyses by the ITT and CMNT did not find any anomalies with the train consist.

Chronological ARS Timeline

A review of ARS	layback, i.e., phone and radio communications, revealed the following timeline:	:
Time	Description	

Time	Description
10:57:00 hours	Radio RTC: Attempted to contact the Train Operator of Train ID 452.
	Train Operator of Train ID 452: No response. [Radio OPS 2]
11:02:38 hours	Radio RTC: Attempted to contact the Train Operator of Train ID 452. [Radio
	OPS 2]
11:02:52 hours	Radio RTC: Attempted to contact the Train Operator of Train ID 452.
	Train Operator of Train ID 452: Train Operator acknowledged ROCC and
	informed them to proceed with their message. [Radio OPS 2]
11:03:01 hours	Radio RTC: Asked the Train Operator of Train ID 452 if they had speed
	commands while leaving Federal Triangle Station and proceeding to Metro
	Center Station.
	Train Operator of Train ID 452: Train Operator reported they had speed
	commands while leaving Federal Triangle Station. [Radio OPS 2]
11:03:08 hours	Radio RTC: Asked the Train Operator of Train ID 452 if they had lost their
	speed commands at any point between Federal Triangle Station and Metro
	Center Station, Track 2.
	Train Operator of Train ID 452: Train Operator reported negative; they did not
	lose their commands at any point. [Radio OPS 2]
11:09:50 hours	Train Operator of Train ID 452: Train Operator arrived at Rosslyn Station,
	Track 2. RTRA Supervisor boarded the train to investigate further. [SPOTS
	Report]
12:44:03 hours	Train Operator of Train ID 452: RTRA Supervisor and Train Operator arrived
	at New Carrollton Station, Track 1. Train Operator is removed at 13:09 hours
	by RTRA Supervisor. Train ID 452 en route to Huntington Station in revenue
	service and will be taken out of service for further investigation by ITT and
	CMNT. [SPOTS Report]
13:56:57 hours	Train ID 452: Train ID 452 arrived at Huntington Station on Track 2 and was
***	taken out of service for transport to Alexandria Yard. [SPOTS Report]

**Note: Times above may vary from other systems' timelines based on clock settings.



Advanced Information Management System (AIMS)

Image 1 - Train ID 452 arrived at Federal Triangle Station Track 2 platform at 10:58 hours.




Image 2 - Train ID 452 departed the Federal Triangle Station Track 2 platform at approximately 11:00 hours without speed commands.

Incident Date: 01/06/2023 Time: 10:59 hours Final Report – Improper Rail Vehicle Movement E23016 Drafted By: SAFE 702 – 03/05/2023 Reviewed By: SAFE 704 – 03/07/2023 Approved By: SAFE 71 – 03/07/2023

ROCS SPOTS REPORT

based on up-to-the-second operational performance data from the Rail Operations Control System

Current date/time: Thu Jan 12 20:13:15 2023

Right Right Left Left		t Platform:			d/or Sel	ect ID:		Leave b	lank to remo eria	ve criteria				
ID Platform length dcode door door dwell door door dwell door close dwell Arrived cleared cars to				~ 20)23 ~	Selec	t Times	(0-24HRS): From 1	0:00 \	∽] т о[12	:00 ~		
ID Platform length dcode door door dwell door dwell door dwell Arrived cleared cleared to	Ge	nerate Re	eport											
		Platform	length	dcode	door	door	dwell	door	door	dwell			cars	Travel Tim door open to

Image 3 - ROCS SPOTS Report showing when Train ID 452 departed Federal Triangle Station.

ROCS SPOTS REPORT

based on up-to-the-second operational performance data from the Rail Operations Control System Current date/time: Thu Mar 2 18:08:11 2023

and/o Selec	t Platform: (r Select 4-d t Date: Jai nerate Re	n ~ 6	umber:	d/or Selec		nk to rem	eave blank t ove criteria 4HRS): Fro			o 12:00	~		
ID	Platform	length	dcode	Right door open	Right door close	dwell	Left door open	Left door close	dwell	Head Arrived	Tail cleared	cars	Travel Time door open to door open
<u>452</u>	<u>C01-2</u>	6	21				11:01:26	11:01:54	28	11:00:56	11:02:16	3048-3049.3239-3238.3282-3283	-
<u>452</u>	D13-2	6	21	11:03:15	11:03:37	22	11:12:44	11:15:31	167	11:02:38	11:16:02	unknown	1:49
<u>452</u>	<u>C02-2</u>	6	21	11:03:29	11:03:54	25				11:02:45	11:04:32	3048-3049.3239-3238.3282-3283	0:14
<u>452</u>	<u>C03-2</u>	6	21	11:05:12	11:05:32	20				11:04:46	11:05:53	3048-3049.3239-3238.3282-3283	1:43
<u>452</u>	<u>C04-2</u>	6	21				11:06:54	11:07:19	25	11:06:25	11:07:47	3048-3049.3239-3238.3282-3283	1:42
<u>452</u>	<u>C05-2</u>	6	21				11:09:50	11:10:13	23	11:09:20	11:10:37	3048-3049.3239-3238.3282-3283	2:56

Image 4 - ROCS SPOTS Report showing the time Train Operator of Train ID 452 arrived at Rosslyn Station.

ROCS SPOTS REPORT

based on up-to-the-second operational performance data from the Rail Operations Control System

Current date/time: Wed Jan 18 19:53:00 2023

			(
	or Select 4-d						ove criteria						
elec	t Date: Ja	n ~ 6	~ 20	023 ~	Select Tim	nes (0-24	HRS): Fro	om 12:0	0 ∨ To	13:00	~		
Ge	Generate Report												
ID	Platform	length	dcode	Right door open	Right door close	dwell	Left door open	Left door close	dwell	Head Arrived	Tail cleared	cars	Travel Time door open to door open
452	<u>C07-1</u>	6	19				12:01:23	12:01:38	15	12:00:54	12:02:08	unknown	-
<u>452</u>	<u>C06-1</u>	6	19	12:04:17	12:04:32	15				12:03:51	12:04:51	unknown	2:54
<u>452</u>	<u>C05-1</u>	6	19				12:06:28	12:06:45	17	12:06:00	12:07:09	unknown	2:11
<u>452</u>	<u>C04-1</u>	6	19				12:09:18	12:09:33	15	12:08:47	12:09:56	unknown	2:50
<u>452</u>	<u>C03-1</u>	6	19	12:10:54	12:11:10	16				12:10:28	12:11:31	unknown	1:36
<u>452</u>	<u>C02-1</u>	6	19	12:12:12	12:12:44	32				12:11:47	12:13:10	unknown	1:18
<u>452</u>	<u>C01-1</u>	6	19				12:14:05	12:14:24	19	12:13:36	12:14:55	unknown	1:53
452	D01-1	6	19				12:15:39	12:15:57	18	12:15:06	12:16:22	unknown	1:34
<u>452</u>	D02-1	6	19	12:17:11	12:17:45	34				12:16:45	12:18:08	unknown	1:32
<u>452</u>	D03-1	6	19				12:19:01	12:19:21	20	12:18:30	12:19:47	unknown	1:50
<u>452</u>	D04-1	6	19				12:20:31	12:20:48	17	12:20:00	12:21:14	unknown	1:30
<u>452</u>	D05-1	6	19				12:22:22	12:22:37	15	12:21:50	12:23:01	unknown	1:51
<u>452</u>	D06-1	6	19				12:24:05	12:24:21	16	12:23:35	12:24:42	unknown	1:43
452	D07-1	6	19				12:25:50	12:26:05	15	12:25:20	12:26:27	unknown	1:45
<u>452</u>	D08-1	6	19				12:27:46	12:27:59	13	12:27:17	12:28:21	unknown	1:56
452	D09-1	6	19				12:31:41	12:32:00	19	12:31:10	12:32:22	unknown	3:55
452	<u>D10-1</u>	6	19				12:33:43	12:33:58	15	12:33:15	12:34:19	unknown	2:02
452	<u>D11-1</u>	6	19	12:35:53	12:36:09	16				12:35:29	12:36:29	unknown	2:10
452	D12-1	6	19				12:38:47	12:39:10	23	12:38:21	12:39:31	unknown	2:54
452	D13-1	6	21	12:58:04	13:01:16	192	12:44:25	12:44:43	18	12:44:03	13:01:48	unknown	5:38

Image 5 - ROCS SPOTS Report showing when the Train Operator of Train ID 452 was removed from service at New Carrollton Station.

ROCS SPOTS REPORT

based on up-to-the-second operational performance data from the Rail Operations Control System

Current date/time: Wed Jan 18 19:48:38 2023

Co	norate D	anart											
	Platform		dcode	Right door open	Right door close	dwell	Left door open	Left door close	dwell	Head Arrived	Tail cleared	cars	Travel Time door open to door open
<u>452</u>	<u>D12-2</u>	6	21				13:04:01	13:04:20	19	13:03:27	13:04:41	3050-3051.3076-3077.3242-3243	-
<u>452</u>	<u>D11-2</u>	6	21	13:07:11	13:07:27	16				13:06:42	13:07:48	3050-3051.3076-3077.3242-3243	3:10
<u>452</u>	<u>D10-2</u>	6	21				13:09:36	13:09:50	14	13:09:03	13:10:18	3050-3051.3076-3077.3242-3243	2:25
<u>452</u>	<u>D09-2</u>	6	21				13:11:45	13:12:05	20	13:11:11	13:12:26	3050-3051.3076-3077.3242-3243	2:09
<u>452</u>	D08-2	6	21				13:15:38	13:15:56	18	13:15:03	13:16:18	3050-3051.3076-3077.3242-3243	3:53
<u>452</u>	D07-2	6	21				13:17:50	13:18:04	14	13:17:14	13:18:31	3050-3051.3076-3077.3242-3243	2:12
<u>452</u>	<u>D06-2</u>	6	21				13:19:47	13:20:04	17	13:19:12	13:20:27	3050-3051.3076-3077.3242-3243	1:57
<u>452</u>	<u>D05-2</u>	6	21				13:21:33	13:21:47	14	13:20:58	13:22:10	3050-3051.3076-3077.3242-3243	1:46
<u>452</u>	<u>D04-2</u>	6	21				13:23:15	13:23:31	16	13:22:42	13:23:56	3050-3051.3076-3077.3242-3243	1:42
<u>452</u>	D03-2	6	21				13:24:42	13:24:57	15	13:24:09	13:25:25	3050-3051.3076-3077.3242-3243	1:27
<u>452</u>	<u>D02-2</u>	6	21	13:26:23	13:26:39	16				13:25:56	13:27: <mark>1</mark> 1	3050-3051.3076-3077.3242-3243	1:41
<u>452</u>	<u>D01-2</u>	6	21				13:28:19	13:28:33	14	13:27:41	13:28:59	3050-3051.3076-3077.3242-3243	1:56
<u>452</u>	<u>C01-2</u>	6	21				13:29:43	13:30:01	18	13:29:10	13:30:27	3050-3051.3076-3077.3242-3243	1:24
<u>452</u>	<u>C02-2</u>	6	21	13:31:27	13:31:43	16				13:30:58	13:32:09	3050-3051.3076-3077.3242-3243	1:44
<u>452</u>	<u>C03-2</u>	6	21	13:32:59	13:33:15	16				13:32:24	13:33:41	3050-3051.3076-3077.3242-3243	1:32
<u>452</u>	<u>C04-2</u>	6	21				13:34:48	13:35:03	15	13:34:15	13:35:27	3050-3051.3076-3077.3242-3243	1:49
<u>452</u>	<u>C05-2</u>	6	21				13:37:37	13:37:53	16	13:37:05	13:38:18	3050-3051.3076-3077.3242-3243	2:49
<u>452</u>	<u>C06-2</u>	6	21	13:39:55	13:40:12	17				13:39:27	13:40:32	3050-3051.3076-3077.3242-3243	2:18
<u>452</u>	<u>C07-2</u>	6	21				13:42:51	13:43:05	14	13:42:17	13:43:28	3050-3051.3076-3077.3242-3243	2:56
<u>452</u>	<u>C08-2</u>	6	21	13:44:32	13:44:48	16				13:44:04	13:45:10	3050-3051.3076-3077.3242-3243	1:41
<u>452</u>	<u>C09-2</u>	6	21	13:46:26	13:46:49	23				13:45:58	13:47:14	3050-3051.3076-3077.3242-3243	1:54
<u>452</u>	<u>C10-2</u>	6	21				13:48:21	13:48:38	17	13:47:45	13:49:02	3050-3051.3076-3077.3242-3243	1:55
<u>452</u>	<u>C11-2</u>	6	21							13:51:11	13:51:33	3050-3051.3076-3077.3242-3243	-
<u>452</u>	<u>C12-2</u>	6	21				13:53:44	13:54:00	16	13:53:08	13:54:22	3050-3051.3076-3077.3242-3243	5:23
452	C13-2	6	21							13:54:59	13:56:13	3050-3051.3076-3077.3242-3243	-
<u>452</u>	<u>C14-2</u>	6	21	13:57:32	14:00:31	179				13:56:57	14:00:52	3050-3051.3076-3077.3242-3243	3:48
452	<u>C14-1</u>	6	19	14:16:41	14:16:57	16				14:16:02	14:17:23	3143-3142.3144-3145.3261-3260	19:09

Image 6 - ROCS SPOTS Report showing the time Train ID 452 was removed from service at Huntington Station.

Office of Chief Mechanical Officer (CMOR) / Incident Investigation Team (IIT)

Adopted from the CMOR IIT report with minor grammatical and formatting edits:

"Based on the VMS data, Train ID 452 Speed Commands dropped to 0 MPH as the train was coming to a stop onto Federal Triangle Station's platform on Track 2. After servicing the station by cycling the doors, Train ID [452's] Stop and Proceed Mode was activated. The Master Controller was moved, but the train did not move. Stop and Proceed Mode was terminated. The train entered Stop and Proceed Mode again and moved while under Stop and Proceed Mode for 479 feet before the Limiting and Regulated Speed limits increased to 50 MPH and 29 MPH, respectively. The Master Controller was moved to P5 Power Mode, and the train increased speed and continued to Metro Center Station, passing the turnback at 13 MPH. Based on VMS data, CMOR IIT did not identify any faults with the train that contributed to the cause of this incident. The train performed and designed and commanded." See the timeline of events below:

Time	Description	Train Speed
10:58:01 hours	Train ID 452 came to a complete stop on Track 2. Limiting and Regulated Speed limits dropped to 0 MPH.	3 MPH
10:58:02 hours	Train ID 452 came to a complete stop at Federal Triangle Station, Track 2.	0 MPH
10:58:09 hours	Left Door Open Pushbutton activated, and the left doors opened.	0 MPH
10:58:50 hours	Left Door Close Pushbutton activated, and the left doors began to close.	0 MPH
10:58:57 hours	DCKR signal goes HIGH, indicating all doors are closed and locked.	0 MPH
10:59:05 hours	Train ID 452 entered Stop and Proceed Mode with Speed Readouts all 0 MPH.	0 MPH
10:59:06 hours	Master Controller placed in a B1 Braking Mode.	0 MPH
10:59:06 hours	Brakes released.	0 MPH
10:59:07 hours	Master Controller placed in a P2 Power Mode.	0 MPH
10:59:08 hours	Master Controller moved to a B5 Braking Mode after not moving at all.	0 MPH
10:59:10 hours	Master Controller placed in a B1 Braking Mode.	0 MPH
10:59:10 hours	Master Controller moved to a B4 Braking Mode.	0 MPH
10:59:11 hours	Stop and Proceed Mode ended.	0 MPH
10:59:24 hours	Train ID 452 entered Stop and Proceed Mode with Speed Readouts all 0 MPH.	0 MPH
10:59:37 hours	Train ID 452 moved towards Metro Center Station while in Stop and Proceed Mode.	1 MPH
11:00:05 hours	Master Controller moved to a P5 Power Mode, and Train ID 452 increased speed towards Metro Center Station.	12 MPH
11:00:09 hours	Train ID 452 passed Turnback at 13 MPH with the Master Controller in a P5 Power Mode.	13 MPH
11:00:45 hours	Train ID 452 came to a complete stop 11 feet from the 8-Car Marker at Metro Center Station.	0
11:00:48 hours	Left Door Open Pushbutton activated, and the left doors opened.	0
11:01:09 hours	Left Door Close Pushbutton activated, and the left doors began to close.	0
11:01:17 hours	DCKR signal goes HIGH, indicating all doors are closed and locked.	0
11:01:19 hours	Master Controller moved to P5 Power position, and Train ID 452 moved towards McPherson Square Station.	1 MPH




Figure 1 – IIT analysis of the Train Operator actions of Train ID 452.

Closed Circuit Television (CCTV) Playback



Image 6 – Train ID 452 [Lead car 3050] arrives near the 8-Car Marker at Federal Triangle Station, Track 2, at 10:58:36 hours.



Image 7 – Train ID 452 serviced the Federal Triangle Station, Track 2 platform, and doors opened at 10:58:47 hours.

Incident Date: 01/06/2023 Time: 10:59 hours Final Report – Improper Rail Vehicle Movement E23016 Drafted By: SAFE 702 – 03/05/2023 Reviewed By: SAFE 704 – 03/07/2023 Approved By: SAFE 71 – 03/07/2023



Image 8 – Train ID 452 serviced the Federal Triangle Station, Track 2 platform, and doors closed at 10:59:33 hours.



Image 9 – Train ID 452 departed Federal Triangle Station, Track 2, at 11:00:12 hours.

Office of Car Maintenance (CMNT)

CMNT personnel performed the necessary operation checks and inspections as recommended by CMOR IIT. CMNT reestablished communications between the Friction Brake System and the VMS. CMNT also performed tests on the Master Controller Operations and Brake Rates with no defects found. CMNT cleared the train for service and released it. (See Appendix B).

Office of Rail Transportation (RTRA)

RTRA's administrative investigation found that the Train Operator violated several established rules and procedures related to operating the train without speed commands, as well as closing platform-side doors without verifying that they had speed commands. The Train Operator was assessed disciplinary action in accordance with the Disciplinary Administration Program, which included retraining.

Interview Findings

As part of the investigation launched into the Improper Rail Vehicle Movement at Federal Triangle Station, SAFE conducted one interview with the Train Operator. The interview was conducted electronically via Microsoft Teams and identified the following key findings associated with this event. Findings detailed below include reported information from interviews and may conflict with other data sources contained in the report.

The Train Operator reported they were servicing Federal Triangle Station on Train 2 and were in the process of changing the train ID before they attempted to proceed to the next station. The Train Operator reported they assumed they had speed commands but did not verify visually if they had speed commands before leaving the station. The Train Operator stated they lost their awareness and did not verify speed commands before moving the train. (*Note: there was no evidence that they changed the Train ID or were instructed to change the Train ID.*)

Weather

On January 6, 2023, at the time of the incident, NOAA recorded the temperature as 49° F, 17 MPH winds, partly sunny, and visibility of 10 miles. This event occurred within a tunneled section of the rail system. Weather was not a contributing factor in this incident (Weather source: NOAA – Location: Washington, DC)

Human Factors

Fatigue

Evidence of Fatigue:

The incident data were evaluated for evidence of fatigue that may have been present at the time of the incident. No signs or symptoms of fatigue were detected from the available data. The employee reported feeling fully alert at the time of the incident. The Train Operator reported experiencing no symptoms of fatigue in the time leading up to the incident.

Fatigue Risk:

The incident data were evaluated for fatigue risk factors. Risk factors for fatigued were identified. The incident time of day did not suggest an increased risk of fatigue-related impairment. The Train Operator reported keeping a regular sleep schedule in the days leading up to the incident. The Train Operator performed day shift work in the days leading up to the incident. The employee was awake for 6.7 hours at the time of the incident. The Train Operator reported 8 hours of sleep in the 24 hours preceding the incident. The off-duty period was 8.5 hours which provides an opportunity for 7-9 hours of sleep. This was more than a comparable amount of sleep to the employee's regular workday sleep durations. The employee reported no issues with sleep.

Post-Incident Toxicology Testing

WMATA's Drug and Alcohol Program determined that the Train Operator was not in violation of the Drug and Alcohol Policy and Testing Program 7.7.3/7.

Work History

The Train Operator is a WMATA employee with over ten years of total service: six years as a Bus Operator and four years of service as a Train Operator. The Train Operator was last certified in July 2022. This employee has no history of sleep issues to report. As noted in the RTRA Investigative report, the Train Operator had two prior infractions, both in 2020. The infractions included opening doors off of the platform and failing to clear their train at the end of the line, which resulted in a customer being brought into the rail yard.

Certifications

The Train Operator completed their train qualification on July 14, 2022, with 94% on the MSRPH Exam and 90% on the TVOIM Exam. The Train Operator successfully completed the practical application portion on July 17, 2022.

Immediate Mitigation to Prevent Recurrence

- RTRA removed the Train Operator service for post-incident toxicology testing.
- RTRA removed the incident consist from service for CMNT inspection and CMOR ITT analysis.

Related Rules and Procedures

- MSRPH Section 3 Operating Rules Ver 2.0 3.18 "Employees shall not operate any vehicle in a reckless or unsafe manner."
- MSRPH Section 3 Operating Rules Ver 2.0 3.79 "Train Operators shall not move trains with zero speed commands except after notifying ROCC or Terminal Supervisor and being given permission to move with zero speed commands and either a permissive block going with traffic or an absolute block going against traffic."
- MSRPH Section 3 Operating Rules Ver 2.0 3.79.1 "Upon losing speed commands on the platform, the operator may NOT adjust the train in the same direction of traffic to service the station without contacting ROCC or Terminal Supervisor for permission. After servicing the station, the operator must keep their train doors open until such time when the operator has received speed commands, a proper signal aspect (Lunar or Flashing Lunar), along with contacting ROCC or Terminal Supervisor for permission to leave and an absolute block for the move if speed commands do not return (Reference SOP # 40)."
- MSRPH Section 3 Operating Rules Ver 2.0 3.79.3 "Legacy Trains Operators shall contact ROCC or terminal supervisor anytime the train loses speed commands and comes to a stop, even within the platform limits. Before moving the train, a permissive or absolute block must be established."
- SOP 40.5.3.1 "Prior to initiating the Close Door Button, the train operator shall check the
 operator console for speed commands and check Roadway ahead o the train to ensure it
 is clear."

Findings

- Train ID 452's Limiting and Regulated Speed limit dropped to 0 MPH in approach to Federal Triangle Station, Track 2.
- Train ID 452 entered Stop and Proceed Mode, with Speed Readouts all 0 MPH after servicing Federal Triangle Station.
- The Train Operator did not contact ROCC and receive permission to proceed when speed commands were at 0 MPH before departing Federal Triangle Station.
- Train Operator proceeded to Metro Center Station while in Stop and Proceed Mode.
- No mechanical defects were identified with the train that would have contributed to the event.

Probable Cause Statement

The probable cause of the event was a human factors error of inattention that resulted in the Train Operator bringing the train to a point of power without having speed commands and excluding permission from ROCC.

Recommended Corrective Actions

The following are the recommended corrective actions identified as a result of this investigation. These are tracked using WMATA's Safety Measurement System Incidents/Accidents (SMS I/A) Module and are verified by SAFE upon completion. The responsible department is identified in the corrective action code, and the respective departmental Safety Risk Coordinator (SRC) will manage the mitigation.

Corrective Action Code	Description	Responsible Party	Estimated Completion Date
105333_SAFE CAPS_RTRA _001	(RC-1) RTRA Management will ensure the Train Operator attends refresher training.	RTRA SRC	Completed

Appendices

Appendix A – Interview Summary

The narrative below summarizes the interview with SAFE and represents the statements made by the individual involved. As such, times and details may present a conflict with the data contained in systems of record.

Train Operator

The Train Operator is a WMATA employee with over ten years of total service: six years as a Bus Operator and four years of service as a Train Operator. The Train Operator was last certified in July 2022. This employee has no history of sleep issues to report.

During the interview, the Train Operator stated they were servicing Federal Triangle Station on Train 2, outbound, and did not notice they did not have speed commands before leaving the station. They reported that the ROCC contacted them to ascertain if they had speed commands. The Train Operator stated they witnessed a lunar signal and assumed they had speed commands before operating the train in revenue service. The Train Operator said they lost focus and were not aware of the status of the train. The Train Operator said the incident may have been prevented if they had taken their time and not rushed through the procedures.

Appendix B – Maximo Inspection Report

Work Order #: 17594808		enance and M	olitan Area Material Mana Order Deta	gement			Stat	Page 1	of 1 MX76PROD
Type: CM							01/1	0/2023 08:1	9
Work Description Job Plan Description	TRAIN ID 452 IMPROPER	R RAIL VEHICLE I	MOVEMENT AT F	EDERAL TR	AINGLE				
voo man beschption									
			Work Informatio	n					
Asset: R3050	3050, RAIL CAR, BREDA, 3000	AC, A CAR	Owning Office	CMNT-CMNT-	CMNT		Par	ent:	
Asset Tag: R3050		Maintenance Office: CMNT-GRBT-INSP							3 20:51
Asset S/N: 3050			Labor Group					tart: 01/06/202	
Location: 1437	E99, GREENBELT YARD		Crew		Actual Comp: 01/06/2023 22:01				
Work Location: 1213	C99, ALEXANDRIA YARD		Lead					em: L1805000	2
Failure Class: CMNT001	RAIL CAR				392-50499160-04	1			
Problem Code: 2424	N/A CODE (GENERAL SYMPTO	DM)	Supervisor				Target S		
Requested By: Chain Mark Start:			Requestor Phone Chain Mark End				Target Co Scheduled S		
Create-Mileage: 2453782.0			Complete-Mileage				scheduled S	tart.	
Task IDs			Complete-Mileage	2455762.0					
Task IDs									
Task ID									
10 RE-ESTABLISHED CO PASSED. Component: 000-300 RAIL CAR; 20	DMM. BETWEEN FRICTION BRAN (/3K/6K/7K	KE SYSTEM AND VMS				GOOD. PERFORMED			PEC. DST
Actual Labor									
Task ID Labor		Start Date	End Date	Start Time	End Time	Approved?	Regular Hours	Premium Hours	Line Cos
10		01/06/2023	01/06/2023	20:30	21:00	Y	00:30	00:00	\$24.6
					Total	Actual Hour/Labor:	00:30	00:00	\$24.6
Failure Reporting									
Cause		emedy			Supervisor			Rem	ark Date
1588 DIAGNOSTIC FAIL; F	ESET	3192 TESTED / II	SPECTED					01/06	6/2023
	M. BETWEEN FRICTION BRAKE SYST								

WT_plust_woprint.rptdesign

Figure 2 – CMNT work order details for Train ID 452, page 1 of 1.

01/12/2023 20:38

Appendix C – Train Operator and RTRA Supervisor Investigative Documents (Abridged)

Date: / /	Incident Time:	and the second se	eted for all incidents Reported:	Reported by: Custom	
1/4/27	11:01	Time	Reported:		er 🖬 Employee 🖬
	11.01		and the second	ROCC D Other D	
Location			T 1 10 11 11		an and an other takes
Mapherson	Mezzanine	ŧ.	Track #/Destination	Chain Marker/Signal I	lumber
			2		
TYPE OF INCIDENT	and the second sec			making the task Name in	
Property Damage	Smoke		□ Fire	Customer Con	
Customer injury	Customer IIIn	BSS	Employee Injury	C Employee Illne	
Criminal Activity	Elevator Entra		🗅 Rail Vehicle Incide		in description of incide
WEATHER	LI	GHT COND	ITIONS (natural ligh	ting) LIGHTING (artificial lighting)
lear 🛎 Rain 🗅	Da	wn/Dusk 🗀 🛛	Daylight 🗅 🖉	Lights On 🖬 I	ights Off 🗅
now 🗆 Sleet/Ice 🗆			Underground 🗹	Lights Not W	orking 🗅
STATION INCIDENT	S: Always include	equipment	t number you use for	MOC/AFC/EOC	
levator/Escalator#:		AFC #	÷	Room Number/Locati	0 n :
ailure Number(s):					
arking Lot 🗆 Paid Are	a 🗆 Free Area 🗆 Ga	rage 🗆 Stat	ion Entrance 🗆 Stairwa	y # Platform 🗆 .	Ancillary Room 🗆
	board Train 💷 Other 🗆				
lame of Responding Su			Department of PLNT/AF	C or other WMATA respond	er
		- and the			5000
TRAIN INCIDENTS			IT AN AVERAGE AND AND	and the second second	
rain ID	Destination	Car N	umbers(list all cars in co	nsist):	d Car:
452	Destination Hundington	R24	43 3077 3051	course).	3050
lame of Responding Su	narvisor:	1 /		CMNT/TRST or other WMA	
ane of Responding Su	pervisor.		Marney Department of	GIVIN 1/1 HOT OF OUT OF THE VINA	IN Tesponder
	IDENT: Include who	t you did	to correct the proble	m and who you notifi	ad and whan
	IDENT. INCIDE WIN	at you uiu	to correct the provid	an and who you nothing	su anu when.
	roperty damage and th and Mc Phiers Inc. 18. V. H. Conversations	51.540 200 and an and a state		nds. Once I	e aller mbiced
I service changing the my speed		51.540 200 and an and a state		ndr. Once I	e alks whice d
I service changing the my speed	d McPherse Ine 15. v. H. conventions	51.540 200 and an and a state		ndr. Once I	e alter insticed
I service changing the my speed	d McPherse Ine 15. v. H. conventions	51.540 200 and an and a state		adr. Once I	e allso noticed
I service changing the my speed	d McPherse Ine 15. v. H. conventions	51.540 200 and an and a state		adr. Once I	e aller
I service changing the my speed	d McPherse Ine 15. v. H. conventions	51.540 200 and an and a state		adr. Once I	e alter
I service changing the my speed	d McPherse Ine 15. v. H. conventions	51.540 200 and an and a state		adr. Once I	e alter
I service changing the my speed	d McPherse Ine 15. v. H. conventions	51.540 200 and an and a state		indr. Once I	e alter
I service changing to my speed billows	ed Mc Pharse Ine 1B. With connenaceds	51.540 200 and an and a state		waed to mov	e altor mbice d
I service changing to my speed billows	ed Mc Pharse Ine 1B. With connenaceds	51.540 200 and an and a state			
I service changing to my speed bilbros	ed Mc Pharse Ine 1B. With connenaceds	51.540 200 and an and a state		Employee #	Date:
I service changing to my speed billows	ed McPharse Ine IB. W. H. C.C. Manadols I ANUS EZ.	no sp no sp 10 fw, an		Employee #-	Date://///23
I service changing to my speed biibnes	ed McPharse Ine IB. W. H. C.C. Manadols I ANUS EZ.	no sp no sp (chu, ni			Date://///23
I service <u>changing th</u> <u>ny speed</u> <u>bibres</u> mployee Completing F <u>Alex</u>	ed Mc Phierse Ine IB. W. H. COMMENTED S. ANUS EZ. Ru	no sp no sp 10 fw, an		Employee #-	Date://///23
I service <u>changing th</u> <u>ny speed</u> <u>bibres</u> mplayee Completing F <u>Alex</u>	ed Mc Phierse Ine IB. W. H. COMMENTED S. ANUS EZ. Ru	no sp no sp (chu, ni		Employee #-	Date://///23
I service <u>changing</u> <u>th</u> <u>my</u> <u>speed</u> <u>biibres</u> <u>biibres</u> <u>Alex</u> o Be Completed By Re	ed Mc Pharse Ine IB. W. H. (C.L. Marked S. J. ANUS EZ. ANUS EZ. Report Report Reviewing Manager	no sp 10 fr/2011		Employee #-	Date; 1/6/23
I service changing to my speed billones	ed Mc Pharse Ine IB. W. H. (C.L. Marked S. J. ANUS EZ. ANUS EZ. Report Report Reviewing Manager	no sp 10 fr/2011	de #2. Pi aecd comman d.	Assigned Day M/7	Date: 1/6/23 S:
I service <u>changing</u> <u>th</u> <u>my</u> <u>speed</u> <u>biibres</u> <u>biibres</u> <u>Alex</u> o Be Completed By Re	ed Mc Pharse Ine IB. W. H. (C.L. Marked S. J. ANUS EZ. ANUS EZ. Report Report Reviewing Manager	no sp 10 fr/2011	de #2. Pi aecd comman d.	Assigned Day M/7	Date: 1/6/23 S:
I service changing to my speed bi:bnes bi:bn	ed Mc Pharse Ine IB. W. H. (C.L. Marked S. J. ANUS EZ. ANUS EZ. Report Report Reviewing Manager	no sp 10 fr/2011	de #2. Pi aecd comman d.	Assigned Day M/7	Date: 1/6/23 S:
I service changing to my speed bi:bres bi:br	ed Mc Pharse Ine IB. W. H. (C.L. Marked S. J. ANUS EZ. ANUS EZ. Report Report Reviewing Manager	no sp 10 km/m 10 km	de #2. Pi aecd comman d.	Assigned Day M/7	Date: 1/6/23 S:

M	RTRA Supervisors' Report				DEPARTMENT OF OPERATIONS-RAIL SERVICE			
metro	WASHINGTON METRO	DPOLITAN AREA TRANSIT AUTHOR	RITY	Office of	of Rail Transp	ortation		
Date -06-2023	Incident Time: 11:01am	Incident Location (S Federal to	iAhg/e		Track/Mezzanine	#		
quipment Number		Escalator/Elevator #, Room #)	,					
452	324	3 3077	3051					
ncident Description	Moring Wi	the out spee	d course	MAL 1				
VMATA Personnel I		Employee #	Rule Violation?	Home Divis	sion	Post Inciden		
	-			Alex	Andia	yes		
lame		Address				Injury?		
Name		Address			Injury?			
Name		Address		анар См. р.	- 1º -	Injury?		
Arrival Time	Unit Number	Person In Charge		Remarks				
uperviso/Submitti	ng Report (include payroll #	#) Date /- 6-2023	Report Reviewed	by	Date			
RTRA Superv	isor's Report	1-6001)	1		P	age 2 of 2		
437 09/10		Report must be faxed to r	DCC 301-618-1012 at (end of tour				



WASHINGTON METROPOLITAN AREA TRANSIT AUTHORITY

INVESTIGATION RE	INVESTIGATION REPORT			DIVISION (Alexandria		SARAGE N/A		FILE N 20230	O. 106-016152
DATE OF OCCURRENCE		ME :00am	VEHICLE NO. (L) 3050-3051-3076-3077-3242-3243		242	RUN # AX-38003		SHIFT	BLOCK NO.
January 6, 2023 LINE: Blue	LINE: Blue LOCATION:				- T	DESTINATION: Huntington			
		Metro Cent	er Track #2					di tanàn mena	
TYPE OF CASE Violation: MSRPH 1.46, 3.79.1, Cardinal Rule 1.3, OR 3.79,	5.3.1	3.1 REPORTED BY ROCC							
NAME OF EMPLOYEE INVOL'									
NATURE OF OCCURRENCE	Tr	ain moving w	ithout speed command	ls					
1. SUMMARY OF INVESTIGAT									
4. ANALYSIS OF FACTS / EVI									
1. On Friday, January 6, 202: commands between Federal T turnback was confirmed operation	rian	gle and Metro	ely 11:01am, ROCC n o Center on track 2. F	eported tha ROCC had o	t Trai cancel	n Operator	ck be	moved his etween the t	train without speed two stations and the
2. Operator you stated i commands. Once I noticed my	n yo spe	eur incident re	port, "I serviced McPh s returned."	erson Track	#2. P	roceed to mov	e afte	er changing	the ID with no speed
ACTION "	ТАК	EN: Level II Disciplina	I violation with Written ary Administration Prog	Reprimand, gram (DAP)	, ten (and R	10) points asse Refresher Train	essed ing w	l under the ith ROQT	
DATE ACT	ION	TAKEN BY:			Â		TITLE Superintendent		
EMPLOYEE SIGNATURE		a All							
I certify that the above has	be	en called to i	my attention, and I un	nderstand t	hat m	y signature d	oes r	not imply a	dmission of guilt
EMPLOYEE MAY WRITE A ST	AT	EMENT IN TH	IIS SPACE						
L 1.21 (6/79) O <u>rig:</u> Office of Bus S Gr <u>een:</u> Employee Div			RAIL Yellow: Employ Pink: Union	ee Gold: Mar	keting/	MARK			

Investigation Report Continuation Sheet

3. Based on the above investigation you violated the following MSRPH Rules:

Cardinal Rule 1.3- Acceptance of employment signifies the individual's willingness to comply with all WMATA's rules and regulations and orders; and to perform specific job duties and requirements in a safe, orderly and efficient manner.

G.R. 1.46- Employees shall not permit unnecessary conversation, reading, lounging or any other action or condition of mind to divert their attention from the safe and efficient performance of duty.

O.R. 3.79 - Train Operators shall not move trains with zero speed commands except after notifying ROCC or Terminal Supervisor and being given permission to move with zero speed commands and either a permissive block going with traffic or an absolute block going against traffic.

O.R. 3.79.1 – Upon losing speed commands on the platform, the operator may <u>NOT</u> adjust the train in the same direct of traffic to service the station without contacting ROCC or Terminal Supervisor for permission. After servicing the station, the operator must keep their train doors open, until such time when the operator has received speed commands, a proper signal aspect (Lunar or Flashing Lunar), along with contacting ROCC or Terminal Supervisor to leave and an absolute block for the move if speed commands do not return.

O.R 3.79.3 - Legacy Trains - Operators shall contact ROCC or Terminal Supervisor anytime the train loses speed commands and comes to a stop, even within the platform limits. Before moving the train, a permissive block or absolute block must be established.

SOP 40.5.3.1 – Prior to initiating the Close Door Button, the train operator shall check the operator console for speed commands and check Roadway ahead of the train to ensure it is clear.

4. An investigation was conducted by Alexandria Division Managers. The investigation included your incident report, ROCC's incident report, and data analyzed from your train ID 452 by the Incident Investigation Team (IIT) engineers. The data provided revealed that train ID 452's speed commands dropped to 0 MPH as the train was coming to a stop onto Federal Triangle Station's platform on Track #2. After servicing the station, the train's Stop and Proceed mode was activated. The Master Controller was moved, but the train did not move. Stop and Proceed Mode was terminated. The train was entered into Stop and Proceed again and moved while under Stop and Proceed for 479 feet with zero speed commands.

5. Operator **Control** in determining the appropriate disciplinary penalty for your actions, the Division considered many factors. The records of WMATA indicate you have been an employee since February 3, 2014. The records indicate that you have been a train operator since March 1, 2020. Since becoming a train operator, you have committed several operational violations to include an improper door operation on August 21, 2020 and failure to follow established procedures for checking out of service trains at the end of the line, resulting in a customer being brought into the rail yard on April 22, 2020.

As a result of the above referenced infraction/violation, you are being issued a Level 3 violation with twelve (12) points assessed under the Discipline Administration Program (DAP). You must use two (2) of your available six (6) positive points towards this violation which brings your total accumulative points to ten (10). Ten (10) points constitutes a written reprimand under the DAP issued June 1, 2022. You are reminded that any future violation(s) may result in more progressive disciplinary action to include disqualification and/or discharge from the Washington Metropolitan Area Transit Authority.

Post incident drug and alcohol testing results ____ Positive___X__Negative

Employee Initials:

Date: 2/2/23

DATE 2023-01-06	TIME 1101		LINE Blue		
LOCATION (STAT Federal Triangle (D		LOCATION/CHAIN Applicable)	MARKER (If	REPORTED BY AIM Display	
TRAIN ID 452	DIRECTION I/B	TRACK NUMBER 2	DEPTS NOTI Everbridge Ale		

	-			-	
CAR NUMBERS (2 Lead Car - Caused Issue D	-	ed Issue 🗆	- Caused Issue 🗆	- Caused Issue 🗆	

View Approved Incident Report

Dispatch RTRA Supervisor. Remove Operator from Service.

		DELAYS IN	MINUTES				
LINE		INCIDENT	TRAI	IN	TOT	AL DURATION	
0		0		0		0	
		TRIPS MO	DIFIED				
PARTIAL	GAP TRAIN	LATE DISPATCHE	S REROUT		ATCHED	OFFLOADS	
0	0	0	0	0 0		0	
		FIVE PRIMARY CONS	SOLE INDIC	ATIONS			
ВСР	BRAKES O				ANUAL B	PP	
				AUT	0		

View Approved Incident Report

	INC	CIDENT CHRONOLOGY				
TIME	DESCRIPTION					
1101	train had been taken before h	Metro Center track two. The turn is train had serviced the platform. y to intercept the train and investi	ROCC instructed Unit 32, RTRA			
1109	Supervisor boarded train 452 at Rosslyn. Supervisor provided reported, after interviewing Operator action , that the operator stated that they did not remember if his train had speed commands at Federal Triangle.					
1300	Operator was removed from service at New Carrollton, transported for post-incident analysis and instructed to submit an incident report.					
0000	Note: It was confirmed with s	ubsequent trains that the turnback	k was operating normally.			
	PREPARED BY NAME		CLICK TO SIGN			
REPORT F	PREPARED BY NAME		CLICK TO SIGN			
	ONTROLLER 1		*			
	CONTROLLER 1		*			
	ONTROLLER 2					
BUTTON	CONTROLLER 2					
	SUPERINTEN	DENTS OR ASSISTANTS SECTI	ON			
	NAL FOLLOW-UP CORRECTIVE OR REMARKS					
	UP INFORMATION OBTAINED F DEPARTMENTS	ROM				
NOTIFICA	ATIONS/PAGE GROUPS	#1/CEO 🗖 #2/DGM &BEL	OW 🗖			
ADDITIO	NAL NOTIFICATIONS MADE BY					
APPROVE	D BY	NAME	CLICK TO SIGN			
REPORT A	APPROVED BY SUPT. OR ASST		1			
		© 2014 Mashinston N	Metropolitan Area Transit Authorit			

© 2014 - Washington Metropolitan Area Transit Authority

Appendix E – Root Cause Analysis

