

Inspection Form

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Depart Number	20231027-WMSC-MAL-1						
Inspection Date	2023/11/12	Report Number	20231027-WWSC-WAL-1						
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name						
Rail Agency Department	CMNT	Contact Information							
Inspection Location	Brentwood S&I Shop - Railyard B99 601 T Street NE V	twood S&I Shop - Railyard B99 601 T Street NE Washington DC 20002							
Inspection Summary									
Inspection Activity #		1							
Activity Code		VM-WI-PI							
Inspection Units	1								
Inspection Subunits	1								
Defects (Number)	3								
Recommended Finding	Yes								

No

No

Activity Summaries

Remedial Action Required¹

Recommended Reinspection

Inspection Activity #	1	Inspe	ection Su	oject	Observation 7K Wheelset Asso			embly Process	Activity Code			VM-WI-PI			
Job Briefing Employee Name/Title	WMATA Insp	ection		Accompar	ied Inspecto	or?	Yes	Out Brief Conducted	Yes Time			07:3	0 AM	Outside Shift	No
Related Reports	N/A			Related C	APS / Findin	igs		N/A							
	Ref Rule			e or SOP St		Standard	indard		Other / Title				Checklist Reference		
Related Rules, SOPs, Standards, or Other	METRORAIL OPERATING RULEBOOK FIRST EDITION Effective: Sept 1, 2023, Safety Rules			Ą			N/A	N/A		N/A			N/A		
Inspection Location	Main Track	Yard	Station	OCC	RTA F	acility	WMSC Office	Track Type	At-grade Tunne		el Eleva		ted	N/A	
		Х												Х	
Line(s) & Track Number	Brentwood S&I Shop - Railyard B99 60 Street NE Washington DC 20002			99 601 T	Chain Marker and/or Station(s) N/A			N/A	From N/				To I/A		
	Head Car Number N			lumber of Cars											
Vehicles	N/A			N/A	N/A Equipment N/A			N/A							
	WMSC Inspectors conducted a rules compliance inspection of the wheelset assembly							Number of Defects					3		
	process at the Brentwood S&I Shop for compliance with the Metrorail Operating Rule and Procedures Handbook (MOR), including Preventive Maintenance Inspections (PI) activities. General Information: WMSC met with personnel from Brentwood's truck shop							Recommended Finding?					Ye	Yes	
								Remedial Action Required?				No			
Description	and CMOR quality assurance personnel. WMSC Conducted an observation of the wheelset pressing process at the Brentwood S&I shop and the following observations were noted. WMATA stated that 8 wheelsets were assembled, and 3 misfits occurred. Wheel press machine operator had just encountered an incident which stopped all wheelset press operations. While trying to demount a wheel from an axle assembly, the machine exerted such a high force that when the wheel popped loose the machine shook severely and knocked off a metal sleeve from the rack that fell and damaged the machine conveyor metal floor. See Attached Photos #1 and #2. The machine applied over 300 tons of force to pull the wheel off, while generally the demounting process is done with a force of less than 200 tons. Previous wheelset record sheets of the axle and wheels were requested for analysis. Recommendation #1 - WMATA consults with the BBM wheelset manufacturer to ensure demounting force limits are not exceeded based on the capacity of the machine.									o					
Remedial Action															

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

	inspector in charge's Signature		2023/11/12
I	Inspector in Charge's Name	Inspection Team	
	Manuel Lopez	John DeRenzo	
I			