



**Red Signal Overruns**  
**At or Near Brentwood Rail Yard and Anacostia Station**  
**April 11, 2024 – April 19, 2024**

**Document Purpose:**

*This WMSC written report on WMATA Metrorail's safety event investigations and review of Metrorail's findings in accordance with the WMSC Program Standard, in conjunction with the attached Metrorail investigation reports that have undergone WMSC staff review and, if necessary, feedback and revision, describes the investigation activities, identifies factors causing or contributing to the safety events, and sets forth ongoing, additional, or upcoming corrective actions and further oversight work (such as inspections and audits) as necessary or appropriate. The WMSC's ongoing oversight during the investigative process, including safety event reporting and verification, participation in investigative interviews, data review, consistent communication with the Metrorail investigations team, and feedback on Metrorail's reports leads to further improvements prior to consideration of the reports by WMSC Commissioners for adoption. The WMSC's safety event investigation oversight assures the sufficiency and thoroughness of Metrorail's investigations. The WMSC Commissioners are considering these documents (the WMSC review and Metrorail's investigation reports) as a unified item for adoption at the Washington Metrorail Safety Commission meeting on December 10, 2024.*

*WMSC staff recommend adoption of these investigations.*

**Red Signal Overruns**

In 2023, Metrorail reported 9 red signal overruns. This included events involving passenger trains and events involving maintenance vehicles.

As of November 15, 2024, there have been 14 such events reported in 2024. WMSC has conducted its own independent review of these events as they occur to understand the contributing causes and to explore methods for correcting precipitating causes to prevent recurrence. WMSC staff have discussed the specifics with key Metrorail personnel and WMATA has developed corrective action plans to create or improve governing procedures, improve work tools and identify additional types of training for Metrorail employees.

The causes of and contributing factors to the events described in more detail below include:

- Non-compliance with operational rules, procedures and instructions
- Inadequate training, including Metrorail's lack of physical characteristics and territory familiarization and qualification requirements
- Loss of/lack of focus and situational awareness

As a result of these investigations Metrorail required personnel to receive reinstruction and refresher training.

Metrorail is in the process of implementing related corrective action plans (CAPs) including:

- C-0183 addresses the finding that Metrorail creates safety risks by not requiring and conducting territory familiarization and physical characteristics training, and not assessing knowledge of physical characteristics prior



to assigning operations personnel work on a line, in a terminal or in a yard (Scheduled completion September 2025).

- C-0268 addresses the finding that Metrorail is not performing its train operator certification activities reliably and consistently in accordance with its safety requirements specified in its Agency Safety Plan and the associated Performance Standardization on Program Manual. Therefore, Metrorail is not ensuring that its trains are only operated by personnel who have demonstrated the skills required to do so safely (Scheduled CAP completion March 2026, interim steps required by the WMSC's February 2024 Train Operator Certification Order were implemented between March and July 2024)

The WMSC and Metrorail's Safety Department continue to discuss with Railcar Engineering the opportunity to improve engineering controls, such as Stop and Proceed Mode on existing railcars or the next generation of railcars, the 8000 Series, so that it resets after actions such as door operation or key up/key down if feasible. Metrorail designed Stop and Proceed Mode (Mode Awareness Tool) to ensure that operators acknowledged that they would be moving a train with zero speed commands prior to doing so, as this is only allowed with specific permission from the control point due to the risk of collision or derailment.

Metrorail conducted safety certification work that may lead to the use of Automatic Train Operation in specific circumstances. Metrorail's initial concept of operations includes multiple scenarios where manual mode will continue to be required as the safest mode of operation. These include mode of operations in single-tracking, in pocket tracks, outside of passenger service, when work crews are on the roadway, in low-adhesion conditions such as snow storms, icy conditions and during fall leaf season, when moving in rail yards or between rail yards and terminals, when provided certain blocks by rail traffic controllers, and in other conditions to reduce the risk of collisions, red signal overruns, and other safety events. The WMSC is currently reviewing Metrorail's safety certification package to determine if Metrorail has followed its own process required to safely activate Automatic Train Operations.

#### **Safety event summaries:**

##### **W-0351 – Brentwood Rail Yard – April 11, 2024 (WMATA ID: E24287)**

While traveling from the mainline to the Brentwood Rail Yard, Prime Mover 39 (PM-39) moved past a red signal without permission. PM-39, while being operated by a different Equipment Operator, struck the ceiling at McPherson Square Station and was being transported to Brentwood Yard for inspection at the time of this safety event. Just prior to this improper movement, the Radio Rail Traffic Controller in Metrorail's Control Center granted PM-39's Equipment Operator an absolute block to no closer than 10 feet of signal B99-06 red and instructed the Equipment Operator to contact the Interlocking Operator at the Brentwood Yard Tower for permission to enter the rail yard. This instruction was repeated a total of six times by the Radio Rail Traffic Controller, three at the request of the Equipment Operator, who then repeated back the directions as required by Metrorail rules.

Minutes later, the Button Rail Traffic Controller identified on their Advanced Information Management System (AIMS) screen that PM-39 had passed Signal B99-06, a red (stop) signal, and was located at Signal B99-16. The Button Rail Traffic Controller inquired with the Interlocking Operator about what they observed. After confirming the red signal overrun, the Interlocking Operator instructed the Equipment Operator to hold their location, and the Radio Rail Traffic



Controller instructed the Equipment Operator to inspect the unit for damage under foul time protection. The Equipment Operator confirmed there was no damage to the unit.

While the majority of signals on the roadway throughout the Metrorail system are located on the right side of the track, signal B99-06 is located on the left side. This event highlights the need for territory familiarization training. There is signage displayed at the 8-car marker at NoMa-Gallaudet Station on track 1 and at Chain Marker B1 114+00 to inform operators of the signal's location, demonstrating the Equipment Operator's lack of focus and situational awareness.

During an investigative interview, the Equipment Operator, who had less than one year of experience in the position, stated they were unfamiliar with the Red Line due to limited on-the-job training, they did not have their map book with them because they were not expecting to operate a vehicle and that they felt rushed to clear the track.

The Equipment Operator was removed from service for post-event toxicology testing. The Prime Mover was removed from service and moved to Brentwood Rail Yard by another operator for further inspection. There was no damage to the switch and no damage to the prime mover.

#### **W-0352 – Anacostia Station – April 19, 2024 (WMATA ID: E24312)**

A Train Operator moved Green Line Train 528 past a red signal at Anacostia Station on track 1. Prior to the event, Green Line trains were passing red signals at Naylor Road Station due to a down track circuit. The Train Operator notified the Rail Traffic Controller in the Control Center that their train lost speed commands in the center of the platform at Anacostia Station. The Rail Traffic Controller in the Control Center granted the Train Operator a permissive block to berth the train on the platform at the 8-car marker, advised that signal F06-08 was red and instructed the Train Operator to standby. The Train Operator repeated by the instructions as required by Metrorail rules. The Train Operator then entered Stop and Proceed, a mode that enables train operators to take a point of power in the absence of speed commands. Stop and Proceed mode does not reset after a door operation until the train gets speed commands. After the Train Operator serviced the station, the mode remained active, allowing the Train operator to continue on despite the red signal and contrary to the direction provided by the Rail Traffic Controller. Two minutes later the Rail Traffic Controller identified an alarm on their AIMS screen and asked if the Train Operator overran the red signal. The Train Operator confirmed they overran the red signal. This created a near-miss of a head on collision with another train that reversed ends outside the station platform limits on the same track and had just crossed over to opposite track as the Train Operator of Train 528 overran the red signal.

Train Service was suspended. The Rail Traffic Controller instructed the Train Operator, who had advised them that the train had two to three cars still on the platform, to walk riders through the train onto the station's platform.

There was no damage to the switch and the train was removed from service and moved to Branch Avenue Rail Yard. The investigation determined that the emergency brake was not activated, there were no faults and that the train operated as commanded by the Train Operator.

The Train Operator was removed from service for post-event toxicology testing.



750 First St. NE • Ste. 900 • Washington, D.C. 20002

Office: 202-384-1520 • Website: [www.wmsc.gov](http://www.wmsc.gov)

As part of the WMSC's order regarding Metrorail's noncompliance with its train operator certification [requirements](#) issued in February 2024, Metrorail identified that the Train Operator, who completed their certification exam in December 2023, was only tested on one of the required types of scenarios.

During an investigative interview the Train Operator, who became certified in December 2023, stated that during the safety event they were rushing, did not identify the red signal and did not remember the instruction to standby.



Washington Metropolitan Area Transit Authority  
Department of Safety  
Office of Safety Investigations  
**FINAL REPORT OF INVESTIGATION A&I E24287**

<b>Date of Event:</b>	April 11, 2024
<b>Type of Event:</b>	O-8, Red Signal Overrun
<b>Incident Time:</b>	06:04 Hours
<b>Location:</b>	B99-06 signal, Chain Marker B1 114+60
<b>Time and How received by SAFE:</b>	06:13 Hours, Safety Information Officer (SIO)
<b>WMSC Notification Time:</b>	06:16 Hours
<b>Responding Safety Officers:</b>	Office of Safety Investigations (OSI)
<b>Rail Vehicle:</b>	Prime Mover (PM 39)
<b>Injuries:</b>	None
<b>Damage:</b>	None
<b>Emergency Responders:</b>	None
<b>SMS I/A Number</b>	20240411#116080

## **Abbreviations and Acronyms**

<b>AIMS</b>	Advanced Information Management System
<b>AOM</b>	Assistant Operations Manager
<b>ARS</b>	Audio Recording System
<b>ATCM</b>	Automatic Train Control Maintenance
<b>CTEM</b>	Car Track Equipment Maintenance
<b>IO</b>	Interlocking Operator
<b>OSI</b>	Office of Safety Investigations
<b>MOC</b>	Maintenance Operations Center
<b>MICC</b>	Metro Integrated Command and Communication Center
<b>MOR</b>	Metrorail Operating Rulebook
<b>NOAA</b>	National Oceanic and Atmospheric Administration
<b>OM</b>	Operations Manager
<b>PM</b>	Prime Mover
<b>RTRA</b>	Office of Rail Transportation
<b>RTC</b>	Rail Traffic Controller
<b>SAFE</b>	Department of Safety
<b>SDOC</b>	Safety Director on Call
<b>SMS</b>	Safety Measurement System
<b>SIO</b>	Safety Information Officer
<b>TRST</b>	Office of Track and Structure
<b>WMATA</b>	Washington Metropolitan Area Transit Authority
<b>WMSC</b>	Washington Metrorail Safety Commission

**B99-06 Signal, CM B1 114 + 60 – Red Signal Overrun**

**April 11, 2024**

**Table of Contents**

Abbreviations and Acronyms----- 2  
Executive Summary ----- 4  
Incident Site ----- 5  
Field Sketch/Schematics ----- 5  
Purpose and Scope ----- 5  
Investigative Methods----- 5  
Investigation ----- 6  
    Chronological Event Timeline----- 10  
    Interview Findings----- 11  
    Weather ----- 11  
    Related Rules and Procedures ----- 11  
    Human Factors ----- 12  
    Post-Incident Toxicology Testing ----- 13  
Findings ----- 13  
Immediate Mitigation to Prevent Recurrence ----- 13  
Probable Cause Statement----- 13  
Recommended Corrective Actions ----- 13  
Appendices ----- 14  
    Appendix A – Interview Summary and Written Statement (redacted) ----- 14  
    Appendix B – Metro Integrated Communication and Command Report (redacted) ----- 16  
    Appendix C – CTEM and Maximo Report (redacted)----- 17  
    ----- 19  
    Appendix D – Why-Tree Analysis----- 21

**Washington Metropolitan Area Transit Authority  
Department of Safety – Office of Safety Investigations**

---

**Executive Summary**

*\*Note that all times listed are approximate and may contain minor variations due to differences between systems of record. \**

On Thursday, April 11, 2024, at 06:06 hours, the Button Rail Traffic Controller (RTC) within the Metro Integrated Communication and Command Center (MICC) contacted the Interlocking Operator at Brentwood Yard and reported that they observed a Red Signal Overrun event via the Advanced Information Management System (AIMS).

At 06:02 hours, the Radio Rail Traffic Controller (RTC) granted Track Unit Prime Mover (PM 39) an Absolute Block to no closer than 10 feet of signal B99-06 red. The Equipment Operator was instructed by the Radio RTC to contact the Brentwood Control Tower Interlocking Operator for permission to enter the Yard and notify the MICC Rail Traffic Controller (RTC) when clear of the mainline. The RTC contacted the Brentwood Interlocking Operator and advised them that PM-39 was approaching signal B99-06 red.

At 06:08 hours, the Button RTC contacted the Brentwood Interlocking Operator to verify which direction the PM-39 was entering Brentwood Yard. During the conversation, the Button RTC noticed on the Advance Information Management System (AIMS), that the track unit was holding at signal B99-16 indicating the track unit passed signal B99-06 which displayed a red aspect. The Interlocking Operator contacted Equipment Operator on PM 39 and instructed them to hold their location.

Notifications were made to the Operation Manager (OM), Assistant Operations Manager (AOM), the Safety Information Officer (SIO), Washington Metropolitan Safety Commission (WMSC), Safety Director on Call (SDOC), Automatic Train Control (ATC) and the Office of Safety Investigation (OSI) were dispatched to the scene.

The Radio RTC requested the Equipment Operator inspect the track unit for damage under foul time protection. The Automatic Train Control Maintenance (ATCM) confirmed no damage to Switch 7 by Chain Marker (CM) B1 114+60, after the switch was tested. SAFE personnel arrived and conducted an investigation.

After the investigation, the scene was released by WMSC and SAFE personnel. In accordance with the Office of the Chief Mechanical Officer, Incident Investigation Team, Operations Administrative Policy 102.06, the Metro Integrated Command and Communications Center promptly initiated the removal of PM 39 non-revenue service for post-incident investigative measures.

The Equipment Operator was removed from service for post-incident testing. This action adhered to the Rail Vehicle Event Investigation Policy, ensuring a comprehensive examination of the incident. A relief Equipment Operator moved PM 39 from the incident location to Brentwood Yard track 18 for storage and further inspection. No damage or injuries resulted from the event.

The probable cause of the Red Signal Overrun event on April 11, 2024, at Brentwood Yard was the Equipment Operator's lack of situational awareness and unfamiliarity with the Redline. The Equipment Operator failed to notice the signage located at the 8-car marker on the platform of



NoMa-Gallaudet Station indicating signal B99-06 was on the left side when entering Brentwood Yard.


This sign was meant to alert the operator that B99-06 was ahead on the left side of the track. Additionally, a second warning sign was located at Chain Marker B1 114+00, which was 60 feet before the signal and interlocking. This sign was also intended to alert operators that the B99-06 signal is located on the left side of the track.

A contributing factor was the Equipment Operator's failure to follow the instruction to stop no closer than 10 feet to signal B99-06 red.

### **Incident Site**

B99-06 signal, Chain Marker 114+60

### **Field Sketch/Schematics**



The above depiction is not to scale.

### **Purpose and Scope**

The purpose of this accident investigation and candid self-evaluation is to collect and analyze available facts, determine the probable cause(s) of the incident, identify contributing factors, and make recommendations to prevent a recurrence.

### **Investigative Methods**

Upon receiving notification of the Red Signal Overrun at the Brentwood Rail Yard signal B99-06 on April 11, 2024, SAFE dispatched a cross-functional team to assess the scene and conduct the subsequent investigation. SAFE team members worked with relevant WMATA subject matter experts to review the incident's facts and data.

The investigative methodologies included the following:

- Physical site assessment

- Formal Interviews – SAFE interviewed one individual as part of this investigation. The interview included persons present at, during, and after the incident, those directly involved in the response process, and representatives from the Washington Metrorail Safety Commission (WMSC). SAFE interviewed the following individual:
  - Equipment Operator
- Informal Interviews – Collected through conversations with individuals during the investigation to provide background and supporting information. Written statements were reviewed by personnel present during the event.
- Documentation Review – A collection of relevant work history information and process documentation contained in Metro systems of record. These records include:
  - Metrorail Operating Rulebook (MOR)
  - National Oceanic and Atmospheric Administration (NOAA)
  - Equipment Operator 30-day Work History
  - Equipment Operator Certification
  - MICC Report
  - Maximo Work Orders
  - Car Tack Equipment Maintenance (CTEM) Inspection of PM 39
  - Office of Track and Structure (TRST) Managerial Incident Investigation Report
  - Equipment Operator Incident Report
- System Data Recording Review – A collection of information contained in Metro Data Recording Systems. This data includes:
  - Audio Recording System (ARS) playback, including OPS 1, BWYD Radio and OPS 1 Phone.
  - Closed-Circuit Television (CCTV)
  - Advance Information Management System (AIMS)

## **Investigation**

On Thursday, April 11, 2024, at 06:06 hours, the Button Rail Traffic Controller (RTC) within the Metro Integrated Communication and Command Center (MICC) contacted the Interlocking Operator at Brentwood Yard and reported that they observed a Red Signal Overrun event.

PM 39 was traveling from McPherson Square Station to Brentwood Yard by a second Equipment Operator. The original Equipment Operator was removed from service after PM 39 struck a ceiling tile at McPherson Square Station. According to the Audio Recording System (ARS), at 06:02 hours, the MICC Radio RTC granted the Equipment Operator of PM 39 an absolute block no closer than 10 feet of signal B99-06 red and contact Brentwood Control Tower for permission to enter Brentwood Yard.

The instruction was given three times during the initial exchange. The instruction was repeated at the Equipment Operator's request another three times. The Equipment Operator responded with 100% repeat back of the message. The Equipment Operator was instructed to contact Brentwood Control Tower for permission to enter the Yard and notify the MICC when clear of mainline. The Button RTC contacted the Brentwood Interlocking Operator and informed them that PM 39 was approaching signal B99-06 red.

Signage was in place at the 8-car marker, track 1 of NoMa-Gallaudet Station was present regarding the positioning of signal B99-06. This sign was meant to alert the operation personnel

that signal B99-06 was ahead on the left side of the track. Additionally, a second warning sign was located at CM B1 114+00, which was 60 feet before the signal and interlocking.

At 06:03 hours, the Equipment Operator of PM 39 advised the Radio RTC that they were clear of NoMa-Gallaudet Station, and PM 39 began moving towards Brentwood Yard from the NoMa-Gallaudet Station on track 1. During this time the Button RTC contacted the Interlocking Operator and inquired why PM 39 was holding at signal B99-16.

The Interlocking Operator stated, no PM 39 was holding at signal B99-06. The Button RTC explained they observed via the AIMS, that PM 39 was holding at signal B99-16 which indicated overran signal B99-06, which displayed a red aspect.

At 06:06 hours, the Buttons RTC and Brentwood Interlocking Operator confirmed that PM 39 had run the signal B99-06 red via the Interlocking Board and AIMS system. The Radio RTC notified the Equipment Operator on PM 39 they had overrun the Signal B99-06 red and to standby. The Radio RTC instructed the Equipment Operator on PM 39 to switch to Brentwood Yard Ops and contact the Interlocking Operator via the radio.

At 06:07 hours, the Buttons RTC notified the Assistant Operations Manager (AOM) of the event. The AOM directed that PM 39 remain at that position.

At 06:08 hours, the Button RTC instructed the Interlocking Operator to contact the Equipment Operator on PM 39 to advise the track unit to hold their location.

At 06:09 hours, OPS 1 began single-tracking between Noma and Rhode Island Avenue Station byway of Brentwood on track 2.

At 06:10 hours the Safety Information Officer (SIO) notified the Safety Director on Call (SDOC) of the event. The SDOC directed OSI respond to the scene.

At 06:12 hours, the SIO notified the on call SAFE investigator who responded.

At 06:14 hours, Rail 2 notified the Maintenance Operations Center (MOC) and was advised MOC units were already enroute to scene.

At 06:14 hours, the Brentwood Interlocking Operator instructed the Equipment Operator of PM 39 to switch back to OPS 1 Radio. The Equipment Operator did and was advised by the Radio RTC to hold their location.

At 06:16 hours, the SIO left a voicemail notification for the on call WMSC representative. Two (2) additional attempts were made to reach the WMSC on call representative.

Between 06:18 and 06:21 hours, the Radio RTC requested the Equipment Operator inspect the PM for damage under foul time protection. The Equipment Operator acknowledged foul time, completed the ground walk, and confirmed no damage to PM 39. The Equipment Operator was removed from service and transported for post-incident testing.

At 06:25 hours, ATCM requested and was granted foul time protection to inspect the switch and complete manual test of the switch. ATCM then requested that the Button RTC exercise the switch. ATCM reported the Switch 7 at Chain Marker (CM) B1 114+60 was in working order with no damage.

At 06:37 hours, the relief Equipment Operator for PM 39 arrived and was standing by.

At 06:42 hours, the SIO was advised by the SDOC that the WMSC had been notified and had granted a WMSC scene release.

At 06:49 hours, ATCM advised Switch 7 was revenue ready and relinquished foul time.

At 06:58 hours, the SAFE investigator arrived and requested foul time on track 1 from NoMa-Gallaudet Station to the end of the roadway. The Radio RTC granted foul time and advised the 3<sup>rd</sup> rail was still energized. The RTC also requested the SAFE investigator photograph the switch and forward them to MICC and call landline when completed. The SAFE Investigator acknowledged.

At 07:06 hours, the SAFE investigator boarded PM 39, relinquished foul time, and released the scene.

At 07:07 hours, the Radio RTC directed PM 39 to switch to Brentwood Yard 1 radio and prepare for movement to a Brentwood storage track. The Equipment Operator of PM 39 acknowledged and switched.

At 07:08 hours, the Brentwood Interlocking Operator gave PM 39 an absolute block to the north bump post track 18 and storage. The Equipment Operator of PM 39 along with the SAFE investigator and the previous Equipment Operator of PM 39 moved to the bump post of track 18.



Image 1 (left) signal alert signage on the platform of NoMa-Gallaudet Station, (right) signal alert signage at CM B1 114+00.



At 07:19 hours, the Brentwood Interlocking Operator confirmed all operations had been restored at 07:10 hours.

No damage or injuries resulted from the event.




Figure 1 - Depicts PM 39 passing B99-06 signal red at 06:04 hours and continuing to a stop at B99-16.

## Chronological Event Timeline

A review of ARS playback, i.e., phone and radio communications, revealed the following timeline:

Time	Description
06:01:01 hours	<u>PM 39</u> : Reported clear Union Station track 1. <u>Radio RTC</u> : Acknowledged. [Radio/Ops 1]
06:02:04 hours	<u>RTC OPS 1</u> : Advised PM 39 three times an absolute block to Signal B99-06. Then repeat additional three times Signal 06. <u>PM 39</u> : Initially asked to repeat and then provided acknowledgement 100 % repeat back. [Radio/OPS 1]
06:03:20 hours	<u>BW Yard 1</u> : <i>The radio transmission is unintelligible.</i> [Radio/BW Yard 1]
06:03:59 hours	<u>PM 39</u> : Advised clear NoMa-Gallaudet Station track 1. <u>Radio RTC</u> : Acknowledged with repeat back. [Radio/Ops 1]
06:04:36 hours	<u>PM 39</u> overran signal B99-06 red. [AIMS]
06:06:37 hours	<u>Buttons RTC</u> and <u>Brentwood Interlocking Operator Tower</u> identified <u>PM 39</u> overran signal B99-06 red while on phone. [Phone/OPS 1]
06:06:46 hours	<u>RTC OPS 1</u> : Contacted <u>PM 39</u> <u>PM 39</u> : Acknowledged. Advised holding at signal B99-16. <u>RTC OPS 1</u> : Advised that they were to stop at signal B99-06, not signal B99-16. Instructed to standby while they contact the Tower. <u>PM 39</u> : Advised that they were switching to the Tower radio ops. [Radio/OPS 1]
06:07:55 hours	<u>Buttons RTC</u> : Advised AOM of <u>PM 39</u> event. <u>AOM</u> : Keep <u>PM 39</u> in position. [Phone/OPS 1]
06:09:16 hours	<u>RTC OPS 1</u> : Announced single tracking. [Radio/OPS 1]
06:10:43 hours	<u>SIO</u> notified <u>SDOC</u> of the event. <u>SAFE</u> directed to respond. [Phone/SIO]
06:12:48 hours	<u>SIO</u> notified the Office of Safety Investigations (OSI) on call who responds to scene. [Phone/SIO]
06:14:24 hours	<u>Rail 2</u> calls <u>MOC</u> and is advised <u>MOC</u> units enroute to scene. [Phone/Rail 2]
06:14:47 hours	<u>BW Yard 1</u> : Directed <u>PM 39</u> to switch to <u>OPS 1</u> Radio. <u>PM39</u> : Acknowledged and switched to <u>OPS 1</u> . [Radio/BW Yard 1] <u>OPS 1</u> : Acknowledged and advised <u>PM 39</u> to standby. [Radio/OPS 1]
06:16:32 hours	<u>Safety Information Officer</u> : A voicemail notification was left for <u>WMSC</u> . Two other attempts were made later. [Phone/SIO]
06:18:16 hours 06:21:40 hours	<u>RTC OPS 1</u> : Directed <u>PM 39</u> to complete a ground walk. <u>PM 39</u> received directions on how to complete it. <u>PM 39</u> given foul time and advised to relinquish when complete. <u>PM 39</u> : Relinquished foul time, on <u>PM 39</u> reports no damage/issues. [Radio/OPS 1]
06:25:46 hours	<u>ATC</u> : Requested foul time for track switch inspection. <u>RTC OPS 1</u> : Granted. <u>ATC</u> : Reported good inspection switch 7, request manual test of switch and then request <u>RTC</u> exercise switch. Reports in working order. [Radio/OPS 1]
06:37:28 hours	<u>PM 39</u> : <u>Relief</u> Equipment Operator boarded <u>PM 39</u> standing by. <u>RTC OPS 1</u> : Acknowledged. Radio/OPS 1

Time	Description
06:42:55 hours	SIO Desk advised by SDOC contact made and scene release-WMSC. [Phone/SIO]
06:49:26 hours	<u>ATC</u> : Advised switch is revenue ready and relinquishes foul time. <u>RTC OPS 1</u> : Acknowledged. [Radio/OPS 1]
06:58:06 hours	<u>SAFE OSI</u> : Requested foul time track 1 NoMa to end of roadway. <u>RTC OPS 1</u> : Granted and advised 3 <sup>rd</sup> rail still energized. Asked OSI to photograph signal and land line RTC. [Radio/OPS 1]
07:06:15 hours	SAFE OSI relinquished foul time and aboard PM39. [Radio/OPS 1]
07:07:14 hours	<u>RTC OPS 1</u> : Advised PM 39 to switch to BW Yard 1 radio to prepare movement to BW storage. <u>PM 39</u> : Acknowledged and switching. [Radio/OPS 1]
07:08:20 hours	<u>BW Yard 1</u> : Granted PM39 (and SAFE) absolute block to north bump post 18 track and storage. <u>PM 39</u> : Acknowledged and begins movement. [Radio/BW Yard 1]
07:19:25 hours	<u>BW Tower</u> : Advised unknown party that all operations restored at 07:10 hours. [Phone/BW Contr]

*\*\*Note: Times above may vary from other systems' timelines based on clock settings and reporting sources.*

## Interview Findings

*As part of the investigation launched into the event, the Office of Safety Investigations interviewed one (1) person. The interviews identified the following key findings associated with this event. The findings detailed below include reported information from involved personnel and may conflict with other data sources contained in the report.*

## Equipment Operator -

- The Equipment Operator stated they were unexpectedly assigned to operate PM 39.
- The Equipment Operator was unfamiliar due to limited on the job training and having been operating for under a year. It was the operator's first time operating in that direction into Brentwood Yard.
- The Equipment Operator stated they did not have their map book with them since they had not anticipated operating that shift.
- The Equipment Operator also felt rushed to clear the track due to delay from previous event extending into revenue hours.

## Weather

At the time of the incident, NOAA recorded the temperature at 64 ° F, with cloudy skies, winds of 11 mph, and 79% humidity. The weather was not a contributing factor in this incident (Weather source: NOAA – Location: [Washington, D.C.]).

## Related Rules and Procedures

Metro Operating Rulebook

### 3.3 Signals Requiring a Stop

Rail vehicles shall not be operated past or closer than a point 10 feet in approach of an interlocking signal or lamp displaying a red aspect, a red flag, or a dark interlocking signal, except at a bumping

post or pocket track, or unless authorized by the Rail Traffic Controller or the Interlocking Operator and the move is consistent with customer safety.

## **Human Factors**

### Evidence of Fatigue

#### Equipment Operator

SAFE evaluated signs and symptoms of fatigue that may have been present at the time of the incident. No signs or symptoms of fatigue were detected from the available data. Video of the incident was not available. The Equipment Operator reported feeling fully alert at the time of the incident. The Equipment Operator reported experiencing no symptoms of fatigue in the time leading up to the incident.

### Fatigue Risk

#### Equipment Operator

SAFE evaluated incident data for fatigue risk factors. No significant risk was identified. The incident time of day did not suggest an increased risk of fatigue-related impairment. The Equipment Operator reported keeping a regular sleep schedule in the days leading up to the incident. The Equipment Operator worked the midnight shift in the days leading up to the incident. The Equipment Operator was awake for sixteen hours at the time of the incident. The Equipment Operator reported 5.5 hours of sleep in the 24 hours preceding the incident. The off-duty period was sixteen hours, providing an opportunity for 7-9 hours of sleep. This was more than the employee's usual workday sleep durations. The Equipment Operator reported no issues with sleep.



## Post-Incident Toxicology Testing

WMATA's Drug and Alcohol Program determined that the Equipment Operator complied with the Drug and Alcohol Policy and Testing Program 7.7.3/6.

## Findings

- The B99-06 signal is located on the left side of the tracks, which differs from the right side location of many signals.
- PM 39 was transported from McPherson Square Station to Brentwood Rail Yard.
- No damaged was observed to any switches or the track unit.
- There is a warning sign at the 8-car marker at NoMa-Gallaudet Station on track 1: "Brentwood Yard Signal B99-06 Ahead on Left."
- At CM B1 114+00, on the right side of the running rails, is a warning sign "Brentwood Yard Signal B99-06 on Left" with an arrow pointing to the left.

## Immediate Mitigation to Prevent Recurrence

- The Equipment Operator was removed from service for post-incident testing.
- The PM remained at Brentwood Rail Yard for a thorough damage inspection.
- Switch 7 was inspected for damage and exercised before being placed back in service.

## Probable Cause Statement

The probable cause of the Red Signal Overrun event on April 11, 2024, at Brentwood Yard was the Equipment Operator's lack of situational awareness and unfamiliarity with the Redline. The Equipment Operator failed to notice the signage located at the 8-car marker on the platform of NoMa-Gallaudet Station indicating signal B99-06 was on the left side when entering Brentwood Yard. This sign was meant to alert the operator that B99-06 was ahead on the left side of the track. Additionally, a second warning sign was located at Chain Marker B1 114+00, which was 60 feet before the signal and interlocking. This sign was also intended to alert operators that the B99-06 signal is on the left side of the track.

A contributing factor was the Equipment Operator's failure to follow the instruction to stop no closer than 10 feet to signal B99-06 red.

## Recommended Corrective Actions

<b>Corrective Action Code</b>	<b>Description</b>	<b>Responsible Party</b>	<b>Estimated Completion Date</b>
116080_SAFE CAPS_RTRA_ 002	The Equipment Operator is to attend refresher training.	Safety Risk Coordinator, Office of Track and Structures	Completed

## Appendices

### **Appendix A – Interview Summary and Written Statement (redacted)**

*The below narratives summarize the incident and represent the statements made by the involved individual. As such, times and details may present a conflict with the data contained in systems of record.*

#### Equipment Operator

The Equipment Operator has been a WMATA employee for less than one year. This position has been the only position held at WMATA. The Equipment Operator is RWP Level 2 certified, expiring 08/2024.

The Equipment Operator stated they were assigned to operate PM 39. The Equipment Operator was unfamiliar due to limited on-the-job training and having been operating for under a year. It was the operator's first time operating in that direction into Brentwood Yard.

The Equipment Operator stated they did not have their map book with them since they had not anticipated operating that shift. The Equipment Operator also felt rushed to clear the track due to delay from previous event extending into revenue hours.

The Equipment Operator stated they did not see a sign referencing the signal being on the left side. No mention was made by supervisor or RTC that the signal was on the left. A brief mention was made in training that a few signals were on the left.

The Equipment Operator stated they felt they were operating without their map book. The Equipment Operator stated they would be more prepared in the future to be able to operate with no or short notice.



# Witness or Employee Statement Form

WASHINGTON METROPOLITAN AREA TRANSIT AUTHORITY

TO BE COMPLETED AND  
DISTRIBUTED WITHIN 24 HOURS

USE SEPARATE FORM FOR EACH PERSON

Page of

PERSONNEL INVOLVED (Use This Block For WMATA Employees and Contractors)			
Name	Age	Employee # or MTPD Badge #	
Phone Number	Job Title	Department	Division/Section
Last Day Worked (prior to)	Hours Worked (within last 24 hrs)	Overtime?	
INVOLVED PERSON OR WITNESS (Use This Block For Non-WMATA Involved Person or Witness)			
Name	Phone Number	E-Mail	
Address			
INCIDENT			
Date	Incident Time	Date/Time Reported	Location
Incident ID# (From ROCC, BOCC, etc.)	Worksafe Incident #		
What happened prior to the incident?			
Describe the incident			
What happened after the incident?			
Form Completed by: (Print Name)		Date	
Signature			

50.689 10/09 Original: RISK Copy 1: Department Copy 2: SAFE Copy 3: Employee File Photocopy to Employee

Document 1 – RTRA Incident Report from Equipment Operator.

Incident Date: April 11, 2024 Time: 06:04 hours  
Final Report – Red Signal Overrun  
E24287

Drafted By: SAFE 709 – 05/31/2024  
Reviewed By: SAFE 702 – 06/03/2024  
Approved By: SAFE 707 – 06/10/2024

# Appendix B – Metro Integrated Communication and Command Report (redacted)



## Washington Metropolitan Area Transit Authority Maintenance and Material Management System ROC Approved Incident Report

Page 5 of 22  
MX76PROD

Incident Number : 8747896		SMS Number : SMS ID: 20240411#116090MX	
Red signal overrun Track Unit PM-39 Operator [REDACTED] at signal B99-06 signal red and No switches clamped for the move.			
Date/Time 04/11/2024 06:04	Trouble Code RSIG	Station Location B99: (BRENTWOOD YARD)	Reported By
RED SIGNAL OVERRUN	RSIG	Location Details	Notifications
Responsibility Code TRK	TRACK DEPT TRK	Direction OUTBOUND	Resolved By
Train ID 126	Line RED	Track Number N/A	Approved/Closed by
		Chain Markers	Org_OCC ROCC

Delays in Minutes				
Line Delay	Train Delay	Passenger Delay		
22	22	22		

Trips Modified				
Partial	Late Dispatch	Recreated	Not Dispatched	Offloads
0	0	0	0	0

Incident Chronology (Timeline)				
Time	Add'l Pass. Delays	Add'l Trouble	Incident Level Code	Description
06:04	22	RSIG	C2	Red signal overrun Track Unit PM-39 Operator [REDACTED] at signal B99-06 signal red and No switches clamped for the move.
06:15				PM-39 [REDACTED] was granted foul time to perform a ground walk around and update central. Revenue trains routing and single track operations initiated.
06:23				PM-39 [REDACTED] relinquished foul time and reported ground walk around was clear and no damage found.
06:26				ATC [REDACTED] arrived on the scene to assist and was granted foul time to inspect switch 7 for revenue service. Single track operations continued.
06:30				Train 126 was holding Brookland station track two. Revenue trains inside the single tracking area between Noma-Gallaudet to Rhode Island Avenue stations via track two. Every other revenue train was offloaded and turned for service from Judiciary Square track one towards Shady Grove. Train 115 was the first train to offload and turn back.
06:50				ATC [REDACTED] relinquished foul time and reported switch 7 passed obstruction and exercise tests and safe for revenue service. PM-39 Supervisor [REDACTED] was granted permission to contact Brentwood yard tower at B99-16 signal for permission to enter the track yard.
06:52				Train 126 track two Brookland station was moving and continued in revenue service towards Shady Grove.
07:10				Single track operations concluded and Train 129 was he first train to continue normal track one Noma-Gallaudet towards Glenmont.

WT ROC Approved Incident.rtdtlesian

04/12/2024 00:24

Document 2 – Depicts a redacted Metro Integrated Communication and Command Report.

Incident Date: April 11, 2024 Time: 06:04 hours  
Final Report – Red Signal Overrun  
E24287

Drafted By: SAFE 709 – 05/31/2024  
Reviewed By: SAFE 702 – 06/03/2024  
Approved By: SAFE 707 – 06/10/2024

# Appendix C – CTEM and Maximo Report (redacted)



## CTEM Post-derailment & Accident Damage Inspection Form

(1 Form per Unit)

DATE: 4-11-24 INSPECTOR: [REDACTED] UNIT #: PM39  
 INCIDENT #: [REDACTED] INCIDENT LOCATION: [REDACTED]

**GUIDELINES:**

- This form is to be used for all rail vehicles involved in derailments, accidents.
- This form is to function as a guide to assist in ensuring that all vehicles are inspected to ensure that they still meet standards for operation.
- Some reference to codes and standards may be required to complete this inspection form.
- All inspection items on this form are to be marked as:  
 ✓ = Passed    **X** = Failed    **NA** = Not Applicable    **UC** = Unable to Check

NOTE: Any items that have failed are to be documented in the "Inspection Fault Report" field included on this form.

Incident Information:	(NOTE: Use blank field under each question for additional information if answered Yes.)
Did the unit contact the 3rd rail? (If Yes, where was the contact on the unit?)	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Did the unit contact infrastructure such as a wall or platform? (If Yes, what was contacted?)	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Did the unit contact another unit? (If Yes, what unit and where was the contact on the unit?)	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

*CEILING TILE / PANEL*

Truck Inspection:	
Roller bearings - no visual damage and in accordance with Rule 36	<input checked="" type="checkbox"/>
Roller bearings - no unusual noises; hand spun or run-by test	<input checked="" type="checkbox"/>
Bearing Adapters - within wear limits and in accordance with Rule 37	<input checked="" type="checkbox"/>
Drive systems - no visual damage or leaks	<input checked="" type="checkbox"/>
Side frames and bolsters - no visual damage and in accordance with Rule 47 & 48	<input checked="" type="checkbox"/>
Ride control - friction shoes & bearing adapters within limits and in accordance with Rule 46	<input checked="" type="checkbox"/>
Springs - no damage, correctly seated and in accordance with Rule 50	<input checked="" type="checkbox"/>
General - no visual damage, all components secured and in accordance with Rule 74	<input checked="" type="checkbox"/>
NOTES:	
<i>PM39 LOCATED TRACK 18 STORAGE AT B99 YARD - AT BUMP POST</i>	

Chassis Inspection:	
Chassis and sub-frames - no cracks, twists, other visual damage	<input checked="" type="checkbox"/>
Center plates and side bearing - no visual damage and in accordance with Rule 60, 61, and 62	<input checked="" type="checkbox"/>
Body & decking - no structural, cladding, or decking damage	<input checked="" type="checkbox"/>
Loading - load is balanced and secure	<input checked="" type="checkbox"/>
Coupler and draft arrangement - no visual damage and in accordance with Rule 16	<input checked="" type="checkbox"/>
General - no visual damage, all components secured and in accordance with Rule 74	<input checked="" type="checkbox"/>
NOTES:	
<i>UNIT COUPLED TO FLAT # F538 - NO VISUAL DAMAGE</i>	

Document 3 – CTEM post-incident Inspection Report also includes a reference to a previous event where PM 39 collided with a ceiling panel prior to the red signal overrun, page 1 of 2.

Incident Date: April 11, 2024 Time: 06:04 hours  
 Final Report – Red Signal Overrun  
 E24287

Drafted By: SAFE 709 – 05/31/2024  
 Reviewed By: SAFE 702 – 06/03/2024  
 Approved By: SAFE 707 – 06/10/2024



### CTEM Post-derailment & Accident Damage Inspection Form

Wheel Inspection:	
Wheels - Discoloration, cracks, spalling, and signs of movement	UC
Gauging - Back to back measurement and in accordance with Rule 43	UC
Gauging - Flanges & tread, and in accordance with Rule 41	UC
General - no visual damage	✓
NOTES: UNIT STORED ON LIVE (HOT) RAIL - NO VISUAL DAMAGE	

Brake Inspection:	
Brake rigging & cylinders - no visual damage or apparent leaks	UC
Brake hoses & trunk lines - no visual damage or apparent leaks	✓
Brake piping, valving and cocks - no visual damage or apparent leaks	✓
Brake operation - passes functional test	✓
Friction shoes - greater than 3/8" and accordance with Rule 12	✓
Rolling brake test - unit stop as designed without locking up wheels	UC
Hand brake - no visual damage and applies as designed	✓
General - no visual damage, all components secured and in accordance with Rule 74	✓
NOTES: UNIT PASSED STANDING BRAKE TEST - BOTH SERVICE AND PARKING	

Miscellaneous Equipment Inspection:	
Horn - operational <i>BOTH AIR AND ELECTRIC</i>	✓
Lighting - operates as designed	✓
Radio - perform radio check, operates as designed	✓
Propulsion and braking controls - all controls operate as designed	✓
Cameras - clear picture, operates as designed	✓
Emergency equipment - Interlocks emergency valves, E-stops, etc., operate as designed	✓
Locks & restraints - mechanical locks and restraints are in place and operate as designed	✓
NOTES:	

Inspection Fault Report:
<i>PAINT SCUFFING - ONLY PHYSICAL DAMAGE - UNIT SEEMS TO OPERATE WITH NO ISSUES.</i>

Can unit be returned to service?  Yes  No

Inspector's Signature:

Document 4 – CTEM post-incident Inspection Report page 2 of 2.

Incident Date: April 11, 2024 Time: 06:04 hours  
 Final Report – Red Signal Overrun  
 E24287

Drafted By: SAFE 709 – 05/31/2024  
 Reviewed By: SAFE 702 – 06/03/2024  
 Approved By: SAFE 707 – 06/10/2024







Washington Metropolitan Area Transit Authority  
Maintenance and Material Management System  
**Work Order Details**

Work Order #: 18532775  
Type: IN



Status: INPRG  
04/11/2024 08:22

Work Description: Signal overrun  
Job Plan Description:

Work Information			
Asset: MPM39	PM39, PRIMEMOVER, HARSCO, 354C, S/ N 6100771, 4	Owning Office: CTBM	Parent:
Asset Tag: MPM39		Maintenance Office: CTBM-ALEX-HVYR	Create Date: 04/11/2024 08:18
Asset S/N: 6100771		Labor Group: CTBM-NCAR-HVY	Actual Start: 04/11/2024 08:22
Location: 1213	C99, ALEXANDRIA YARD	Crew:	Actual Comp:
Work Location: 1743	B99, BRENTWOOD YARD, STORAGE AREA	Lead:	Item: CTBM49200006
Failure Class: CTBM001	GENERAL	GL Account: WMATA-02-33380-50499070-041-*****0 PR**	Supervisor: ED07403
Problem Code: 2907	SAFETY INSPECTION	Requestor Phone: 301/955-5279	Target Start:
Requested By:			Target Comp:
			Scheduled Start:
Create-Mileage: 0.0		Complete-Mileage: 0.0	

**Task ID**

Task ID	Description	Component	Work Accomplished	Reason	Status	Position	Warranty?
10	Signal overrun Inspect at station yard - brake test - lights - all safety items - no abnormality at this time 000-400 CTBM-CAR TRACK EQUIPMENT (NON-REVENUE VEHICLES)	REVENUE VEHICLES	INSPECTED	INSPECTION	INPRG		N

Actual Labor									
Task ID	Labor	Start Date	End Date	Start Time	End Time	Approved?	Regular Hours	Premium Hours	Line Cost
10		04/11/2024	04/11/2024	10:00	14:00	N	04:00	00:00	\$196.01
10		04/11/2024	04/11/2024	10:00	14:00	N	04:00	00:00	\$151.71
Total Actual Hour/Labor:							08:00	00:00	\$347.72

Failure Reporting			
Cause	Remedy	Supervisor	Remark Date
		ED07403 Wolard, Steven W	
Remarks:			


Document 6 – Work Order Inspection of PM 39.

Incident Date: April 11, 2024 Time: 06:04 hours  
Final Report – Red Signal Overrun  
E24287

Drafted By: SAFE 709 – 05/31/2024  
Reviewed By: SAFE 702 – 06/03/2024  
Approved By: SAFE 707 – 06/10/2024



## Appendix D – Why-Tree Analysis



## Root Cause Analysis


7   
E24287 – Red Signal Overrun – B99-06

Table 1 - Root Cause Analysis



Washington Metropolitan Area Transit Authority  
Department of Safety (SAFE)  
Office of Safety Investigations (OSI)  
**FINAL REPORT OF INVESTIGATION A&I E24312**

<b>Date of Event:</b>	April 19, 2024
<b>Type of Event:</b>	O-8: Red Signal Overrun
<b>Incident Time:</b>	22:05 hours
<b>Location:</b>	Anacostia Station, track 2 - Signal F06-08
<b>Time and How received by SAFE:</b>	22:11 hours, Mission Assurance Coordinator (MAC)
<b>WMSC Notification Time:</b>	22:49 hours
<b>Responding Safety Officers:</b>	WMATA: Office of Safety Investigations (OSI) WMSC: Other:
<b>Rail Vehicle:</b>	Train ID 528 (L7678-7679x7511-7510x7386-7387x7519-7518T)
<b>Injuries:</b>	None
<b>Damage:</b>	None
<b>Emergency Responders:</b>	None
<b>SMS I/A Number</b>	20240420#116295MX

# Anacostia Station – Red Signal Overrun

April 19, 2024

## Table of Contents

Abbreviations and Acronyms	3
Executive Summary	4
Incident Site	5
Field Sketch/Schematics	5
Purpose and Scope	5
Investigative Methods	5
Investigation	6
Chronological Event Timeline	7
Automated Information Management System (AIMS)	9
The Office of Chief Mechanical Officer (CMOR) / Vehicle Monitoring and Diagnostic System (VMDS)	10
Office of Systems Maintenance, Office of Radio Communications (COMR)	12
Office of Rail Transportation (RTRA)	12
Interview Findings	12
Weather	13
Related Rules and Procedures	13
Human Factors	13
Fatigue	13
Post-Incident Toxicology Testing	14
Findings	14
Immediate Mitigation to Prevent Recurrence	14
Probable Cause Statement	14
Recommended Corrective Actions	14
Appendices	15
Appendix A – Interview Summary	15
Appendix B – Scene Photographs	16
Appendix C – Train Operator’s Manifest	20
Appendix D – Train Operator’s Certification	21
Appendix X – Why-Tree Analysis	23

## **Abbreviations and Acronyms**

<b>ARS</b>	Audio Recording System
<b>ATCM</b>	Automatic Train Control Maintenance
<b>CAP</b>	Corrective Action Plan
<b>CCTV</b>	Closed-Circuit Television
<b>CMOR</b>	Chief Mechanical Officer
<b>MAC</b>	Mission Assurance Coordinator
<b>MOC</b>	Maintenance Operations Control
<b>MICC</b>	Metro Integrated Command and Communication Center
<b>MOR</b>	Metrorail Operating Rulebook
<b>NOAA</b>	National Oceanic and Atmospheric Administration
<b>OM</b>	Operations Manager
<b>OSI</b>	Office of Safety Investigations
<b>RTC</b>	Rail Traffic Controller
<b>RTRA</b>	Office of Rail Transportation
<b>SAFE</b>	Department of Safety
<b>SDOC</b>	Safety Director On Call
<b>SMS</b>	Safety Measurement System
<b>SPOTS</b>	System Performance Ontime Summary
<b>WMATA</b>	Washington Metropolitan Area Transit Authority
<b>WMSC</b>	Washington Metrorail Safety Commission
<b>VMDS</b>	Vehicle Monitoring and Diagnostic System

### **Washington Metropolitan Area Transit Authority**

---

Incident Date: 04/19/2024      Time: 22:05 hours  
Final Report – Red Signal Overrun  
E24312

Drafted By: SAFE 702 – 06/13/2024
Reviewed By: SAFE 707 - 06/13/2024
Approved By: SAFE 707 – 06/18/2024

Page 3

## Department of Safety – Office of Safety Investigations

---

### Executive Summary

*\*Note that all times listed are approximate and may contain minor variations due to differences between systems of record. \**

On Friday, April 19, 2024, at 22:05 hours, Train ID 528 (L7678-7679x7511-7510x7386-7387x7519-7518T) located at Anacostia Station on track 2 passed signal F06-08 displaying a red aspect.

Prior to the event, at 22:03 hours, the Radio Rail Traffic Controller (RTC) granted Train ID 528 a permissive block to berth the train on the platform at Anacostia Station on track 2, advised the Train Operator that signal F06-08 was red, and instructed the Train Operator to standby. The Train Operator acknowledged, repeated the instruction, and then entered the Stop and Proceed method to move the train.

At 22:05 hours, Train ID 528 passed signal F06-08 red.

At 22:06 hours, the Radio RTC contacted the Train Operator and inquired if the train had passed signal F06-08 red. The Train Operator confirmed passing signal F06-08 red.

The Button RTC notified the Operations Manager (OM), and Communications Section. Metro 1 notified Maintenance Operations Center (MOC), and Bus 1 to establish a bus bridge. Communications notified the Metro Transit Police Department (MTPD). The Mission Assurance Coordinator (MAC) contacted the Safety Director On Call (SDOC) and the Safety On-Call personnel.

Train service was suspended between Navy Yard Station and Congress Heights Station.

At 22:13 hours, the Train Operator advised the Radio RTC that two to three cars were remaining on the platform. The Radio RTC instructed the Train Operator to walk the customers through the train onto the platform and verify the train was clear of all passengers.

The first Safety Investigator arrived at 22:41 hours, and initiated the initial investigation. At 22:50 hours, Automatic Train Control Maintenance (ATCM) personnel arrived at Anacostia Station. At 23:05 hours, the ATCM personnel inspected and verified that Train ID 528 did pass switch 1B and did not pass switch 3B, and there was no damage to switch 1B. Train ID 528 was returned to the platform at Anacostia Station.

At 23:35 hours, the Radio RTC dispatched Train ID 528 (728) to Branch Avenue Station. At 23:54 hours, Train ID 528 (728) was stored at Branch Avenue Yard.

The Train Operator passed their certification exam in December 2023 on their second attempt. A review of the certification records, conducted as part of a WMSC Order, revealed that the Train Operator completed their certification with one discrepancy in the practical testing. The Operator was given two scenarios from Group B (troubleshooting) and did not receive a Group A (Circuit Breaker) scenario. This Train Operator is not included as part of the non-compliant certification group requiring recertification, according to the Office of Rail Transportation.

In adherence to Standard Operating Procedure 102-01-02, which outlines the protocol for Removing an Employee from Service for involvement in an operational safety event, the Radio RTC dispatched a Rail Supervisor to relieve the Train Operator from duty for post-incident testing.

---

Incident Date: 04/19/2024      Time: 22:05 hours  
Final Report – Red Signal Overrun  
E24312

Drafted By: SAFE 702 – 06/13/2024
Reviewed By: SAFE 707 - 06/13/2024
Approved By: SAFE 707 – 06/18/2024

Page 4


In accordance with the Office of the Chief Mechanical Officer (CMOR) Incident Investigation Team (IIT) Operations Administrative Policy (OAP) 102.06, the Metro Integrated Command and Communications Center (MICC) promptly initiated the removal of Train ID 528 from revenue service for post-incident investigative measures. This action adhered to the Rail Vehicle Event Investigation Policy, ensuring a comprehensive examination of the incident.

The probable cause of the Red Signal Overrun event on April 19, 2024, at Anacostia Station was the lack of situational awareness by the Train Operator, and the Train Operator's failure to follow the instructions given by the Radio RTC. A contributing factor was the Stop and Proceed method was still active, which allowed the train to move with speed commands displayed on the console; this inadequate safeguard is a contributing factor to this incident occurring.

### **Incident Site**

Anacostia Station, track 2 – Signal F06-08

### **Field Sketch/Schematics**



*The above depiction is not to scale.*

### **Purpose and Scope**

The purpose of this accident investigation and candid self-evaluation is to collect and analyze available facts, determine the probable cause(s) of the incident, identify contributing factors, and make recommendations to prevent a recurrence.

### **Investigative Methods**

The investigative methodologies included the following:

- Physical Site Assessment
- Formal Interviews – SAFE interviewed one individual as part of this investigation. The interview included persons present at, during, and after the incident, those directly involved in the response process, and representatives from the Washington Metrorail Safety Commission (WMSC). SAFE interviewed the following individual:
  - Train Operator (Train ID 528)
- Documentation Review – Collection of relevant work history information and process documentation contained in WMATA systems of record. These records include:

Incident Date: 04/19/2024      Time: 22:05 hours  
Final Report – Red Signal Overrun  
E24312

Drafted By: SAFE 702 – 06/13/2024  
Reviewed By: SAFE 707 - 06/13/2024  
Approved By: SAFE 707 – 06/18/2024

- Train Operator Training Records
  - Train Operator Certifications
  - Train Operator 30-Day work history review
  - Train Operator Written Statement
  - Metrorail Operating Rulebook (MOR)
  - National Oceanic and Atmospheric Administration (NOAA)
  - Metro Integrated Command and Control (MICC) Incident Report Maximo Data
- System Data Recording Review – Collection of information contained in Metro Data Recording Systems. This data includes:
    - Audio Recording System (ARS) playback [Radio and Landline Communications]
    - The Office of Chief Mechanical Officer (CMOR) Incident Investigation Team (IIT) Vehicle Monitoring and Diagnostic System (VMDS)
    - Closed-Circuit Television (CCTV)

## **Investigation**

On Friday, April 19, 2024, at 22:05 hours, Train ID 528 (L7678-7679x7511-7510x7386-7387x7519-7518T) located at Anacostia Station on track 2 passed signal F06-08 displaying a red aspect.

Prior to the event, and earlier in the day at 09:17 hours, the Radio RTC announced a down track circuit at Naylor Road Station on track 2 causing a red signal. The Radio RTC instructed the Train Operators to make announcements to the customers and advise of delays towards Branch Avenue Station. At 09:28 hours, a Rail Supervisor clamped switches 1B and 3B in normal position for train movement. At 09:29 hours, trains began passing red signals at Naylor Road Station on track 2, including the train operator involved in the red signal overrun incident until the system closed.

The System Performance On-Time Summary (SPOTS) revealed that at 21:29 hours, Train ID 528 departed Greenbelt Station on track 2 with the destination of Branch Avenue Station.

The Audio Recording System (ARS) revealed that at 22:03 hours, the Radio RTC granted Train ID 528 a permissive block to the 8-car marker at Anacostia Station on track 2, advised the Train Operator that signal F06-08 was red, and instructed the Train Operator to standby. The reason the Train Operator on Train ID 528 was given those instructions was because the Event Train ID 551, was instructed to clear the interlocking and reverse ends at Anacostia Station on track 2 and was holding at signal F06-06. This action prevented Train ID 528 in approach to the Anacostia Station platform on track 2 from receiving a lunar at signal F06-08. The Train Operator acknowledged, repeated the instruction, and then entered the Stop and Proceed<sup>1</sup> method to move the train. At 22:04 hours, Train ID 528 arrived at Anacostia Station. Train ID 528 serviced the Anacostia Station platform on track 2, departed the station, and passed signal F06-08 displaying a red aspect. During this time, Train ID 551 was departing Anacostia Station on track 1, traveling in the direction of Navy Yard Station

---

<sup>1</sup> *Stop and Proceed mode enables Train Operators to take a point of power in the absence of speed commands, with the ATP System enforcing a maximum speed of up to 15 MPH. If speed commands are lost on the mainline, and the consist comes to a stop with the ADU displaying the code number, the Operator must contact MICC to obtain either a Permissive or Absolute block before pressing the corresponding number on the ADU Touchpad to enter Stop and Proceed Mode.*

The Train Operator was able to move the train because the Stop and Proceed method was still active and speed commands were displayed on the console. However, the Train Operator did not verify that signal F06-08 was lunar.

At 10:05 hours, a visual alarm indicating a red signal overrun occurred at signal F06-06 was displayed on the AIMS.

At 22:06 hours, the Radio RTC attempted to contact the Train Operator via radio to ascertain the train location. The Train Operator advised the Radio RTC that they were at Anacostia Station. The Radio RTC inquired if the train had passed signal F06-08 red. The Train Operator confirmed passing signal F06-08 red.

The Button RTC notified the OM and Communications Section. Metro 1 notified MOC, and Bus 1 to establish a bus bridge. Communications notified the MTPD. The MAC contacted the SDOC and Safety On-Call personnel.

Train service was suspended between Navy Yard Station and Congress Heights Station.

At 22:13 hours, the Train Operator advised the Radio RTC that there were two to three cars that remained on the platform. The Radio RTC instructed the Train Operator to walk the customers through the train onto the platform and verify the train was clear of all passengers.

At 22:50 hours, ATCM personnel arrived at Anacostia Station. At 23:05 hours, the ATCM personnel inspected and verified that Train ID 528 did pass switch 1B and did not pass switch 3B, and there was no damage to switch 1B. Train ID 528 was returned to the platform at Anacostia Station.

At 23:35 hours, Radio RTC dispatched Train ID 528 (728) to Branch Avenue Station. At 23:54 hours, Train ID 528 (728) was stored at Branch Avenue Yard.

During the informal interview, the Train Operator stated that they received a permissive block to Anacostia Station and that they entered the stop-and-proceed method. The Train Operator stated that they forgot the instructions from the RTC to standby, were rushing, and did not notice that the signal was red.

The Train Operator is a WMATA employee with 9 months of service and 4 months of experience as a Train Operator. The Train Operator holds a Roadway Worker Protection (RWP) Level 2 certification that expires in December 2024.

The Train Operator's initial certification was conducted on December 5, 2023, when they failed the practical portion of the certification. On December 11, 2023, the Train Operator passed the Train Operator Certification on the second attempt. This Train Operator is not included as part of the non-compliant certification group requiring recertification per the Office of Rail Transportation.

### Chronological Event Timeline

A review of ARS playback, i.e., phone and radio communications, revealed the following timeline:

Time	Description
09:17:37 hours	Radio RTC: Announced a down track circuit at Naylor Road Station on track 2 causing a red signal. Instructed the Train Operators to make



Time	Description
	announcements to the customers and advise of delays towards Branch Avenue Station. [Radio Ops 3]
09:27:02 hours	<u>Rail Supervisor</u> : Advised switch 1B was clamped in a normal position. [Radio Ops 3]
09:28:52 hours	<u>Rail Supervisor</u> : Advised switch 3B was clamped in a normal position. [Radio Ops 3]
09:29:54 hours	<u>Radio RTC</u> : Instructed Train ID 516 to pass F09-08 red. [Radio Ops 3]
21:29:25 hours	Train ID 528 departed Greenbelt Station. [Spots]
22:03:43 hours	<u>Radio RTC</u> : Granted Train ID 528 a permissive block to Anacostia Station on track 1. Advised that signal F06-08 was red, and standby. <u>Train ID 528</u> : Acknowledged. [Radio Ops 3]
22:04:08 hours	Train ID 528 arrived at Anacostia Station. [Spots]
22:05:42 hours	Train ID 528 passed F06-08 red. [AIMS]
22:06:11 hours	<u>Radio RTC</u> : Attempted to contact Train ID 528. <u>Train ID 528</u> : Acknowledged. <u>Radio RTC</u> : Requested the train location. <u>Train ID 528</u> : Responded Anacostia. <u>Radio RTC</u> : Inquired if the train was on the platform. <u>Train ID 528</u> : Responded Affirmative. [Radio Ops 3]
22:06:54 hours	<u>Radio RTC</u> : Instructed Train ID 552 approaching Anacostia Station to stop the train. [Radio Ops 3]
22:07:12 hours	<u>Button RTC</u> : Notified to Operations Manager. [Phone Rail 1]
22:07:13 hours	<u>Metro 1</u> : Notified MOC. [Phone Rail 1]
22:07:25 hours	<u>Radio RTC</u> : Attempted to contact Train ID 528. <u>Train ID 528</u> : Acknowledged. <u>Radio RTC</u> : Inquired if the train passed signal F06-08 red. <u>Train ID 528</u> : Responded repeat. <u>Radio RTC</u> : Requested a radio check from Train ID 528. <u>Train ID 528</u> : Acknowledged. <u>Radio RTC</u> : Inquired if the train passed signal F06-08 red. <u>Train ID 528</u> : No Response. [Radio Ops 3]
22:08:39 hours	<u>Radio RTC</u> : Inquired if the train passed signal F06-08 red. <u>Train ID 528</u> : Responded Affirm. [Radio Ops 3]
22:09:22 hours	<u>Button RTC</u> : Notified the Communications Section. [Phone Yel/Grn]
22:09:37 hours	<u>Metro 1</u> : Requested a bus bridge between Naylor Road and Congress Heights Station. [Phone Rail 1]
22:09:42 hours	<u>Button RTC</u> : Notified the AOM. [Phone Yel/Grn]
22:10:33 hours	<u>MAC</u> : Notified SDOC. [Phone MAC]
22:11:56 hours	<u>MAC</u> : Dispatched SAFE On-Call personnel. [Phone MAC]
22:12:34 hours	<u>Communications</u> : Notified MTPD. [Phone SOCC]
22:12:49 hours	<u>Radio RTC</u> : Inquired if any cars were on the platform. <u>Train ID 528</u> : Responded two or three cars on the platform. <u>Radio RTC</u> : Instructed to key down and key the customers off the train. <u>Train ID 528</u> : Acknowledged. [Radio Ops 3]
22:18:25 hours	<u>MAC</u> : Contacted the WMSC. (ESR 22:19 hours) [Phone MAC]
22:20:35 hours	<u>Radio RTC</u> : Announced that train service was suspended between Navy Yard and Southern Avenue Stations. [Radio Ops 3]

Time	Description
22:40:00 hours	SAFE OSI arrived at Anacostia Station. [CCTV]
22:48:00 hours	Incident Command Established [Radio, Ops 3]
22:50:00 hours	ATC arrived at Anacostia Station [CCTV]
22:53:00 hours	<u>Field Assistant Superintendent:</u> Reported that they observed that Train ID 528 did pass switch 1B and did not pass switch 3B. [Radio, Ops 3]
23:05:00 hours	ATC inspected and verified there was no damage to switch 1B. [Radio, Ops 3]
23:06:00 hours	Train ID 528 was moved back to Anacostia platform track 2. [CCTV]
23:35:05 hours	Radio RTC: Dispatched Train ID 528 (728) to Branch Avenue Station. [Radio, Ops 3]
23:54:27 hours	Train ID 528 (728) arrived at Branch Ave Yard. [Radio, BA Yard 2]

Note: Times above may vary from other systems' timelines based on clock settings.

### Automated Information Management System (AIMS)




Image 1 – AIMS depicts the event Train ID 551 crossing over from track 2 to track 1 at signal F06-06 at 22:04 hours.




Image 2 – Depicts Train ID 551 on the platform at Anacostia Track 1 at 22:05 hours.

Incident Date: 04/19/2024      Time: 22:05 hours  
 Final Report – Red Signal Overrun  
 E24312

Drafted By: SAFE 702 – 06/13/2024  
 Reviewed By: SAFE 707 - 06/13/2024  
 Approved By: SAFE 707 – 06/18/2024




Image 3 – Depicts Train ID 528 passing signal F06-08 red at 22:06 hours.

### The Office of Chief Mechanical Officer (CMOR) / Vehicle Monitoring and Diagnostic System (VMDS)

Adopted from CMOR IIT report with minor formatting and grammatical edits:

Based on the video and data, Train ID 528, entered Anacostia Station, track #2, in the direction of Congress Heights Station (F07). Lead car 7678 ER data confirmed prior to overrun that signal F06-08 was red. Train ID 528 lost speed commands and came to a complete stop 385 feet within the platform limits at this time, Stop and Proceed Mode was initiated. The train properly berthed at the 8-car marker and serviced the station.

The train departed Anacostia Station while in the Stop and Proceed Mode. Once the train’s speed reached 15.6 MPH, 92 feet before signal F06-08 stop and proceed mode was terminated.


The train passes signal F06-08 red at a speed of 12.9 MPH with the Master Controller in “B5” position, coming to a complete stop 48 feet beyond the signal F06-08. The emergency brake was not initiated. There were no faults with the train that contributed to the cause of this incident, the train performed as designed.

See below timeline of events:

Time	Description of Events	Master Controller	Train Speed	Regulated Speed	Limiting Speed	Distance to Signal F06-08
22:03:45:200	Train ID 528, entered Anacostia station (F06), track #2 at a speed of 12.1 MPH, with the Master Controller in the “Coast” position, Limiting and Regulated speed limits set to 22 MPH respectfully.	Coast	12.1 MPH	22 MPH	22 MPH	762 feet.
22:03:46:300	The speed limit decreased to 15 MPH while train’s speed remained at 12.1 MPH.	Coast	12.1 MPH	22 MPH	15 MPH	743 feet.

Time	Description of Events	Master Controller	Train Speed	Regulated Speed	Limiting Speed	Distance to Signal F06-08
22:03:47:320	The Regulated speed decreased to 15 MPH while train's speed was 11.4 MPH.	<i>Coast</i>	<i>11.4 MPH</i>	<i>15 MPH</i>	<i>15 MPH</i>	<i>726 feet.</i>
22:03:58:290	The speed limit dropped to 0 MPH while train's speed was 7.8 MPH. Overspeed Alarm activated.	<i>P5</i>	<i>7.8 MPH</i>	<i>15 MPH</i>	<i>0 MPH</i>	<i>575 feet.</i>
22:03:59:590	Train lost speeds commands. The Regulated speed dropped to 0 MPH while train's speed was 7.5 MPH.	<i>P1-P4</i>	<i>7.5 MPH</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>562 feet.</i>
22:04:02:900	Overspeed Alarm silence with the Master Controller moved to "B5" position.	<i>B5</i>	<i>0.1 MPH</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>547 feet.</i>
22:04:03:240	Train came to a complete stop. Master Controller in "B5".	<i>B5</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>547 feet.</i>
22:04:06:800	<b>Stop and Proceed Mode was initiated</b>	<i>B5</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>1 MPH</i>	<i>547 feet.</i>
22:04:08:390	The Master Controller was placed in "P5" Power mode and the train started to move toward Anacostia's platform limit.	<i>P5</i>	<i>&lt;1 MPH</i>	<i>0 MPH</i>	<i>1 MPH</i>	<i>547 feet.</i>
22:04:17:690	The train reached the center of the Anacostia platform.	<i>P1-P4</i>	<i>9.7 MPH</i>	<i>0 MPH</i>	<i>1 MPH</i>	<i>462 feet.</i>
22:04:45:490	<b>The train came to a complete stop, 1 foot short to the Anacostia's 8-car marker.</b>	<i>B5</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>1 MPH</i>	<i>163 feet.</i>
22:04:54:200	Left doors were opened and station was serviced.	<i>B5</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>1 MPH</i>	<i>163 feet.</i>
22:05:10:780	Left doors were closed and locked.	<i>B5</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>1 MPH</i>	<i>163 feet.</i>
22:05:14:310	The Master Controller was placed in "P5" Power mode and the train started to move toward F06-08 signal.	<i>P5</i>	<i>&lt;1 MPH</i>	<i>0 MPH</i>	<i>1 MPH</i>	<i>163 feet.</i>
22:05:21:580	Stop and Proceed mode deactivated with the train's speed over 15 MPH.	<i>B5</i>	<i>15.6 MPH</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>92 feet.</i>
22:05:25:590	<b>The train reached the F06-08 signal. Master Controller in "B5".</b>	<i>B5</i>	<i>12.9 MPH</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>0 feet.</i>
22:05:31:980	<b>The Train came to a complete stop after F06-08 signal. Overran by 48 feet. Master Controller in "B5".</b>	<i>B5</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>0 MPH</i>	<i>-48 feet.</i>

Note: Times above may vary from other systems' timelines based on clock settings.



**Office of Systems Maintenance, Office of Radio Communications (COMR)**

The Office of System Maintenance, Office of Radio Communication (CMOR) conducted a comprehensive radio check on both tracks at Anacostia Station. All radio checks were loud and clear.

**Office of Rail Transportation (RTRA)**  
*Adopted from RTRA report:*

RTRA determined the Train Operator would receive discipline in accordance with the Disciplinary Administrative Program (DAP), and complete Re-Instruction Training with Rail Quality Control Training (ROQT).

**Interview Findings**

*As part of the investigation launched into the event, SAFE interviewed one person. The interview identified the following key findings associated with this event. The findings detailed below include reported information from involved personnel and may conflict with other data sources contained in the report.*

**Train Operator Written Statement**

“Overran red signal track 2 Anacostia. Upon entering Anacostia there was a red signal for the train ahead to clear the interlocking. Central gave me permission to properly berth to the 8-car marker using stop and proceed. I serviced the station, closed the doors, then continued on. After realizing the signal was still red, I stopped but had already cleared the signal. I used stop and



proceed to properly berth. My train was stopped in the middle of the platform. After servicing, I was already still in stop and proceed. I didn't have to press it again. 5-10 MPH through red signal."

## **Weather**

On April 19, 2024, at the time of the incident, NOAA recorded the temperature as 53°F, with clear skies, winds 6mph, and 60% humidity. Weather was not a contributing factor in this incident (Weather source: NOAA) – Washington, DC

## **Related Rules and Procedures**

### **Metrorail Operating Rulebook (MOR)**

12.4.3 Personnel shall not take any action until they are positive that all radio transmissions or receptions are heard, fully understood, and acknowledged. Individual radio transmissions shall always be repeated by the receiver so the transmitter can confirm that the message was received completely and by the intended receiver.

12.4.4 Whenever the transmitter has completed their transmission and is turning the airtime over to the receiving party for acknowledgment or reply, they are to end their communication with the word "over."

12.4.5 Positive Identification must be established prior to transmitting a message. Positive identification includes the transmitter stating their Train/Equipment Number or Unit ID Number, location, and track number at the beginning of a transmission and the receiver repeating back the Train/Equipment Number or Unit ID Number, location, and track number when acknowledging the radio call.

12.4.6 Rail Traffic Controllers shall acknowledge employees by repeating the train number, location, and track.

12.4.7 When communicating with Rail Vehicles, personnel are to identify the train ID or unit ID by the complete number series. This method of positive train/unit identification shall be consistently used when transmitting and acknowledging information.

12.4.8 When an employee is communicating with Rail Operations Control, Central will close out a communication loop by saying, "Central, out."

## **Human Factors**

### Fatigue

#### *Signs and Symptoms of Fatigue*

We evaluated signs and symptoms of fatigue that may have been present at the time of the incident. No signs or symptoms of fatigue were detected from the available data. Video of the incident was reviewed for signs of the Train Operator's fatigue. No signs or symptoms of fatigue were evident from the video. The Train Operator reported feeling fully alert and slightly sluggish at the time of the incident.

#### *Fatigue Risk*

SAFE evaluated incident data for fatigue risk factors. Risk factors for fatigue were present. The incident time of day did not suggest an increased risk of fatigue-related impairment. The Train

Operator reported no variation in the sleep schedule in the days leading up to the incident. The Train Operator performed night work in the days leading up to the incident. The Train Operator was awake for ten hours and fifty minutes at the time of the incident. The Train Operator reported six hours of sleep in the 24 hours preceding the incident. The off-duty period was sixteen hours and eleven minutes, which provided an opportunity for 7-9 hours of sleep. This was less than the employee's usual workday sleep durations. The Train Operator reported no issues with sleep.

Post-Incident Toxicology Testing

WMATA's Drug and Alcohol Program determined that the Train Operator complied with the Drug and Alcohol Policy and Testing Program 7.7.3/6.

**Findings**

- The RTC advised the Train Operator that signal F06-08 was red.
- The Train Operator reported entering the stop and proceed method prior to stopping at the 8-car marker.
- The Train Operator failed to verify a lunar signal at F06-08 after servicing Anacostia Station.

**Immediate Mitigation to Prevent Recurrence**

- Service was suspended between Navy Yard Station and Congress Heights Station.
- ATCM assessed the interlocking switches.
- The Train Operator was removed from service.

**Probable Cause Statement**

The probable cause of the Red Signal Overrun event on April 19, 2024, at Anacostia Station was the lack of situational awareness by the Train Operator, and the Train Operator's failure to follow the instructions given by the Radio RTC. A contributing factor was the Stop and Proceed method was still active, which allowed the train to move with speed commands displayed on the console; this inadequate safeguard is a contributing factor to this incident occurring.

**Recommended Corrective Actions**

Corrective Action Code	Description	Responsible Party	Estimated Completion Date
116295MX_SAFE CAPS_RTRA_001	The Train Operator to complete Re-Instruction Training with ROQT.	RTRA_SRC	Completed

## Appendices

### **Appendix A – Interview Summary**

*The below narratives summarize the incident and represent the statements made by the involved individual. As such, times and details may present a conflict with the data contained in systems of record.*

#### *Train Operator*

The Train Operator is a WMATA employee with 9 months of service and experience as a Train Operator. The Train Operator holds a Roadway Worker Protection (RWP) Level 2 certification that expires in August 2024.

During the formal interview, the Train Operator stated that trains were single tracking the whole day on track 2 but not until Naylor Road, due to a down signal. Trains were going over clamped switches. The Train Operator stated everything was fine towards the end of the evening.

The Train Operator stated an event train had to clear the interlocking before their train arrived at the platform. The Train Operator stated that in approach Anacostia Station on track 2 their train lost speed commands in the middle of the platform. The MICC gave them a Permissive Block to the 8-car marker.

The Train Operator stated after arriving to Anacostia Station on track 2, they serviced the station and waited for a lock out, since the switch had the correct rail alignment, they just didn't have a lunar signal.

The Train Operator stated they serviced the station and continued on. After continuing through the signal, the overspeed alarm went off, making them realize the train was still in Stop and Proceed from when they were given the Permissive Block, and then the train came to a complete stop.

The Train Operator stated the MICC contacted them immediately after the incident happened. The RTC instructed them to stand by. The Train Operator stated once the train stopped, they realized they had three cars still on the platform.

The Train Operator stated the RTC sent a Station Manager to assist with offloading the customers from the three cars that were still on the platform. They keyed the train down, walked back and began keying the remaining customers off the train.



## Appendix B – Scene Photographs



Figure 1 – Incident train partially on platform



Figure 2 – Incident train 2 cars in the tunnel



Figure 3 – View of Train ID 528 after the train was repositioned.




Figure 4 – F06-08 signal red



Apr 19, 2024 at 11:09:05 PM  
Washington DC  
United States



*Figure 5- Switch 1B in normal position. (no damage)*

Apr 19, 2024 at 11:18:26 PM  
Washington DC  
United States




Figure 6 – Train ID 528 secured on track 2, Anacostia.







CATEGORIES / SUBCATEGORIES	QUALITY LEVEL	REMARKS (Remarks are required for a quality level score of 2 or 3)
<b>I. Preparation for Service</b>		
	QL-1	Cars Used: 7680-7681X7711-7710
1. Exterior Inspection	1	Loose Barrier #7710 Door Open #7681 TLBCO #7680
2. Interior Inspection - Trailing Cab	1	ATP seal missing #7680
3. Interior Inspection - Each Car	1	Valance Open #7681 Horn c/o #7711
4. Interior Inspection - Oper. Cab	1	
5. Rolling Test / Rolling Brake Test	1	AX Trk #20
		Time Allotted: 35:00 / Actual Time: 24:03 min.
<b>II. Mainline Operation</b>		
6. Communications		
7. Door Oper. & Station Stopping		
8. Use of Horn		
9. Speed Adherence/Manual Oper.		
10. Turn Back Moves		Location: _____ Time Allotted: 02:00 / Actual Time: _____
11. Manual Route Selection		Location: _____
12. EV Shutoff		Time Allotted: 00:30 (1:00) / Actual Time: _____
<b>III. Yard Operation</b>		
13. Communications		
14. Yard Movements		
15. Coupling B to B		Time Allotted: 08:00 (12) / Actual Time: _____ Cars Used: +
16. Uncoupling		Time Allotted: 05:00 (7.5) / Actual Time: _____ Cars Used: < >
17. Isolation (Self-Recovery)		Time Allotted: 15:00 (22.5) / Actual Time: _____ Cars Used: _____
18. Manual Switch Operation		
<b>IV. Miscellaneous</b>		
19. Recovery Train Operation		Time Allotted: 12:00 (18) / Actual Time: _____ Cars Used: +
20. Troubleshooting	Problem 1	
	Problem 2	

Image 6 – Train Operators Certification Evaluation

# Appendix X – Why-Tree Analysis

