

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	20240531-WMSC-LBW-1
	2024/05/31		
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department Contact Information	Name
Rail Agency Department	SAFE		
Inspection Location	Alexanderia Rail Yard		

Inspection Summary

Inspection Activity #	1		
Activity Code	OBS-RTRA-PI		
Inspection Units	2		
Inspection Subunits	0		
Defects (Number)	1		
Recommended Finding	No		
Remedial Action Required ¹	No		
Recommended Reinspection	No		

Activity Summaries

Inspection Activity # 1 Inspection Subject Corrective Action Compliance Inspect	ction Activity Code OBS-RTRA-PI
Fmployee Supervisor - S&I Facility Accompanied Inspector? No.	t Brief ducted Yes Time 07:00 AM Outside Shift No
Related Reports NA Related CAPS / Findings TOC-0	C-OTR-15-006 TOC-COL-15-003-A
Ref Rule or SOP Standard	Other / Title Checklist Reference
Related Rules, SOPs, Standards, or Other Task Order (FQ 17044-19- 031) for the installation of the car wash warning systems at the (6) identified locations	NA NA
	ck Type At-grade Tunnel Elevated N/A
X	
Line(s) & Track Number Alexanderia Rail Yard Alexanderia Rail Yard NA	From To NA
Head Car Number Number of Cars	NA .
Vehicles NA NA Equipment NA	
The WMSC Inspectors conducted a follow up inspection for corrective action TOC-C	
006 (WMATA must install a Train Movement Indication system in all car wash faci This corrective action was closed by the WMSC after Metrorail confirmed funding	
availability and provided the Task Order (FQ 17044-19-031) for the installation of t	
wash warning systems at the (6) identified locations (West Falls Church, Alexand Greenbelt, Branch Ave New Carrollton, and Glenmont Yard Rail Facilities). The inspection team observed a rail vehicle approaching, entering, activating, and exithe car wash facility. As the rail vehicle approached the wash facility, the warning sounded, and the warning lights illuminated. As the vehicle passed through the facility, lights above entry doors were observed flashing and a recorded message heard throughout the maintenance facility warning worker that a vehicle was pass through the car wash. The WMSC inspection team also performed a visual inspect the guardrails in the car wash as a follow-up inspection for closed corrective action colored. The constructive action required Metrorail to "Design and install a ne railing system that reduced the number of openings and eliminates the ability of handrails to swing into the direction of the dynamic envelope of ta rail car, in she locations and rail facilities to replace the sectional type of railing system current installed". This corrective action was closed after review of the mitigations and d drawing for the proposed slide gate. The inspection team did observe the newly designed railing installed, but all gates were not closed and secured as required inspection team closed the fall gates that were accessible and notified Alexande Management of the remaining gates that were open. The WMSC conducted a final debrief with Metrorail personnel at the conclusion of the inspection.	exiting ng alarm e wash ge was assing ection of tion TOC- new of the hop ntly design y ed. The deria
Remedial Action	



Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission

Photos: 20240531_084611.heic



20240531_084614.heic



Inspector in Charge's Signature

Date
2024/05/31

Inspector in Charge's Name
LeBon Bruce Walker

Inspection Team
Darrell Braxton Manual Lopez

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.