

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY/MM/DD	Donart Number	20240531-WMSC-DLB				
Inspection Date	2024/05/31	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	SAFE	Contact Information					
Inspection Location	Alexandria Rail Yard 3201 Eisenhower Ave, Alexandria, VA 22314						

Inspection Summary

Inspection Activity #	1
Activity Code	OBS-RTRA-PI-WI
Inspection Units	3
Inspection Subunits	0
Defects (Number)	1
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	Yes


Activity Summaries

Supervisor - S&l Facility Accompanied Inspector? No Out Brief Conducted Yes Time O7:00 AM Outside Shift No	Inspection Activity #	1	Ins	pection Subj	Corrective Action Compliance Inspection					Activity	OBS-RTRA-PI-WI						
Related Rules, SO'Rs, Standards, or Other (FQ 1704-19- Rule or SOP Standard Other / Title Checklist Reference Task Order (FQ 1704-19- Rule or SOP Standard Other / Title Checklist Reference Task Order (FQ 1704-19- Osh Park Osh Osh Osh Osh Osh Osh Task Order (FQ 1704-19- Osh Osh Osh Osh Osh Osh Osh Osh Osh Task Order (FQ 1704-19- Osh	Employee	Supervisor - S&I Facility			Accompanied Inspector?			No		Yes Time		07:00 AM			No		
Task Order (FQ 17044-19-031) for the installation of the car wash warning systems at the (6) identified locations N/A. N/A. N/A. N/A.	Related Reports	N/A.			Related CA	APS / Findin	ngs		TOC-OTR-15-00	06 TOC-COL-15-003-A							
Other		Ref		Rule	or SOP			Standard		Other / Title Checklis					ist Refer	st Reference	
Inspection Location Track Yard Station OCC RTA Facility Office Track Type At-grade Tunnel Elevated N/A	SOPs, Standards, or	031) for the installation of the car wash warning N/A systems at the (6)			A.			B/A.		N/A.			ı	N/A.			
Line(s) & Track Number Alexandria Rail Yard 3201 Eisenhower Ave, Alexandria, VA 22314 Vehicles Head Car Number Number of Cars N/A. N/A.	Inspection Location	-	Yard	Station	осс		<u>'</u>	1			At-grade Tunne		el	Elevate		N/A	
Number Ave, Alexandria, VA 22314 Station(s) N/A. N/A. N/A. Head Car Number Number of Cars N/A. N/A. N/A. N/A.						>	X										
No. New Part Number of Cars New Part New Part	• •	The state of the s				or	N/A						-				
N/A. N/A. N/A. Equipment N/A.		•			umber of (<u>, </u>		N/A.				N/A.				
BACKGROUND: The following two corrective action plan were required and implemented by Metrorail: 1. TO-OTR-15-006 - Per the record of the Corrective Action Plan (CAP) from Metrorail; "(WMATA must install a Train Movement Indication system in all car wash facilities). "The corrective action was closed by the WMSC after evidence of its completion was provided via Task Order -FQ 17044-19-031 which required the installation of the car wash visual and audible warning system. The system was installed at West Falls Church, Alexandria, Greenbelt, Branch Ave, New Carrollton and Glenmont Rail Yards. 2. TOC-COL- 15-003-A - As quoted from the Metrorail closed corrective action Metrorail was required to "Design and install a new railing system that reduced the number of openings and eliminates the ability of the handrails to swing into the direction of the dynamic envelope of a rail car, in shop locations and rail facilities to replace the type of railing system currently installed." METHOD: The WMSC Inspectors used visual and walking inspections to verify the implementation and effectiveness of the above-mentioned corrective action plans. OBSERVATIONS/FINDINGS:The WMSC observed a train that entered, activated and exited the car wash facility. The visual and audible alarm system functioned as it was designed to. For example, lights were observed flashing inside and outside of the facility. Additionally, a recorded voice warning which served to warn personnel all through the maintenance facility that a train was passing through the car wash. The WMSC Inspectors observed the newly installed and implemented guardrails with sliding gates. A few of the sliding gates were not closed. Therefore, upon observing this the WMSC Inspectors closed	Vehicles						Equipm	ent	N/A.								
Metrorail," (WMATA must install a Train Movement Indication system in all car wash facilities). "The corrective action was closed by the WMSC after evidence of its completion was provided via Task Order -FQ 17044-19-031 which required the installation of the car wash visual and audible warning system. The system was installed at West Falls Church, Alexandria, Greenbelt, Branch Ave, New Carrollton and Glemmont Rail Yards. 2. TOC-COL-15-003-A - As quoted from the Metrorail closed corrective action Metrorail was required to "Design and install a new railing system that reduced the number of openings and eliminates the ability of the handrails to swing into the direction of the dynamic envelope of a rail car, in shop locations and rail facilities to replace the type of railing system currently installed." METHOD: The WMSC Inspectors used visual and walking inspections to verify the implementation and effectiveness of the above-mentioned corrective action plans. OBSERVATIONS/FINDINGS:The WMSC observed a train that entered, activated and exited the car wash facility. The visual and audible alarm system functioned as it was designed to. For example, lights were observed flashing inside and outside of the facility. Additionally, a recorded voice warning which served to warn personnel all through the maintenance facility that a train was passing through the car wash. The WMSC Inspectors observed the newly installed and implemented guardrails with sliding gates. A few of the sliding gates were not closed. Therefore, upon observing this the WMSC Inspectors closed				-				•		Number o	of Defects			1			
facilities). "The corrective action was closed by the WMSC after evidence of its completion was provided via Task Order -FQ 17044-19-031 which required the installation of the car wash visual and audible warning system. The system was installed at West Falls Church, Alexandria, Greenbelt, Branch Ave, New Carrollton and Glenmont Rail Yards. 2. TOC-COL-15-003-A - As quoted from the Metrorail closed corrective action Metrorail was required to "Design and install a new railing system that reduced the number of openings and eliminates the ability of the handrails to swing into the direction of the dynamic envelope of a rail car, in shop locations and rail facilities to replace the type of railing system currently installed." METHOD: The WMSC Inspectors used visual and walking inspections to verify the implementation and effectiveness of the above-mentioned corrective action plans. OBSERVATIONS/FINDINGS:The WMSC observed a train that entered, activated and exited the car wash facility. The visual and audible alarm system functioned as it was designed to. For example, lights were observed flashing inside and outside of the facility. Additionally, a recorded voice warning which served to warn personnel all through the maintenance facility that a train was passing through the car wash. The WMSC Inspectors observed the newly installed and implemented guardrails with sliding gates. A few of the sliding gates were not closed. Therefore, upon observing this the WMSC Inspectors closed			` ,									Recommended Finding?					
wash visual and audible warning system. The system was installed at West Falls Church, Alexandria, Greenbelt, Branch Ave, New Carrollton and Glenmont Rail Yards. 2. TOC-COL- 15-003-A - As quoted from the Metrorail closed corrective action Metrorail was required to "Design and install a new railing system that reduced the number of openings and eliminates the ability of the handrails to swing into the direction of the dynamic envelope of a rail car, in shop locations and rail facilities to replace the type of railing system currently installed." METHOD: The WMSC Inspectors used visual and walking inspections to verify the implementation and effectiveness of the above-mentioned corrective action plans. OBSERVATIONS/FINDINGS:The WMSC observed a train that entered, activated and exited the car wash facility. The visual and audible alarm system functioned as it was designed to. For example, lights were observed flashing inside and outside of the facility. Additionally, a recorded voice warning which served to warn personnel all through the maintenance facility that a train was passing through the car wash. The WMSC Inspectors observed the newly installed and implemented guardrails with sliding gates. A few of the sliding gates were not closed. Therefore, upon observing this the WMSC Inspectors closed		, ,	•		,				Remedial Action Required?				No				
Remedial Action		wash visual Alexandria, 15-003-A - A "Design and eliminates t of a rail car, currently ins to verify the plans. OBSE exited the cadesigned to. Additionally distinguished by the cadesigned to additionally sliding gates	and audibl Greenbelt, s quoted fr install a ni he ability c in shop lo stalled." M e implemer RVATIONS, ar wash fac . For exam, , a recorde e facility the e newly ins	and audible warning system. The system was installed at West Falls Church, reenbelt, Branch Ave, New Carrollton and Glenmont Rail Yards. 2. TOC-COL-quoted from the Metrorail closed corrective action Metrorail was required to install a new railing system that reduced the number of openings and eability of the handrails to swing into the direction of the dynamic envelope in shop locations and rail facilities to replace the type of railing system shalled." METHOD: The WMSC Inspectors used visual and walking inspections implementation and effectiveness of the above-mentioned corrective action VATIONS/FINDINGS:The WMSC observed a train that entered, activated and wash facility. The visual and audible alarm system functioned as it was for example, lights were observed flashing inside and outside of the facility. The visual which served to warn personnel all through the facility that a train was passing through the car wash. The WMSC Inspectors newly installed and implemented guardrails with sliding gates. A few of the were not closed. Therefore, upon observing this the WMSC Inspectors closed					Ye	s							




Washington Metrorail Safety Commission

Photos:





Train_Inside_Car_Wash_Alex_Yard_053124.jpg






Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission

Opening_along_the_Catwalk_inside_the_Car_Wash_Alex_Yard_053124.jpg



1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2024/05/31
	Inspection Team Bruce Walker Manny Lopez	