

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Daniel Number	20240520 WMAS AAA 4				
Inspection Date	2024/07/01	Report Number	20240628-WMSC-MAL-1				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	CMNT	Contact Information					
Inspection Location	Greenbelt MRO Shop - Railyard E99 5801 Sunnyside Ave, College Park, MD 20740						

Inspection Summary

Inspection Activity #	1
Activity Code	VM-WI-PI
Inspection Units	1
Inspection Subunits	1
Defects (Number)	1
Recommended Finding	Yes
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	Inspection Subject			On-site Observation				Activity Code			VM-WI-PI			
Job Briefing Employee Name/Title	WMATA Inspection			Accompanied Inspector?			No	Out Brief Conducted	Yes	Yes Time			M	utside Shift	No
Related Reports	N/A			Related CA	APS / Findin	gs		N/A							
	Ref		Rule	e or SOP Standard				Other / Title				Checklist Reference			
Related Rules, SOPs, Standards, or Other	METRORAIL OPERATING RULEBOOK FIRST EDITION Effective: Sept 1, 2023, Safety Rules			A			N/A		N/A			N	N/A		
Inspection Location	Main Track	Yard X	Station	occ	RTA F	acility	WMSC Office	Track Type	At-grade Tunne		Tunne	el I	Elevated N/A		•
Line(s) & Track Number	Greenbelt MRO	O Shop - Ra			Chain Ma		or	N/A	From	From			То		
rumber	•	Sunnyside Ave, College Park, MD 20740 Station(s) N/A Head Car Number Number of Cars						N/A	N/A						
Vehicles	N/A	unibei	IV	N/A	Ja13	Equipment N/A									
	WMSC Inspect	Number of Defects													
	with the Metro Preventive Ma		Recommended Finding?					Yes							
	inspector met	Remedial Action Required?					No								
Description	and CENV engineering. The following observations were noted Discussed the status of the investigation into the increase of 7K traction motors electrical shorts CENV completed an investigation on the cause of 7K traction motors electrical shorts and results of the investigation will be discussed with Toshiba. Results of the investigation point to an improper baking process used to insulate the wire windings on the traction motor stators as the cause for the electrical shorts CENV will be sending a few failed traction motor stators to Toshiba's facilities in Texas, where they are going to cut the traction motor stators in half to examine the insulation on the wire windings Discussed the results of investigation report on the 7K wheels out of round issue WMATA stated that they have been running 75 mph tests on the RED line Defect #1 - WMATA stated that they were planning to conduct a railcar engineering test using a different friction modifier on the wheel tread. This effort is based on a recommendation provided in Dr Z's report. WMSC stated that a friction modifier cannot be used on the wheel tread since it will insulate the wheels from making electrical contact with the running rail and can cause a loss of shunt and a loss of ATP protection. The friction modifier on the wheel tread can also affect the railcar slip-slide braking system and the railcar electrical grounding system. Notified CENV engineering of the issue WMATA is investigating the effective use of metal shims during the installation of chevrons, and the effect it has on the truck leveling mechanism.							Recommended Reinspection?					No		

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

action. Closeout of nemedial Actions may also be subject to ongoing windse verification inspections to ensure corrections are sufficient and effective.							
Inspector in Charge's Signature	Date 2024/07/01						
Inspector in Charge's Name Manuel Lopez	Inspection Team N/A						