

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY/MM/DD	Donart Number	20241031-WMSC-MAL-2				
Inspection Date	2024/11/03	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	CMNT	Contact Information					
Inspection Location	Greenbelt CTEM Shop - Railyard E99 5801 Sunnyside Ave, College Park, MD 20740						

Inspection Summary

Inspection Activity #	1
Activity Code	VM-WI-PI
Inspection Units	1
Inspection Subunits	1
Defects (Number)	0
Recommended Finding	Yes
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Related Reports N/A Related CAPS / Findings N/A Related Reports N/A Related Rules, SOPs, Standards, or Other / Title REFRORAL OPERATING RULEBOOK FIRST EDITION Effective: Sept 1, 2023, Safety Rules Main Yard Station OCC RTA Facility Office Track Type Greenbelt CTEM Shop. Railyard E99 5801 Sunnyside Ave, College Park, MD 20740 Whiches Head Car Number N/A N/A N/A N/A N/A N/A N/A Related CAPS / Findings N/A N/A N/A N/A N/A N/A N/A N/A N/	#	1	Inspe	ection Sub	ject	On-site Observation				Activity (VM-WI-PI					
Related Rules, SOPs, Standards, or Other / Title Checklist Reference Related Rules, SOPs, Standards, or Other / Title Checklist Reference RuleBOOK FIRST EDITION Effective: Sept 1, 2023, Safety Rules N/A	Employee W	VMATA Inspec	TA Inspection Acco			Accompanied Inspector?				Yes Time			09:30 AM			No
Related Rules, SOPs, Standards, or Other SOPs, Standards, or Other SOPs, Standards, or Other Sorting Sopies, Sopies, Standards, or Other Sorting Sopies, S	Related Reports N	N/A			Related CA	NPS / Findin	gs		N/A				•			
SOPs, Standards, or Other Standards, or Other Commended Com	R	Ref		Rule	or SOP			Standard		Other /	Γitle		(Checkli	ist Refer	ence
Inspection Location Track	SOPs, Standards, or Other	RULEBOOK FIRST EDITION Effective: Sept 1, 2023,				N/A				N/A			1	N/A		
Number Sunnyside Ave, College Park, MD 20740 Station(s) N/A N/A N/A Pequipment N/A	Inspection Location			Station	OCC RTA Facility				Track Type	At-grade Tunna			el	Elevated		N/A
Number Sunnyside Ave, College Park, MD 20740 Station(s) N/A N/	Line(s) & Track G	Greenhelt CTFN	/ Shon - F	Railvard F	99 5801	Chain Ma	rker and/o	nr.		From					o	
N/A WMSC Inspector conducted a rules compliance of the Greenbelt CTEM Shop in compliance with the Metrorail Operating Rules and Procedures Handbook (MOR), including Preventive Maintenance Inspections (PI) activities. General Information: WMSC met with personnel from the CTEM Shop. The following observations were noted. - Positive practices - CTEM is implementing a safety initiative to install seat belts in all RMMs due to a recent event where an employee fell from an RMM due to not having a seat belt installed. CTEM conducted an inspection of all RMMs and is in the process of designing and installing seat belts in all RMMs. Currently there are only two RMMs remaining that need seat belts Positive practices - CTEM personnel stated that Facilities Maintenance is in the process of replacing railroad ties on the front apron of the New Carrollton shop, which were creating a trip hazard for mechanics, which must work on RMMs on the apron due to the lack of space inside the CTEM shop. Asphalt is being used to replace the railroad ties. This is a sample of positive practices being implemented CTEM personnel stated that a procurement card issue was preventing the procurement of spare parts for CTEM RMMs, which were causing an excessive number of RMMs being out of service due to the inability to buy spare parts. RMMs are needed to repair and maintain track and wayside equipment on a continuous basis. This issue was brought up during the Railcars Bi-weekly Meeting as a deficiency. The spare parts, which are needed to repair, maintain, and get RMMs including Prime Movers back in service Positive practices - CTEM personnel stated that they have a poor lighting issue in the open pit at the CTEM Shop in Branch Avenue. CTEM is working with Facilities Maintenance to replace the existing lighting with LED fixtures Positive practices - CTEM								,					-			
WMSC Inspector conducted a rules compliance of the Greenbelt CTEM Shop in compliance with the Metrorail Operating Rules and Procedures Handbook (MOR), including Preventive Maintenance Inspections (PI) activities. General Information: WMSC met with personnel from the CTEM Shop. The following observations were noted. - Positive practices - CTEM is implementing a safety initiative to install seat belts in all RMMs due to a recent event where an employee fell from an RMM due to not having a seat belt installed. CTEM conducted an inspection of all RMMs and is in the process of designing and installing seat belts in all RMMs. Currently there are only two RMMs remaining that need seat belts Positive practices - CTEM personnel stated that Facilities Maintenance is in the process of replacing railroad ties on the front apron of the New Carrollton shop, which were creating a trip hazard for mechanics, which must work on RMMs on the apron due to the lack of space inside the CTEM shop. Asphalt is being used to replace the railroad ties. This is a sample of positive practices being implemented CTEM personnel stated that a procurement card issue was preventing the procurement of spare parts for CTEM RMMs, which were causing an excessive number of RMMs being out of service due to the inability to buy spare parts. RMMs are needed to repair and maintain track and wayside equipment on a continuous basis. This issue was brought up during the Railcars Bi-weekly Meeting as a deficiency. The spare parts, which are needed to repair, maintain, and get RMMS including Prime Movers back in service Positive practices - CTEM personnel stated that they have a poor lighting issue in the open pit at the CTEM Shop in Branch Avenue. CTEM is working with Ecol Fixtures Positive practices - CTEM		Head Car Nu	ımber	N	lumber of C	ars										
compliance with the Metrorail Operating Rules and Procedures Handbook (MOR), including Preventive Maintenance Inspections (PI) activities. General Information: WMSC met with personnel from the CTEM Shop. The following observations were noted. - Positive practices - CTEM is implementing a safety initiative to install seat belts in all RMMs due to a recent event where an employee fell from an RMM due to not having a seat belt installed. CTEM conducted an inspection of all RMMs and is in the process of designing and installing seat belts in all RMMs. Currently there are only two RMMs remaining that need seat belts Positive practices - CTEM personnel stated that Facilities Maintenance is in the process of replacing railroad ties. This is a sample of positive practices being implemented CTEM personnel stated that a procurement card issue was preventing the procurement of spare parts for CTEM RMMs, which were causing an excessive number of RMMs being out of service due to the inability to buy spare parts. RMMs are needed to repair and maintain track and wayside equipment on a continuous basis. This issue was brought up during the Railcars Bi-weekly Meeting as a deficiency. The spare parts purchasing issue has been corrected and CMNT is now able to order the spare parts, which are needed to repair, maintain, and get RMMS including Prime Movers back in service Positive practices - CTEM personnel stated that they have a poor lighting issue in the open pit at the CTEM Shop in Branch Avenue. CTEM is working with Facilities Maintenance to replace the existing lighting with LED fixtures Positive practices - CTEM	Vehicles					Equipment N/A			N/A							
personnel stated that they are working on an initiative to improve the current personal protective equipment (PPE) to prevent debris from going into mechanics eyes.	Description ir the control of the co	including Preventive Maintenance Inspections (PI) activities. General Information: WMSC met with personnel from the CTEM Shop. The following observations were noted. - Positive practices - CTEM is implementing a safety initiative to install seat belts in all RMMs due to a recent event where an employee fell from an RMM due to not having a seat belt installed. CTEM conducted an inspection of all RMMs and is in the process of designing and installing seat belts in all RMMs. Currently there are only two RMMs remaining that need seat belts Positive practices - CTEM personnel stated that Facilities Maintenance is in the process of replacing railroad ties on the front apron of the New Carrollton shop, which were creating a trip hazard for mechanics, which must work on RMMs on the apron due to the lack of space inside the CTEM shop. Asphalt is being used to replace the railroad ties. This is a sample of positive practices being implemented CTEM personnel stated that a procurement card issue was preventing the procurement of spare parts for CTEM RMMs, which were causing an excessive number of RMMs being out of service due to the inability to buy spare parts. RMMs are needed to repair and maintain track and wayside equipment on a continuous basis. This issue was brought up during the Railcars Bi-weekly Meeting as a deficiency. The spare parts purchasing issue has been corrected and CMNT is now able to order the spare parts, which are needed to repair, maintain, and get RMMS including Prime Movers back in service Positive practices - CTEM personnel stated that they have a poor lighting issue in the open pit at the CTEM Shop in Branch Avenue. CTEM is working with Facilities								N	0					

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

| Inspector in Charge's Signature | Date 2024/11/03

Date 2024/11/03



Inspection Form

Form WMSC-IR-1
Washington Metrorail Safety Commission

Inspector in Charge's Name	Inspection Team
Manuel Lopez	N/A