

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

12Agency/Department Information

Incuration Data	YYYY	MM	DD	Donast Number	20191217-WMATA-KEK-15				
Inspection Date	2019	12	17	Report Number					
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	ATC Sub- Department				
	Name			Email	Office Phone		Mobile Phone		
Rail Agency Department									
Contact Information									
Inspection Location	F09 – CM-378+15 to CM-383+25 – Naylor Road – Green Line								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TRK-OBS-PI					
Inspection Units	0					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	0					
Remedial Action Required ¹	NO					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1 Ir	spection Sub	ject	Wayside Inspection			Activity Co	ode AT		С	OBS	WI		
Job Briefing Employee Name/Title	WMATA	WMATA RWIC –				mpanied ector?	YES	Out Brief Conducted	YES	Time			Outside Shift	YES/NO
Related Reports	Track Inspection Verfication #14			Related CAPS / Findings N/A										
	Ref Rule			Rule or S	le or SOP		Standard		Other / T	Other / Title		Checklist Reference		
Related Rules, SOPs, Standards, or Other	RWP					ATPA-RT-S	ATPA-RT-S-SC-041-03		WO#					
Standards, or Strict	ATC-100	ATC-1000 3003 –		3003 – II	– Interlocking Insp		Vendor O8	Vendor O&M Manual		TCR-Book of Plans		Form 3003		
Inspection Location	Main Track	Yard	Statio	on (осс	RTA Facility	WMSC Office	Track Trace	At-grad	le Tunnel		Elevated		Interlock
	х		Х					Track Type					х	Х
Line/a)	Green-Line Track Number			1 2 0	3t Chain Ma and/or St				From			То		
Line(s)			er	1, 2, &					+15 Green Line F09 -		F09 -	– CM-383+25 Green Line		
	Head Car Number		N	Number of Cars		Equipment								
Vehicles	N/A			N/A				N/A						
Description	Wayside walk-thru Inspection from station to interlocking Number o					of Defect	cts 0							

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
Kemmery E. Kendrick		December 17, 2019
Inspector in Charge – Name	Inspection Team	
Kemmery E. Kendrick	Washington Metrorail Safety Commission	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	ATC-PMI Audio Frequency Track Circuit (Shunt Verification) testing, December 17,	Recommended Finding?	NO
	2019. Between CM378+51 Naylor Road F09 to CM-383+25 Interlocking. ATC work crew under the direction of RWIC-Thomas Smith, using ETO, working under	Remedial Action Required?	NO
	normal revenue service in conjunction with speed restrictions (via couplers) performed regular PMI inspection. Job Safety Briefing performed the roadway crew members entered the ROW to perform Wayside Inspection in conjunction with track shunting approximately 1045am. The ATC TCR room Technician — using Local Control in TCR, monitored the work crew movement through the interlocking, and provided an additional level of Roadway Worker Protection. After the Job Safety Briefing the roadway crew members entered the roadway to perform the quarterly ATC Wayside Inspection on Track #1 at approximately 01045am. With Form #3003 in hand the ATC roadway crew working from CM — 378+15, proceeding East CM — 383+25 began inspecting the route; assuring that the right-of-way is free of defects that can result in failures. The inspection includes checking all platform areas, appropriate signage, ballast, rails, impedance bond connections, ATO markers, and junction boxes for any visible anomalies Once work crew members reached CM — 383+256, they crossed over to Track #2 West and inspected the route in the opposite direction until they reached CM 378+15. Inspection compete, all roadway workers cleared the interlocking, reported clear to the ROCC, and restored the system to normal operation at 1059am. No deficiencies to note	Recommended Reinspection?	NO
Remedial Action			

Photos:...

Form WMSC-IR-1 Version date: 10/5/18