

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20101217 WAATA KEK 16					
inspection Date	2019	12	18	Report Number	20191217-WMATA-KEK-16					
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	ATC	Sub- Dep	partment	Contractor		
	Name			Email	Office Phone		Mobile Phone			
Rail Agency Department										
Contact Information										
Inspection Location	Roadway Worker Inspection – ROW – Track #2 East Direction – F09 (Naylor Road Station) to F10 (Suitland Station)									

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	ATC-OBS-PI - AMF	ATC-OBS-PI - ROW				
Inspection Units	9	2				
Inspection Subunits	0	0				
Defects (Number)	1	1				
Recommended Finding	0	0				
Remedial Action Required ¹	YES	YES				
Recommended Reinspection	YES	YES				

Activity Summaries

Inspection Activity #	1	Inspection	Subject	ATC	AMF &	Roadway Work Observation			Activity Code		ATC		OBS	PI
Job Briefing Employee Name/Title	WMATA RWIC – N/A				companied spector?	N/A	Out Brief Conducted	N/A	Time	1120	lam	Outside Shift	NO	
Related Reports	N/A				Re	Related CAPS / Findings N/A								
	Ref Rule or			or SOP	DP Standard			Other / Title			Checklist Reference			
Related Rules, SOPs, Standards, or Other	RWP – Section 5 MSRF			ч										
Standards, or Other														
	Main Track	Yard	l St	ation	occ	RTA Facility	WMSC Office	Tuesda Taure	At-grad	e Tui	nnel	Ele	evated	N/A
Inspection Location	x			x				Track Type				x		
1:	Crean	Tr	ack	Track #2 Chain		Chain Ma	Marker		From		То			
Line(s)	Green-Line Number		Ira	CK #2	and/or St	and/or Station(s) CM 378+15 -		F09 - Naylor Road CM 4		448+50 – F10 – Suitland Sta.				
	Head	Car Numb	er	Numb	er of Ca									
Vehicles	N/A			N/A	Equip	ment	N/A							
Description	AMF Platform and Roadway Worker (ROW) Observ				V) Observatio	n Number of Defects				2				

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY E. KENDRICK		December 17, 2019
Inspector in Charge – Name	Inspection Team	
Kemmery E. Kendrick	Washington Metrorail Safety Commission	



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	At approximately 1125am, a contractor acting as the Advance Mobile Flagger	Recommended Finding?	NO
	(AMF) at location F09 Naylor Road, East end of the platform, did perform watchman/lookout. The AMF provided protection for 2 ATC work crew members	Remedial Action Required?	YES
	 watchman/iookout. The AMF provided protection for 2 ATC work crew members who were performing track inspection. Using Foul Time, under revenue service, the work crew performed inspection due to a bobbing track circuit between - F09 Naylor Road and F10 Suitland Stations. The AMF displayed the following PPE: safety glasses, safety footwear, high visibility orange safety vest, amber lantern, orange flag, air horn, whistle, and an approved certified radio. 1135(am), while aboard WMATA train, riding on the lead car #7562, along with consist #7563, 7501, 7600, 7503, 7457 and 7456, headed eastward in proximity of CM: 397+39 and CM: 448+50, I did witness 2 roadway workers fouling within the Dynamic Envelope. Meaning; 2 WMATA employees, field side, up against a wall type structure of the roadway, did foul within the required 4ft clearance of the track. I did not see a catwalk/safety walk. The work crew members did display the appropriate hand signals to the approaching train. The crew members had on the required PPE. MSRPH Section 5.4.2 - states "when there is no engineered safety zone (catwalk, safety walk, etc.), the minimum distance from the field side of the rail to a point of safety is not less than 4 feet. " The train operator did reduce her speed through the area, using short blasts of the trains horn until she passed the work crews on the ROW. 	Recommended Reinspection?	YES
Remedial Action	Notified ATC Superintendents of the actions of WMATA employees and contractors	for re-enforcement of WMATA poli	cies for RWP

Photos: