

# **Inspection Form**

### Washington Metrorail Safety Commission

# Form WMSC-IR-1

#### Agency/Department Information

Inspection Date	YYYY	MM DD		Report Number	20200720 \/\/ 4 4 TA   D\// 1					
inspection Date	2020	07	29	Report Number	20200729-WMATA-LBW-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Operations	Sub- Department		Stations		
	Name			Email	Office Phone		Mobile Phone			
Rail Agency Department										
Contact Information										
Inspection Location	Eisenhowei	<sup>-</sup> Avenue (C1	4)							

#### Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	RTRA-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	2					
Recommended Finding	No					
Remedial Action Required <sup>1</sup>	No					
Recommended Reinspection	Yes					

### **Activity Summaries**

Inspection Activity #	1	lnsp Subj	ection ject		Station	Assessment – Eisenhower Avenue(C14)				Activity Code		RTRA		GEN	RR
Job Briefing Employee Name/Title	NA			Accompanied Inspector?		NA	Out Brief Conducted	NA	Time	N	4	Outside Shift	NA		
Related Reports	N/A			Related CAPS / NA Findings											
Related Rules, SOPs, Standards, or Other	Ref				Rule or 3	SOP		Standard		Other /	Title		Cheo	cklist Refer	ence
Inspection Location	Ma Tra		Yard	Stat	ion C	OCC	RTA Facility	WMSC Office	Track Type	At-grad	e Tur	nnel	Elev	vated	N/A
Line(s)	Char	lie	Track Numb		x		Chain Marker and/or Station(s)		F	X   From			То		
Vehicles	Неа	d Car	Number	N	lumber o	of Cars	;	ment							
Description	Stati of Ei	ion Co senho	ndition R wer Aver	ollup nue (C	Report. C14), QIC	In pre O and	paration fo	or the retur ssed statio	e Restoration in to service n readiness.	Number	of Defect	ts			2
identify documented a				ed and	aintenance records were queried by QICO to d outstanding items. A risk rating was assigned ntified during field assessments.					Recommended Finding?				No	



# **Inspection Form**

# Form WMSC-IR-1

# Washington Metrorail Safety Commission

	Due to COVID-19 and social distancing, this inspection was completed without entering Eisenhower Avenue (C14) and without interacting with	Remedial Action Required?	No
Remedial Action	any Metrorail personnel. Discrepancies Identified for further review and follow up: 1. Train Approach Warning (TAW) lights did not flash as train transited the station Risk – Moderate (3,3) – LVEM Sisk – Moderate (3,3) – LVEM	Recommended Reinspection?	Yes

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		<b>Date</b> 07/29/20
Inspector in Charge – Name	Inspection Team	
Bruce Walker	Bruce Walker	