

# **Inspection Form**

### Form WMSC-IR-1

## Washington Metrorail Safety Commission

#### Agency/Department Information

Inspection Date	YYYY MM DD			Report Number	2020102C WMAATA TVS 1				
	2020	10	26	Report Number	20201026-WMATA-TKS-1				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRPM	Sub- Dep			
Rail Agency Department Contact Information	ı	Name		Email	Office Phone		Mobile Phone		
Inspection Location	B-Line, Windam Lane (B10-1) Traction Power Substation (TPSS), Wheaton								

#### **Inspection Summary**

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-GEN-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required <sup>1</sup>	No					
Recommended Reinspection	No					

#### **Activity Summary**

Inspection Activity #	1	Inspe	ection Sub	ject	Virtual Inspection – Breaker PMI				Activity Co	ode	TP		GEN	OBS		
Job Briefing Employee Name/Title	WMATA TRPM Personnel					Accompanied Inspector?		N/A	Out Brief Conducted	N/A	Time	1000 140		Outside Shift	No	
Related Reports	N/A					Rela	Related CAPS / Findings N/A			N/A						
	Ref R			Rule	Rule or SOP			Standard		Other / Title			Checklist Reference			
Related Rules, SOPs, Standards, or Other	"PREVENTIVE MAINTENANCE INSPECTION FOR NDC HIGH SPEED 750 VDC CIRCUIT BREAKER Annual Inspection" REVISION 2, 06/20/2013 MSRPH															
Inspection Location		Main Track Yard Star		Stati	tion OCC		RT. Faci		WMSC Office	T	At-grade	e Tui	Tunnel		vated	N/A
							х	I		Track Type						x
Line(s)	B-Line		Track		N/A Chain Mai		n Mai	ker		From			То			
Line(s)	D-Line	Number		er	14//	<u> </u>	and/or Sta		ation(s) Windham La		e TPSS (B10-1) Wind		Windl	dham Lane TPSS (B10-1)		
Vehicles	Head Car Number			1	Number of Cars		ers Equipment		mant	N/A						
venicies	N/A				N/A Equi		.quipi	ment N/A								
Description	WMSC inspector performed a virtual inspection of the job safety briefing via							Number of Defects					0			
	Traction Power Maintenance's					RPM) job safety briefing forms.					Recommended Finding?					No
										Remedial Action Required?				No		

Form WMSC-IR-1 Version date: 10/5/18

1



## **Inspection Form**

### Form WMSC-IR-1

## Washington Metrorail Safety Commission

	The WMSC inspector did not note any defects with the Job Safety Briefing.  WMSC inspector performed a virtual inspection of the feeder breakers and cathode breakers PMI conducted at Windham Lane (B10-1) Traction Power Substation via test sheets provided by TRPM.  The WMSC inspector did not note any defects.	Recommended Reinspection?	No
Remedial Action	N/A		<u> </u>

<sup>&</sup>lt;sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

are sufficient and effective.							
Inspector in Charge - Signature	Date						
		l					
Inspector in Charge – Name	Inspection Team						
Tino Sahoo	Tino Sahoo						

Form WMSC-IR-1 Version date: 10/5/18