

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY MM DD			Report Number	20201215-WMATA-TKS-1			
	2020	12	15	Report Number	20201213-VVIVIA1A-1K3-1			
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRPM Sub- Department			
Rail Agency Department Contact Information	ı	Name		Email	Office Phone		Mobile Phone	
Inspection Location	B-Line, Rhode Island (B04) Parking Garage							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-GEN-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	1					
Recommended Finding	No					
Remedial Action Required ¹	Yes					
Recommended Reinspection	Yes					

Activity Summary

Inspection Activity #	1	Inspe	spection Subject Virtual		Virtual I	nspection – Generator PMI			Activity Code		TP	GEN	OBS	
Job Briefing Employee Name/Title	WMATA TRPM Personnel				Accompanied Inspector?		N/A	Out Brief Conducted	N/A	Time	1200 1600		No	
Related Reports	N/A	N/A				Related CAPS / Findings N/A						•		
	Ref Rule			Rule or SOP			Standard	Other / Title			Checklist Reference			
Related Rules, SOPs, Standards, or Other	MAINT INSPEC FOR STATIC EMERC STANE GENER Month	ONARY GENCY D-BY PO RATOR hly, Bi- al Inspe	ICE	d										
	Main Track		Yard	Statio	n C	СС	RTA Facility	WMSC Office		At-grad	e Tu	nnel	Elevated	N/A
Inspection Location				X					Track Type	х				
lima/a)	Track			N/A	Chain Ma		rker		From			То		
Line(s)	B-Line Number		r	N/A	and/or St		ation(s) Rhode Island		(B04) Rhoo		Rhode	de Island (B04)		
	Head Car Number		N	Number of Cars										
Vehicles N/A N/A Equipment N/A					Equip	nent	N/A							

Form WMSC-IR-1 Version date: 10/5/18

1



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	WMSC inspector performed a virtual inspection of the job safety briefing via	Number of Defects	1				
	Traction Power Maintenance's (TRPM) job safety briefing forms.	Recommended Finding?	No				
	The WMSC inspector did not note any defects with the Job Safety Briefing.	Remedial Action Required?	Yes				
Description	WMSC inspector performed a virtual inspection of the generator PMI conducted at Rhode Island (B04) via test sheets provided by TRPM. The WMSC inspector did note the following defect: 1. Generator door(s) are broken and cannot be secured.	Recommended Reinspection?	Yes				
Remedial Action	To achieve compliance with WMATA's requirements: • WMATA must either repair or replace the broken doors of the generator.						

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

are sufficient and effective.							
Inspector in Charge - Signature		Date					
Inspector in Charge – Name	Inspection Team						
Tino Sahoo	Tino Sahoo						
Tino Sanoo	Tino Sanoo						

Form WMSC-IR-1 Version date: 10/5/18