

Inspection Form

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date		YYYY/MM/DD	Report Number	20210503-WMATA-TKS-1				
Inspection Date		2021/05/03	Report Number	20210202-MMMUM-1K2-1				
Rail Agency Name	Wash	ington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	TRPN	1	Contact Information					
Inspection Location	F-Lin	ne, Southern Ave (F08) Traction Power Substation (TPSS)						
Inspection Summary								
Inspection Activity #	tion Activity # 1							
Activity Code		TP-GEN-OBS						
Inspection Units		1						

Inspection Suburits 1 Inspection Suburits 1 Defects (Number) 0 Recommended Finding No Remedial Action Required¹ No Recommended Reinspection No

Activity Summaries

Inspection Activity #	1	Ins	pection Sub	ion Subject Virtual Inspec			- Battery Bai	Activity Code			TP-GEN-OBS					
Job Briefing Employee Name/Title	WMATA TRPM Personnel			Accompanied Inspector?			No	Out Brief Conducted	No	No Time			05:00 PM		No	
Related Reports				Related CAPS / Findings										-		
	Ref		Rule	e or SOP			Standard		Other / Title				Checklist Reference			
Related Rules, SOPs, Standards, or Other	"PREVENTIVE MAINTENANCE INSPECTION FOR BATTERY MAINTENANCE 84 Day Inspection" REVISION 1, AUGUST 22, 2011		MSR	MSRPH												
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunn		el Elevat		ited I	N/A		
					×	(Х	
Line(s) & Track	F-Line, Sout	•	08) Tractic	on Power	Chain Ma	rker and/	or Station(s)		From e (F08) TPSS			То				
Number	Substation ((TPSS)			chain ma		01 5tation(5)	Southern Ave (Southern Ave (F08) TPSS				
Vehicles	Head Car Number			Number of Cars		Equipm	nent N/A									
	N/A			N/A			Inpinent N/A									
Description	WMSC inspector performed a virtual inspection of the job safety briefing by reviewing the Traction Power Maintenance's (TRPM) job safety briefing forms provided for each inspection. The WMSC inspector did not note any defects with the Job Safety Briefing. WMSC inspector performed a virtual inspection of the battery bank PMI conducted at									Number of Defects					0	
										Recommended Finding?					No	
										Remedial Action Required?					No	
	Southern Ave (F08) TPSS via test sheets provided by TRPM. The WMSC inspe note any defects.								or did not Recommended Reinspection?				No	J		
Remedial Action																

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.
Inspector in Charge's Signature
Date

inspector in charge's signature		2021/05/03
Inspector in Charge's Name Tino Tanmaya Sahoo	Inspection Team	