

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	20210704-WMATA-KEK-20			
	2021/07/07	Report Number	20210704-WIVIATA-KEK-20			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	Rail Operations Control Center (ROCC) - Ops #2	Contact Information	ROCC			
Inspection Location	WMATA Open MHz - Channel - Ops #2					

Inspection Summary

Inspection Activity #	1
Activity Code	OBS/QAI/OBS
Inspection Units	1
Inspection Subunits	1
Defects (Number)	1
Recommended Finding	
Remedial Action Required ¹	Yes
Recommended Reinspection	No

Activity Summaries

Inspection Activity #		Ins	pection Sub	ject	t					Activity Code				OBS/QAI/OBS			
Job Briefing Employee Name/Title				Accompanied Inspector?				Out Brief Conducted	Time		05:42 PM		Outside Shift	Yes			
Related Reports			Related CAPS / Findings				-	-									
Related Rules,	Ref Rule or SOP Stand				Standard	Other / Title					Checklist Reference						
SOPs, Standards, or Other	MSRPH 1.79																
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		de Tunnel El		Eleva	ted	N/A		
Line(s) & Track Number	WMATA Op	en MHz - Cl	hannel - O _l	rel - Ops #2 Chain Marker and/or Station(s) 415 + 04				From To 409 + 04					То	0			
Vehicles	Head Car		N	Number of 0	Cars	Equipm	ent	Radio MHz Co	MHz Communications								
								ter roadway,	Number of Defects				1				
	or person has entered the roadway at East Falls Church. 5:25pm ROCC Operator, Ops #2 reported "person/customer attempting to enter roadway, or person has entered the roadway at East Falls Church – K05. 5:25pm ROCC Operator, Ops #2 called for a 10mph									Recommended Finding?							
										Remedial Action Required?				Y	es		
Description	Speed Restriction. 5:45:27pm ROCC Operator, Ops #2 requested Station Manager to investigate. 5:46:19pm Station Mgmt. reported back to confirm that no visible evidence of person entering or on about the roadway. Ops #2 radio appeared to go low/high. Meaning it was difficult to hear the conclusion of this event. This does not conclude that transmission between Train Operator and ROCC Ops #2 was not clearly understood between the receiver or transmitter.								lo								
Remedial Action	Derween un	e receiver i	JI LI GIISIIII	rrei													

1 The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to again WMSC verification inspections to ensure corrections are sufficient and effective.

Action. Closeout of Kemediai Actions may also	be subject to ongoing wivisc verification inspections to ensure corrections are sufficient and effective.	
Inspector in Charge's Signature		Date 2021/07/07
Inspector in Charge's Name Kemmery Kendrick	Inspection Team N/A	

Form WMSC-IR-1 Version date: 1/14/2022