

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/	/Department	Information
---------	-------------	-------------

Inspection Date	YYYY/MM/DD	Report Number	20220210-WMATA-LBW-02			
	2022/02/10	Report Number				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	RTRA	Contact Information				
Inspection Location	Rhode Island Station 919 Rhode Island Ave NE Washington, DC 20018					

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity	Train operator - mainline operation															
#	1	Ins	spection Sub	Subject inspection Activity Code												
Job Briefing Employee Name/Title	NA			Accompanied Inspector?			No	Out Brief Conducted		Time		07:09 AM		Outside Shift	No	
Related Reports	NA		Related CAPS / Findings			NA										
Related Rules,	Ref		Rule	e or SOP			Standard		Other / Title				Checklist Reference			
SOPs, Standards, or Other	NA Ba			P #40 Door operations SOP #50 seline Announcements GR 9; 3.82			NA		NA				NA			
Inspection Location	Main Track	Yard	Station	occ	RTA F	acility	WMSC Office Track Type		At-grade Tunne		el	Elevated N/A		N/A		
	Х								Х	X X			Х			
Line(s) & Track	Rhode Islan	Rhode Island Station 919 Rhode Isl				Island			From				To			
Number	Ave NE Washington, DC 20018			Chain Marker and/o			Rhode Island		d Ave Gall Stat				lery Place - Chinatown tion			
Vehicles	Head Car Number N			Number of Cars			ent NA									
venicles	3063			NA Equipme												
	The WMSC inspector conducted a riding inspection of Train ID 101 from Rhode Island									Number of Defects				0		
	Avenue Station (RI) to Gallery Place - Chinatown Station (GP). The purpose of the inspection was train operator (TO) rules compliance. On approach to RI station, the TO									Recommended Finding?					No	
Description	entered and properly berthed at the 8-car marker. The TO was observed following all								Remedial Action Required?				١	No		
	rules of SOP #40 (door operations). The TO was observed entering all stations at under 39mph and responded correctly to all over speed alarm conditions. The train operator performed all required train announcements.								Recommended Reinspection?				١	No		
Remedial Action																

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/02/10
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team	