

Inspection Form

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Report Number	20221602-WMATA-KEK-49					
Inspection Date	2022/02/16	Report Number	20221002-WWAIA-KEK-49					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	ATCM	Contact Information						
Inspection Location	E08 Prince George's Plaza Station- W/O #16198089 - Complete - 09/02/21 E09 - W/O #16198212 - Complete - 08/24/21 E10 - W/O #16198216 - Complete - 08/31/21							
Inspection Summary								
Inspection Activity #		1						
Activity Code								
Inspection Units								
Inspection Subunits								
Defects (Number)								
Recommended Finding								

Remedial Action Required¹ Recommended Reinspection

Activity Summaries

Inspection Activity #	3	Ins	pection Sub	ject	Deferred PMIs - Switch Indication Locking Test			Activity Code							
Job Briefing Employee Name/Title	N/A	A			Accompanied Inspector?		No	Out Brief Conducted	No	Time		11:00 AM		Outside Shift	No
Related Reports	Maintenance	e Log 0.0-12	21 Related CAPS / Findings			WMSC-21-C010	VMSC-21-C0106								
Related Rules,	Ref Rule			le or SOP		Standard		Other / Title				Checklist Reference			
SOPs, Standards, or Other	MSRPH, TCR Manuals, CF ATC-2000	,											ATC-1000, Form 1009 Rev. 4.0		
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		el	Eleva	ited	N/A	
Line(s) & Track Number	E08 - W/O #16198089 - Complete - 09/02/21 E09 - W/O #16198212 - Complete - 08/24/21 E10 - W/O #16198216 - Complete - 08/31/21 Chain Marker and/or Station(s)					From To					То				
Vehicles	Head Car	Head Car Number Of Cars Equipment													
	1009 - Switch Indication Locking Testing and Deferred Maintenance. MID Shift assignment. Purpose: This test is performed every 2 years, or after any disarrangement, repair or modification. Test is to ensure that no Signal may be cleared over a switch or derail that failed to operate to the corresponding position of its controlling device. This								Number of Defects						
									Recommended Finding?						
									Remedial Action Required?						
Description	is a Federal Railroad Administration (FRA) required test per CFR Title 49 - 236.105. WMATA ATCM and ATCE use regulatory guidance from ATPA, FTA, and FRA to accomplish System Safety Testing Practices. Responsible ATC qualified staff: ATC Mechanic C/B/A/AA, as determined by the OJT Qualification Program or approved as proficient by ATCM Management.						Recommended Reinspection?								
Remedial Action														-	

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/02/16
Inspector in Charge's Name Kemmery Kendrick	Inspection Team	