

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Inspection Date	YYYY/MM/DD	Report Number	20220224-WMATA-LBW-02				
	2022/02/24	Report Number	20220224-WIWATA-LBW-02				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	RTRA	Contact Information					
Inspection Location	Boarding Location Rhode Island Station 919 Rhode Island Ave NE Washington, DC 20018						
In a section Community							

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Inspection Activity #	1	Insp	oject Train operator - mainline operation inspection				Activity (
Job Briefing Employee Name/Title	NA			Accompanied Inspector?			No	Out Brief Conducted	No	Time		02:07 PM		Outside Shift	No	
Related Reports	NA		Related CAPS / Findings NA			NA	NA									
Dalata I Dalata	Ref		e or SOP			Standard		Other / Title				Checklist Reference				
Related Rules, SOPs, Standards, or Other	NA Bas			P #40 Door operations SOP #50 seline Announcements GR 9; 3.82		NA		NA				NA				
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		el Elevat		ted	N/A		
	Х															
Line(s) & Track Number	Boarding Location Rhode Island S 919 Rhode Island Ave NE Washing 20018						or Station(s)	From Rhode Island Avenue Station				To Medical Center Station				
Vehicles	Head Car Number N			Number of Cars												
	6004			Equipment			ent									
Description	The WMSC inspector conducted a riding inspection of Train ID 111 from Rhode Island									Number of Defects						
	Avenue Station to Medical Center. The purpose of the inspection was train operator (TO) rules compliance. On approach to Rhode Island Avenue Station, the TO entered and									Recommended Finding?					No	
	properly berthed at the 8-car marker. The TO was observed following all rules of SOP #40									Remedial Action Required?					No	
	(door operations). The TO was observed entering all stations at under 39mph and responded correctly to all over speed alarm conditions. The train operator performed all required train announcements.									Recommended Reinspection?					No	
Remedial Action																

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/02/24
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team	