

Inspection Form

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Data	YYYY/MM/DD	Report Number	20220317-WMATA-LBW-02					
Inspection Date	2022/03/17	Report Number						
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	RTRA	Contact Information						
Inspection Location	Rhode Island Ave to Gallery Place	ie Island Ave to Gallery Place						
Inspection Summary								
Inspection Activity #	spection Activity # 1							
Activity Code	RTRA-RI-OBS							
Inspection Units		1						
Inspection Subunits		0						
Defects (Number)		0						
Recommended Finding	No							

No

No

Activity Summaries

Remedial Action Required¹ Recommended Reinspection

Inspection Activity #	1	Insp	ection Subj	Train operator - mainline operation inspection			Activity Code			RTRA-RI-OBS					
Job Briefing Employee Name/Title	NA			Accompanied Inspector?			No	Out Brief Conducted	Yes	Time		11:07 AM		Outside Shift	No
Related Reports	NA			Related CAPS / Findings NA			NA					-			
Related Rules,	Ref Rul			le or SOP		Standard		Other / Title				Checklist Reference			
SOPs, Standards, or Other	NA			#40 Door o line Annou 3.82	•		NA		NA				NA		
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-g	rade Tunnel		l Elevated		ted I	N/A
	Х		х						х		х				
Line(s) & Track Number								From				1	То		
	Rhode Islan	d to Galler	Chain Marker and/o		Rhode Island		Avenue Station				allery Place - China own Station				
Vehicles	Head Car	Head Car Number Of Cars		NA											
venicies	32	70		NA Equipmen			em	NA							
	The WMSC inspector conducted a riding inspection of Train ID 111 from Rhode Island								Number of Defects				0		
Description	Avenue Station to Gallery Place. The purpose of the inspection was train operator (TO) rules compliance. On approach to Rhode Island Avenue Station, the TO entered and									Recommended Finding?				No)
	properly berthed at the 8-car marker. The TO was observed following all rules of SOP #40								Remedial Action Required?				No)	
Description	(door operations). The TO was observed entering all stations at under 39mph and responded correctly to all over speed alarm conditions. The train operator performed all required train announcements. There were Metrorail personnel on the roadway and the T/O sounded the mainline horn as required and followed all speed requirements.						Recommended Reinspection?				No)			
Remedial Action															

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2022/03/17
Inspector in Charge's Name	Inspection Team	
LeBon Bruce Walker	NA	