

Office: 202-384-1520 • Website: www.wmsc.gov

WMSC Commissioner Brief: W-0247 Evacuation for Life Safety Reasons - Greenbelt Rail Yard - April 18, 2023

Prepared for Washington Metrorail Safety Commission meeting on October 24, 2023

Safety event summary:

On Tuesday, April 18, 2023, the Greenbelt Rail Yard Railcar Service and Inspection Shop was evacuated for life safety reasons due to a natural gas leak outside the building. There were no injuries reported as a result of this event.

At 2:29 a.m., an Office of Car Maintenance Supervisor reported a gas leak outside the building to the Maintenace Operations Center Controller in the Rail Operations Control Center, who in turn requested assistance from the Prince George's County Fire Department (PGFD) and notified the Metro Transit Police Department. Plant Maintenance personnel were dispatched to use a gas leak detector to assist in identifying the leak.

PGFD identified the gas meter, owned by Washington Gas, as the source of the leak and shut off the gas. Personnel were allowed to reenter the building.

Washington Gas responded the following day and identified a defective regulator on the gas meter as the cause of the leak. Maintenance and the inspection of the meter are the responsibility of Washington Gas. Washington Gas replaced the manifold feeding the Service and Inspection Shop.

A work order in Maximo, Metrorail's asset management system, showed that a gas leak was previously reported in the same location on April 13, 2023, and that Washington Gas was scheduled to make repairs the day this event occurred.

Probable Cause:

The probable cause of this evacuation for life safety reasons was a gas leak caused by a defective regulator that had not yet been maintained and repaired.



Washington Metropolitan Area Transit Authority Department of Safety (SAFE) Office of Safety Investigations (OSI)

FINAL REPORT OF INVESTIGATION A&I E23266

Date of Event:	April 18, 2023
Type of Event:	Evacuation for Life Safety Reasons (Gas Leak)
Incident Time:	02:29 hours
Location:	Greenbelt Yard – Building B, Service & Inspection
	(S&I) Shop
Time and How received by SAFE:	03:31 hours – MAC (Mission Assurance Coordinator)
WMSC Notification Time:	03:14 hours
Responding Safety Officers:	None
Rail Vehicle:	None
Injuries:	None
Damage:	None
Emergency Responders:	Prince George's County Fire Department (PGFD),
	Metro Transit Police Department (MTPD)
SMS I/A Incident Number:	20230427#108038

Incident Date: 04/18/2023 Time: 02:29 hours Final Report - Evacaution for Life Safety Reasons

E23266

Drafted By: SAFE 710 - 06/13/2023 Reviewed By: SAFE 704 - 06/15/2023 Approved By: SAFE71 – 06/20/2023

Greenbelt Yard Building, Service & Inspection Shop – Evacuation for Life Safety Reason

April 18, 2023

Table of Contents

Albana intima and Amanana	
Abbreviations and Acronyms	
Executive Summary	4
Incident Site	
Field Sketch/Schematics	
Purpose and Scope	
Investigative Methods	
Investigation	6
Chronological Event Timeline	
Interview Findings	
Weather	
	_
Related Rules and Procedures	
Human Factors	_
Evidence of Fatigue	8
Fatigue Risk	8
Post-Incident Toxicology Testing	
Findings	
Findings	
Immediate Mitigation to Prevent Recurrence	
Probable Cause Statement	
Recommended Corrective Actions	9
Appendices	· 10
Appendix A – Photographs	
Appendix B – Work Orders (Redacted)	
Appendix C - CMNT Fire Drill Exercise Form	· 15

Approved By: SAFE71 – 06/20/2023

Abbreviations and Acronyms

ARS Audio Recording System

CAP Corrective Action Plan

CCTV Closed-Circuit Television

CMNT Office of Car Maintenance

MAC Mission Assurance Coordinator

MOC Maintenance Operations Center

MSRPH Metrorail Safety Rules and Procedures Handbook

MTPD Metro Transit Police Department

NOAA National Oceanic and Atmospheric Administration

PGFD Prince George's County Fire Department

PLNT Plant Maintenance

RTRA Office of Rail Transportation

ROCC Rail Operations Control Center

S&I Service and Inspection

SAFE Department of Safety

SMS Safety Measurement System

WMATA Washington Metropolitan Area Transit Authority

WMSC Washington Metrorail Safety Commission

Approved By: SAFE71 – 06/20/2023

Washington Metropolitan Area Transit Authority Department of Safety – Office of Safety Investigations

Executive Summary

*Note that all times listed are approximate and may contain minor variations due to differences between systems of record. *

On Tuesday, April 18, 2023, at 02:29 hours, an Evacuation for Life Safety Reasons event occurred at Greenbelt Rail Yard's Service and Inspection (S&I) Shop due to a natural gas leak outside the building. The Office of Car Maintenance (CMNT) Supervisor reported a gas leak outside of the S&I shop to the Maintenance Operations Center (MOC) Plant Maintenance (PLNT) desk. The MOC Controller confirmed this event with the reporting person and contacted the Prince George's County Fire Department (PGFD).

At 02:33 hours, Metro Transit Police Department (MTPD) and PLNT maintenance personnel were notified of the gas leak. PGFD arrived on the scene and detected the location of the gas leak as the gas meter, which is owned by Washington Gas. At 03:09 hours, PGFD shut the gas off, and personnel were allowed to return to the building. PLNT contacted Washington Gas, who responded on April 19, 2023, and identified the cause of the leak as a defective regulator. Maintenance and inspection of the equipment is the responsibility of Washington Gas, who are able to access the facility.

The probable cause of the Evacuation for Life Safety Reasons (Gas Leak) event was determined to be a gas leak from the gas meter located on the external portion of Building B. Washington Gas responded on April 19, 2023, and determined the source of the leak to be a defective regulator and replaced the manifold feeding the S&I shop.

Incident Site

Greenbelt Yard Service & Inspection (S&I) Shop – Building B,

Field Sketch/Schematics



Figure 1 - Building - B (S&I Shop) location of leaking gas meter. The above depiction is not to scale.

Purpose and Scope

The purpose of this accident investigation and candid self-evaluation is to collect and analyze available facts, determine the probable cause(s) of the incident, identify contributing factors, and make recommendations to prevent a recurrence.

Investigative Methods

Upon receiving notification of the Evacuation for Life Safety Reasons event at the Greenbelt Rail Yard, Building B (S&I shop) on Tuesday, April 18, 2023, SAFE team members worked with relevant WMATA subject matter experts to review the incident's facts and data.

The investigative methodologies included the following:

- Physical Site Assessment
- Informal Interviews Collected through conversations with individuals during the investigation to provide background and supporting information. Written statements were reviewed from personnel present during the event.
 - CMNT Electrician
- Documentation Review Collection of relevant work information and process documentation in WMATA record systems. These records include the following:
 - Metrorail Safety Rules and Procedures Handbook (MSRPH)
 - National Oceanic and Atmospheric Administration (NOAA)
 - Maximo
 - Rail Operation Control Center (ROCC) Incident Report

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons E23266

- CMNT Fire Drill Exercise Form
- System Data Recording Review Collection of information contained in Metro Data Recording Systems. This data includes:
 - Audio Recording System (ARS) playback (Phone)
 - Closed-Circuit Television (CCTV)

<u>Investigation</u>

On Tuesday, April 18, 2023, at 02:29 hours, an Evacuation for Life Safety Reasons event occurred at Greenbelt Rail Yard's S&I Shop due to a natural gas leak outside the building. CMNT Supervisor notified MOC's PLNT desk of a gas leak outside the S&I shop. The MOC Maintenance Controller confirmed this event with the reporting person and contacted PGFD.




Image 1 - Front View of Leaking Gas Meter on Exterior of Building B (S&I Shop)

At 02:33 hours, MTPD and PLNT maintenance personnel were notified of the gas leak.

During an informal interview with the electrician on duty, they reported that PGFD arrived on the scene and detected the location of the gas leak. At 03:09 hours, PGFD shut the gas off, and personnel were allowed to return to the building.

Washington Gas responded on April 19, 2023, and determined the source of the leak to be a defective regulator and replaced the manifold feeding the S&I shop.

According to WO# 17805063, the smell of gas was previously reported on 4/13/2023, and the gas was shut off. Washington Gas was scheduled to make repairs on 4/18/2023.

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons E23266



Image 2 - Side View of Leaking Gas Meter on Exterior of Building B (S&I Shop)

Chronological Event Timeline

A review of ARS playback, i.e., phone and radio communications, revealed the following timeline:

	biayback, i.e., phone and radio communications, revealed the following timeline
Time	Description
02:29:54 hours	CMNT Supervisor: Reported the smell of gas leaking in the front of Building B (S&I shop) at Greenbelt rail yard. MOC Controller: Acknowledged and requested that the building be
	evacuated. [Phone/ MOC]
02:31:11 hours	MOC Controller: Notified PGFD of the reported smell of gas leaking from Building B (S&I shop) [Phone/ MOC]
02:33:23 hours	MOC Controller: Notified PLNT department and requested plumbers to Building B (S&I shop) [Phone/ MOC]
02:33:43 hours	MOC Controller: Notified MTPD of the gas leak at E99 [Phone/ MOC]
02:34:34 hours	MOC Controller: Notified Rail 1 of the gas leak at E99 [Phone/ MOC]
02:35:21 hours	<u>Unidentified Caller:</u> Advised the meter outside was broken, and Baltimore Gas Company was aware of the broken meter. It was reported that PGFD previously shut off gas to the meter. <u>MOC Controller:</u> Acknowledged and advised that PGFD & plumbers are still headed to check the gas leak. [Phone/ MOC]
03:09:16 hours	<u>CMNT Supervisor:</u> Reported PGFD has cleared the scene, and personnel is returning to the building. The gas leak was deemed a maintenance issue and awaiting the arrival of Washington Gas. <u>MAC:</u> Acknowledged. [Phone/ MAC]
03:19:43 hours	MOC Controller: Confirmed a gas leak was detected, and PGFD shut the gas off. [Phone/ MOC]

Note: Times above may vary from other systems' timelines based on clock settings.

Interview Findings

As part of the investigation launched into the event, SAFE informally interviewed one person. The interview identified the following key findings associated with this event. Findings detailed below include reported information from involved personnel and may conflict with other data sources in the report.

- The smell of gas was outside of the S&I building only.
- The CMNT Electrician reported the smell of gas to the CMNT Supervisor.

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons E23266

Weather

On April 18, 2023, at the time of the incident, NOAA recorded the temperature as 61° F. Weather was not a contributing factor in this incident (Weather source: NOAA) – Location: [Greenbelt, MD].

Related Rules and Procedures

SOP #503.01 – Greenbelt Building B Safety and Emergency Procedures

Human Factors

Evidence of Fatigue

The biomathematical fatigue modeling application (SAFTE-FAST Web SFC) was not applied for this event.

Fatigue Risk

The biomathematical fatigue modeling application (SAFTE-FAST Web SFC) was not applied for this event.

Post-Incident Toxicology Testing

This incident did not meet the criteria for WMATA's Drug and Alcohol Policy and Testing Program 7.7.3/6.

Findings

- PGFD located the leaking gas meter on the exterior of Building B (S&I shop) and shut off the source of the leak.
- Washington Gas determined that the source of the leak was a defective regulator.
- A previous report of a gas leak was reported on 4/13/2023 (WO#1785063) and scheduled for repair on 4/18/2023.

<u>Immediate Mitigation to Prevent Recurrence</u>

- PGFD was dispatched and identified the gas leak source, shutting the gas off.
- PLNT Plumber was dispatched to identify the gas leak using a gas leak detector. Washington Gas responded the following day with PLNT personnel.

Probable Cause Statement

The probable cause of the Evacuation for Life Safety Reasons (Gas Leak) event was determined to be a gas leak from the gas regulator located on the external portion of Building B.

Recommended Corrective Actions

There were no Recommended Corrective Actions related to the emergency response and evacuation for this event.

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons E23266

Reviewed By: SAFE 704 – 06/15/2023 Approved By: SAFE71 – 06/20/2023

SAFE 710 - 06/13/2023

Drafted By:

Appendices

Appendix A - Photographs





Image 4 - Front View of Leaking Gas Meter on Exterior of Building B (S&I Shop)

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons

E23266



Washington Metropolitan Area Transit Authority Maintenance and Material Management System PLNT Work Order Details Report

Page 1 of 3 MX76PROI

Work Order #: 04/19/2023 08:47 17813373 Type: CM Status: COMP Work Description: 17813373: E93 SUPERVISOR REPORTS SMELL OF GAS Job Plan Description: Work Information PLPLMWS4 PLNT, PLUMBING, PIPING/ VALVES/ FILTERS, RAIL Shop Code: PLBM-PLM2 Parent Alias: PIPES VAL2 Maint. Office: PLNT-BMSS-PLM2 Create Date: 4/18/2023 02:41 Asset Tag: GREENBELT YARD BLDG G S&I ANNEX/ MRO/SR251 Facility Loc: E93 Labor Group: PLNT-BMSS-PLM2 Act Start: 4/19/2023 08:47 E93, GREENBELT YARD, BUILDING (G) S&I ANNEX/MRO/SR251 Location: 14089 Act Comp: 4/19/2023 08:47 STATION PLUMBING GL Account: WMATA-02-31520-50499160-042-Failure Class: PLNT015 Target Start: Problem Code: Target Comp: Requested By: Request Phone: Sched Start: Task ID Labor Start Date **End Date** Start Time **End Time** Approved? Hours Hours 4/18/23 08:00 00:00 \$374.63 \$164.71 03:30 00:00 Total Actual Labor: \$539.34 WO Description Class Status Relationship 17805063 E93 SUPERVISOR REPORTS SMELL OF GAS WORKORDER COMP RELATED

WT_plust_woprintP.rptdesign 05/2/2023 09:22

Class

Status

Relationship

Image 5 - Completed Work Order for Gas Leak page 1 of 3.

Description

E93 SUPERVISOR REPORTS SMELL OF GAS

Ticket

Drafted By: SAFE 710 - 06/13/2023 Reviewed By: SAFE 704 - 06/15/2023 Approved By: SAFE71 - 06/20/2023



Washington Metropolitan Area Transit Authority Maintenance and Material Management System

Page 2 of 3 MX76PROD

SA > Escotted Washington Gas for diaphragin repair. Washington Gas wants to replace the gas manifold feeding the S&i. They need to know the gas load for the building (total BTUs of gas fixtures).

PLNT Work Order Details Report

04/19/2023 08:47 Work Order #: 17813373 Type: CM Status: COMP Work Description: 17813373: E93 SUPERVISOR REPORTS SMELL OF GAS Job Plan Description: Long Description

op class="MsoNormal" style="margin-bottom:
8 (bt_background:white">~span
class="contentpasted(")~sp>~span style="fontsize:14.0pt_color:black">~span
style="fontsize:14.0pt_color:black">~span
style="fontsize:14.0pt_color:black">~span
style="fontsize:14.0pt_color:black">~span
style="fontsize:15.0pt_size: Date Class Created By Subject Description Long Description 4/19/23 WORKORDER E015815 04/7/23 See Details 4/19/23 WORKORDER E973447 Escorted Washington Gas for diaphragm repair. Escorted Washington Gas for diaphragm senari

WT_plust_woprintP.rptdesign 05/2/2023 09:22

Image 6 - Completed Work Order for Gas Leak page 2 of 3.

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons

E23266

Drafted By: SAFE 710 - 06/13/2023 Reviewed By: SAFE 704 - 06/15/2023 Approved By: SAFE71 - 06/20/2023



Washington Metropolitan Area Transit Authority Maintenance and Material Management System PLNT Work Order Details Report

Page 3 of 3 MX76PROD

Work Order #: 17813373 Status: COMP

04/19/2023 08:47 Type: CM

Date	0.1				
	Class	Created By	Subject	Description	Long Description
4/19/23		MAXADMIN	Maximo WO# 17813373 has been resolved	>div> >br/>Thank you for contacting MOC. Work Order #17813373 reported to MOC has been resolved. div> ⟨div> ⟨div> ⟨br/>P/Work Order Description: E93 SUPERVISOR REPORTS SMELL OF GAS br/>br/>br/>br/>P ¬br/>br/>P ¬br/>P <	
4/18/23		MAXADMIN	Maximo WO# 17813373 has been opened by MOC	<p>Thank you for contacting MOC. Work Order #17813373 has been opened to resolve the following reported issue, <div>Work Order Description: E93 SUPERVISOR REPORTS SMELL OF GAS-of /> <</br></br></br></br></div></p>	

WT_plust_woprintP.rptdesign 05/2/2023 09:22

Image 7 - Completed Work Order for Gas Leak page 3 of 3.

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons E23266

Drafted By: SAFE 710 - 06/13/2023 Reviewed By: SAFE 704 - 06/15/2023 Approved By: SAFE71 - 06/20/2023



Washington Metropolitan Area Transit Authority Maintenance and Material Management System Work Order Details

MX76PROD

Status: CLOSE 05/09/2023 13:17



Work Description: E93 SUPERVISOR REPORTS SMELL OF GAS Job Plan Description:

Work Information Asset: PLNTE93 E93, PLNT YARD EQUIPMENT, GREENBELT YARD TRST FIELD BASE Owning Office: Parent: Maintenance Office: PLNT Create Date: 04/13/2023 22:38 Asset Tag: Labor Group: PLNT-BMSS-PLM1 Actual Start: 04/14/2023 04:50 Asset S/N: Location: 14089 E93, GREENBELT YARD, BUILDING (G) S&I ANNEX/MRO/SR251 Actual Comp: 04/18/2023 05:58 Work Location: Lead: PLBM-PLM1 GL Account: WMATA-02-31520-50499950-042-******-****-OPR** Failure Class: Problem Code: Supervisor: Target Start: Requested By: Requestor Phone Target Comp: Chain Mark End: Scheduled Start: Chain Mark Start: Create-Mileage: 0.0 Complete-Mileage: 0.0 Regular Hours Premium Hours Task ID Labor Start Date End Date Start Time Line Cost 02:00 00:00 \$91.82 04/13/2023 \$91.82 Total Actual Hour/Labor: \$183.64 Description Class E93 SUPERVISOR REPORTS SMELL OF GAS SR RELATED Relationship Description 17813373 E93 SUPERVISOR REPORTS SMELL OF GAS WORKORDER CLOSE RELATED Cause Remedy Supervisor Remark Date Remarks

WT_plust_woprint.rptdesign 08/26/2023 16:28

Drafted By:

Approved By: SAFE71 - 06/20/2023

Image 8 - 4/13/2023 - Work Order for Gas Leak page 1 of 1.

Appendix C – CMNT Fire Drill Exercise Form

CMNT FIRE DRILL EXERCISE FORM

	Il Conducted:			Drill Commence m. I	ΔM	Time Re	53	vacuate Build	ling: Date	of this Report:	2 023
Department	Notified? Y	es(x) No) ()	Did Alarms w		Yes (_X)	No ()	Were Sprink	klers Tested?	Number of pa exercise: 14	articipants in
Fire Warden: Camille Dell/Bissessar Gjock (Usually Division Superintendent)		Assistant Fire Warden: L SANDERS/M.SHAW (OPER Supt)			Fire Drill Coordinator: L.SANDERS/M.SHAW		Time Fire Drill Ended: 3:00 AM Hr				
10 × 20 × 10 × 10 × 10 × 10 × 10 × 10 ×	A CONTRACTOR OF THE	in the	U4-00-000 - 20	Fire Ev	acuation	Coordin	nators:	MANUAL MANUAL			
Station 1	Station 2	Station 3	Station 4	Station 5	Statio	on 6	Station 7	Station8	Station 9	Station 10	Station 11
1st FLOOR	2nd floor	ANNEX H BUILDING									
SANDERS	SHAW	N/A									
		I I				T					
Positives: <i>L</i>	ist items that	went correctly	c _	DI	BRIEF	FING:	3				
		went correctly	- 8	DI	EBRIEF	FING:	5				20
All personnel	evacuated ii	n FIVE minute	es								
All personnel	evacuated ii	n FIVE minute	es	Di or areas of imp							
All personnel	evacuated ii	n FIVE minute	es								
All personnel	evacuated ii	n FIVE minute	es								

This form is proprietary to the Washington Metropolitan Area Transit Authority (WMATA). No reproduction is allowed without prior consent.

Image 9 - CMNT Fire Drill Exercise Form

Incident Date: 04/18/2023 Time: 02:29 hours Final Report – Evacaution for Life Safety Reasons E23266

Drafted By: SAFE 710 - 06/13/2023 Reviewed By: SAFE 704 - 06/15/2023 Approved By: SAFE71 - 06/20/2023