

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Damant Namehan	20230918-WMSC-LBW-1			
Inspection Date	2023/09/18	Report Number				
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name			
Rail Agency Department	RTRA	Contact Information				
Inspection Location	WMSC Office	•				

Inspection Summary

Inspection Activity #	1
Activity Code	RR-RTRA-QAI
Inspection Units	1
Inspection Subunits	0
Defects (Number)	3
Recommended Finding	Yes
Remedial Action Required ¹	No
Recommended Reinspection	Yes

Activity Summaries

located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are	Inspection Activity #	1 Inspection Subject Rail Transportation QA/O Document Review						tification	Activity Code			RR-RTRA-QAI				
Related Reports Investigation W-0232 (Adopted) Ref Rule or SOP Standard Other / Title Checklist Refe NA NA NA NA Inspection Location Inspection Location Inspection Location WMSC Office Chain Marker and/or Station(s) WMSC Office Chain Marker and/or Station(s) Tack Number Vehicles The WMSC Inspectors conducted an unannounced Quality Assurance/ Quality Control (QA/QC) certification records inspection at the Carmen Turner Training Facility (CTF) located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are	Employee	NA			Accompanied Inspector?			No	0 000 = 1100	No	No Time				No	
SOPs, Standards, or Other Inspection Location Main Track Yard Station OCC RTA Facility WMSC Office X Line(s) & Track Number WMSC Office Chain Marker and/or Station(s) Head Car Number Number of Cars NA NA The WMSC Inspectors conducted an unannounced Quality Assurance/ Quality Control (QA/QC) certification records inspection at the Carmen Turner Training Facility (CTF) located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 abut of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are	Related Reports	Investigation		Related CAPS / Findings NA			NA									
SOPs, Standards, or Other NA NA NA NA NA NA NA NA NA N	Related Rules.	Ref		Rule	or SOP			Standard		Other / Title Checklis					st Reference	
Inspection Location Track Yard Station OCC RTA Facility Office Track Type At-grade Tunnel Elevated Tunnel To NA NA Vehicles To NA NA NA Requipment NA NA The WMSC Inspectors conducted an unannounced Quality Assurance/ Quality Control (QA/QC) certification records inspection at the Carmen Turner Training Facility (CTF) located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are	SOPs, Standards, or				NA NA			NA		NA			NA			
Line(s) & Track Number WMSC Office Chain Marker and/or Station(s) From To	Inspection Location		Yard	Station	осс						At-grade Tunne		el E	levated	N/A	
Number Namber Number Number of Cars Equipment Namber of Cars						Х	(
Vehicles Head Car Number Number of Cars NA NA NA NA NA NA NA N		WMSC Office	WMSC Office Chain Marker and for Station(s)							From				То		
The WMSC Inspectors conducted an unannounced Quality Assurance/ Quality Control (QA/QC) certification records inspection at the Carmen Turner Training Facility (CTF) located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are	Number	NA NA						NA								
The WMSC Inspectors conducted an unannounced Quality Assurance/ Quality Control (QA/QC) certification records inspection at the Carmen Turner Training Facility (CTF) located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are	Vahicles	Head Car	Number	N				ont	NΔ							
(QA/QC) certification records inspection at the Carmen Turner Training Facility (CTF) located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are	Verificies	N/	A		NA		Equipin	ieiit	NA .							
located in Landover, Maryland. The inspectors requested the training records for Train Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are		(QA/QC) certification records inspection at the Carmen Turner Training Facility (CTF)								Number of Defects					3	
Operator (TO) 23-07 to perform a certification records review. This inspection is a follow up to inspection report 20230823-WMSC-LBW-1 and adopted report W-0232 where a train operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are										Recommended Finding?					Yes	
operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are											Remedial Action Required?				No	
passing all required tasks as outlined in the Performance Standardization Manual. The certification records review of TO Class 23-07 covered 19 train operators with 28 separate certification records being reviewed during this inspection. 84% or 16 out of the 19 train operator records reviewed were completed in accordance with the Performance Standardization Manual. 16% or 3 out of 19 train operator records did not follow the Performance Standardization Manual. Examples of deviation include: - Certifications completed without the QA certifier including the required time - Train Operators passing a second certification without passing all required tasks as outlined in the Performance Standardization Manual. A further review additional certification records is recommended.	Description	operator moved against the normal flow of traffic without permission or protection and radio communications did not include 100% repeat back. In the above referenced WMSC report on Rail Class 23-06, 52% or 14 out of 27 train operator records did not follow the Performance Standardization Manual. The practical examination phase of the Primary Qualification Examination is constructed to gauge the train operator examinees' proficiency in every aspect of train operations. Report 20230823-WMSC-LBW-1 identified that train operator certification is concluded without documenting student operators are passing all required tasks as outlined in the Performance Standardization Manual. The certification records reviewed during this inspection. 84% or 16 out of the 19 train operator records being reviewed during this inspection. 84% or 16 out of the 19 train operator records reviewed were completed in accordance with the Performance Standardization Manual. 16% or 3 out of 19 train operator records did not follow the Performance Standardization Manual. Examples of deviation include: - Certifications completed without the QA certifier including the required time - Train Operators passing a second certification without passing all required tasks as outlined in the Performance Standardization Manual. A further review additional certification records is								Yes						

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2023/09/18
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team Darrell Braxton	



Inspection Form

Form WMSC-IR-1