

**Inspection Form** 

## Washington Metrorail Safety Commission

## Agency/Department Information

Inspection Date	YYYY/MM/DD	Depart Number	20231018-WMSC-MAL-1						
inspection Date	2023/11/12	Report Number							
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name						
Rail Agency Department	CMNT	Contact Information							
Inspection Location	Greenbelt S&I Shop - Railyard E99 5801 Sunnyside Av	nbelt S&I Shop - Railyard E99 5801 Sunnyside Ave, College Park, MD 20740							
Inspection Summary									
Inspection Activity #		1							
Activity Code		VM-WI-PI							
Inspection Units		1							
Inspection Subunits	1								
Defects (Number)	3								
Recommended Finding	Yes								

No

No

## **Activity Summaries**

Remedial Action Required<sup>1</sup> Recommended Reinspection

Inspection Activity #	1	Insp	ection Sub	oject	Observation 7K Wheel Boring Process				Activity Code			VM-WI-PI					
Job Briefing Employee Name/Title	WMATA Insp	ection		Accompan	ied Inspecto	or?	No	Out Brief Conducted	Time 07:			07:3	60 AM	Outside Shift	No		
Related Reports	N/A			Related C/	APS / Findin	gs		N/A									
	Ref Rule			e or SOP		Standard	Standard		Other / Title			Checklist Reference					
Related Rules, SOPs, Standards, or Other	METRORAIL OPERATING RULEBOOK FIRST EDITION Effective: Sept 1, 2023, Safety Rules			4		N/A		N/A				N/A					
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunnel		l Elevat		ted	N/A			
		х													Х		
Line(s) & Track Number	Greenbelt S& Sunnyside Av		,		Chain Ma	irker and/	or Station(s)	N/A	From N/A			٦	То				
Maltala.	Head Car Number			lumber of Cars													
Vehicles	N/A			N/A	Equipment			N/A									
	WMSC Inspectors conducted a rules compliance inspection of the wheelset assembly							Number of Defects					3	5			
	process at the Greenbelt S&I Shop for compliance with the Metrorail Operating Rule and Procedures Handbook (MOR), including Preventive Maintenance Inspections (PI)								Recommended Finding?					Ye	Yes		
	activities. General Information: WMSC met with personnel from Greenbelt's truck shop,									Remedial Action Required?				No			
Description	and personnel from CMOR quality assurance group during the boring process. The wheel boring machine's operator took the lead in going through the process from the start when the wheel is received, cleaned, checked, bored, marked, data sheets completed, and prepared ready for transportation to the desired location. The following observations were noted. Went through the boring process of one wheel. The boring machine requires highly skilled operators to properly operate the machine. Four mechanics have been trained to operate the machine. Wheels are moved around with overhead cranes and forklifts. WMATA stated that they can bore six to eight wheels per day. The boring machine can produce an accuracy of plus or minus 4 ten thousandth of an inch (ű .0004 inch). CMOR QA oversaw the process. WMATA stated that wheels are not normally protected with an anti-rust coating, after being cut, since they get used immediately. A completed bored wheel with holes for the brake disk. See attached Photo #1.								0								
Remedial Action																	

<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

inspector in Charge's Signature	2023/11/12	
Inspector in Charge's Name	Inspection Team	
Manuel Lopez	No.	