

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY/MM/DD	Daniel Ministry	20240417-WMSC-MAL-1				
Inspection Date	2024/04/22	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name				
Rail Agency Department	CMNT	Contact Information					
Inspection Location	Brentwood S&I Shop - Railyard B99 601 T Street NE Washington DC 20002						

Inspection Summary

Inspection Activity #	1
Activity Code	VM-WI-PI
Inspection Units	1
Inspection Subunits	1
Defects (Number)	0
Recommended Finding	No
Remedial Action Required ¹	No
Recommended Reinspection	No

Activity Summaries

Name/Title Related Reports ETP 14 Ref Related Rules, SOPs, Standards, or Other NETR RULES Effect Safett	BOOK FIRST E tive: Sept 1, 2	TING	Rule	Related CA	ied Inspecto		No	Out Brief Conducted		Time		07.00		Outside		
Related Rules, SOPs, Standards, or Other RULE Effect Safet	RORAIL OPERA BOOK FIRST E tive: Sept 1, 2		Rule		PS / Finding			Conducted	Time		07:00 AM		Shift	No		
Related Rules, SOPs, Standards, or Other Effect Safet	BOOK FIRST E tive: Sept 1, 2		Rule			Related CAPS / Findings N/A										
SOPs, Standards, or Other Effect Safet	BOOK FIRST E tive: Sept 1, 2			e or SOP Standard				Other / Title				Checklist Reference				
	y Rules	METRORAIL OPERATING RULEBOOK FIRST EDITION Effective: Sept 1, 2023, Safety Rules		4			N/A	N/A		N/A			N/A			
	ain ack Yar		ation	осс	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		el Elevate		ted	N/A		
	Х													Х		
	twood S&I Sho	. ,		9 601 T	Chain Ma	Chain Marker and/or Station(s)			From				То			
	t NE Washing							N/A	N/A							
Vehicles	ad Car Numb	er	N	Number of Cars Equipme			ent	N/A								
Partio	N/A N/A N/A ' N/A						ess at the	Number of Defects						0		
Brent	Brentwood S&I Shop. Pulled axle 56477 from railcar 7258, and axle LRZ-576 from railcar									Recommended Finding?					lo	
	7259. Personnel from the Brentwood truck shop, CENV, CMOR, Quality assurance, and								Remedial Action Required?				N	No		
Description Description Description Description Description Description Meas With a on all whee #4F diame	WMSC were present. CMOR took the lead in the cleaning, measurement, and inspection process. The following observations were noted Inspections of the third set of 4 wheelsets per ETP 140134 at a 20,000 miles interval The wheels bore was cleaned with a rag The wheels bore, and axles had signs of damage from the de-mounting process. Hydraulic assist is not being used to demount the wheels. CENV engineering is working on a process to add hydraulic assist chamfers to new wheels in house to prevent wheel and axle damage during the de-mounting process The wheel bore diameter was then measured at three locations. Dimensions were compliant with the original measurements The wheel bore was then coated with a red die-penetrant spray, and they were set aside to sit for 30 minutes to allow this very thin die-penetrant fluid to go in any possible cracks After 30 minutes the die-penetrant is wiped clean with a rag. The die-penetrant will remain in any possible cracks. The wheel bore is then sprayed with a white developer spray to visually enhance any sign of cracks. None were detected on all four wheels WMSC noted the following diameters of the wheels based on the wheel size diameter written on the face of the wheel. See Attached Photos #1 through #4 Railcar 7258, axle 56477, - MS wheel 18220 diameter 27.975 - GS wheel 18273 diameter, 27.990, - Railcar 7259, axle LRZ-576, - MS wheel 17452, diameter 28.0 - GS wheel 17478, diameter 28.0						Recommended Reinspection?				N	lo				

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2024/04/22
Inspector in Charge's Name Manuel Lopez	Inspection Team N/A	