

# **Inspection Form**

Form WMSC-IR-1

Washington Metrorail Safety Commission

### Agency/Department Information

Inspection Date	YYYY/MM/DD	Donart Number	20240731-WMSC-DLB-1					
Inspection Date	2024/07/31	Report Number	ZUZ4U/31-WIVI3C-DLD-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	SAFE	Contact Information						
Inspection Location	Carmen E. Turner Maintenance and Training Facility (CTF)							

#### **Inspection Summary**

Inspection Activity #	1
Activity Code	QAI-TNG-OBS
Inspection Units	1
Inspection Subunits	0
Defects (Number)	0
Recommended Finding	No
Remedial Action Required <sup>1</sup>	No
Recommended Reinspection	Yes

### **Activity Summaries**

No	Inspection Activity #	1	Ins	pection Subj	ect	Verificati class (CR)		ction of cont	ractor RWP	Activity Code			QAI-TNG-OBS			
Relate Rules, SOPs, Standards, or Other / Title	Employee	N/A.	·		Accompan	ied Inspecto	or?	No		Yes	Yes Time 09:			0 AM	M I N O	
Related Rules, SOPs, Standards, or Other    Industry Safe Report 7520.   Procedure Number: 2710-3-01/01   N/A.   N/A.   N/A.   N/A.   N/A.	Related Reports			2024	Related C/	APS / Findin	ıgs		N/A.	•						
SoPs, Standards, or Other    Industry Safe Report 7520.   Procedure Number: 2710-3-01/01   N/A.   N/A.   N/A.   N/A.   N/A.	Deleted Dules	Ref		Rule	or SOP			Standard		Other /	Title			Check	ist Refe	rence
Inspection Location    Track   Yard   Station   OCC   RTA Facility   Office   Track Type   At-grade   Tune   Elevated   N/A	SOPs, Standards, or	Industry Safe Report 7520.			Contractor Worker Protection			N/A.	N/A.		N/A.			N/A.		
Carmen E. Turner Maintenance and Training Facility (CTF)   Station(s)   N/A.   N/A.   N/A.	Inspection Location		Yard	Station	occ	RTA F	acility		Track Type	At-g	At-grade Tunne		el	Elevated		N/A
Number   Training Facility (CTF)   Station(s)   N/A.   N/A.   N/A.						>	<b>K</b>									Х
PURPOSE: On Wednesday July 31, 2024, two WMSC Inspectors performed a follow up inspection of a Contractor Roadway Worker Protection (CRWP) class. The CRWP class was conducted at the Carmen Turner Training Facility (CTF) and was instructed by Metrorall SAFE personnel. This inspection was a follow up inspection to the original inspection conducted on Wednesday July 10, 2024 Industry Safe Report 7520. METHOD: The inspection used observations and discussion via questioning to obtain the information to substantiate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, 2024, inspection that required mitigation and verification: 1. The participants did not demonstrate the required proficiency or knowledge to safely cross over the third rail. Although there is an inside and outside track setup available for RWP testing at the Carmen Turner Training Facility (CTF), students completed the class without performing the required practical assessment. The practical for CRWP requires successful crossing of the third rail to pass the class and this did not occur. 2. Retesting occurred simultaneously while the class was being instructed. Participants were required to take the retest assessment unsupervised at tables in the hallway which was disruptive to the learners. 3. Two of the retesting students finished the retest in five minutes. The participants were told by the instructor that completing the test that quickly was not possible since he had designed the assessment might be compromised. Mitigations by Metrorall and verification by the WMSC Wednesday July 31, 2024: -Metrorail SAFE Department retrieved the mockup of the third rail and implemented its required used for the practical assessment protrino of the Contrator Roadway Worker Protection (CRWP) classRetest assessments were conducted at the conclusion of the class and took place inside of the classroom. This action by Metrorail removed the disruptive classroom environment and allowed for more effective and efficient vetting of re-testers. Ad	` '			ntenance ar	nd			or		From	1			То		
PURPOSE: On Wednesday July 31, 2024, two WMSC Inspectors performed a follow up inspection of a Contractor Roadway Worker Protection (CRWP) class. The CRWP class was conducted at the Carmen Turner Training Facility (CTF) and was instructed by Metrorall SAFE personnel. This inspection was a follow up inspection to the original inspection conducted on Wednesday July 10, 2024 Industry Safe Report 7520. METHOD: The Inspection used observations and discussion via questioning to obtain the information to substantiate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, 2024, inspection that required mitigation and verification: 1. The participants did not demonstrate the required proficiency or knowledge to safely cross over the third rail. Although there is an inside and outside track setup available for RWP testing at the Carmen Turner Training Facility (CTF), students completed the class without performing the required practical assessment. The practical for CRWP requires successful crossing of the third rail to pass the class and this did not occur. 2. Retesting occurred simultaneously while the class was being instructed. Participants were required to take the retest assessment unsupervised at tables in the hallway which was disruptive to the learners.  3. Two of the retesting students finished the retest in five minutes. The participants were told by the instructor that completing the test that quickly was not possible since he had designed the assessment. This suggests that cheating is occurring during the CRWP class, and the assessment might be compromised. Mitigations by Metrorall and verification by the WMSC Wednesday July 31,2024: -Metrorall SAFE Department retrieved the mockup of the third rail and implemented its required used for the practical assessment portion of the Contractor Roadway Worker Protection (CRWP) class Retest assessments were conducted at the conclusion of the class and took place inside of the classroom. This action by Metrorall removed the disruptive classroom	Number						)		N/A.				N/A.			
PURPOSE: On Wednesday July 31, 2024, two WMSC Inspectors performed a follow up inspection of a Contractor Roadway Worker Protection (CRWP) class. The CRWP class was conducted at the Carmen Turner Training Facility (CTF) and was instructed by Metrorail SAFE personnel. This inspection was a follow up inspection to the original inspection used observations and discussion via questioning to obtain the information to substantiate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, 2024, inspection that required mitigation and verification: 1. The participants did not demonstrate the required proficiency or knowledge to safely cross over the third rail. Although there is an inside and outside track setup available for RWP testing at the Carmen Turner Training Facility (CTF), students completed the class without performing the required practical assessment. The practical for CRWP requires successful crossing of the third rail to pass the class and this did not occur. 2. Retesting occurred simultaneously while the class was being instructed. Participants were required to take the retest assessment unsupervised at tables in the hallway which was disruptive to the learners.  3. Two of the retesting students finished the retest in five minutes. The participants were told by the instructor that completing the test that quickly was not possible since he had designed the assessment. This suggests that cheating is occurring during the CRWP class, and the assessment might be compromised. Mitigations by Metrorail and verification by the WMSC Wednesday July 31,2024: -Metrorail SAFE Department retrieved the mockup of the third rail and implemented its required used for the practical assessment portion of the Contractor Roadway Worker Protection (CRWP) class Retest assessments were conducted at the conclusion of the class and took place inside of the classroom. This action by Metrorail removed the disruptive classroom environment and allowed for more effective and efficient vetting of re-testers. Additi	Vehicles	Head Car	Number	N		Cars	Equipm	ent	N/A.							
inspection of a Contractor Roadway Worker Protection (CRWP) class. The CRWP class was conducted at the Carmen Turner Training Facility (CTF) and was instructed by Metrorall SAFE personnel. This inspection was a follow up inspection to the original inspection conducted on Wednesday July 10, 2024 Industry Safe Report 7520. METHOD: The inspection used observations and discussion via questioning to obtain the information to substantiate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, 2024, inspection that required mitigation and verification: 1. The participants did not demonstrate the required proficiency or knowledge to safely cross over the third rail. Although there is an inside and outside track setup available for RWP testing at the Carmen Turner Training Facility (CTF), students completed the class without performing the required practical assessment. The practical for CRWP requires successful crossing of the third rail to pass the class and this did not occur. 2. Retesting occurred simultaneously while the class was being instructed. Participants were required to take the retest assessment unsupervised at tables in the hallway which was disruptive to the learners. 3. Two of the retesting students finished the retest in five minutes. The participants were told by the instructor that completing the test that quickly was not possible since he had designed the assessment. This suggests that cheating is occurring during the CRWP class, and the assessment might be compromised. Mitigations by Metrorail and verification by the WMSC Wednesday July 31, 2024: -Metrorail SAFE Department retrieved the mockup of the third rail and implemented its required used for the practical assessment portion of the Contractor Roadway Worker Protection (CRWP) class Retest assessments were conducted at the conclusion of the class and took place inside of the classroom related activities in		DUBBOCE O				1/11/16/6/1			<u> </u>						_	
conducted at the Carmen Turner Training Facility (CTF) and was instructed by Metrorail SAFE personnel. This inspection was a follow up inspection to the original inspection conducted on Wednesday July 10, 2024 Industry Safe Report 7520. METHOD: The inspection used observations and discussion via questioning to obtain the information to substantiate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, 2024, inspection that required mitigation and verification: 1. The participants did not demonstrate the required proficiency or knowledge to safely cross over the third rail. Although there is an inside and outside track setup available for RWP testing at the Carmen Turner Training Facility (CTF), students completed the class without performing the required practical assessment. The practical for CRWP requires successful crossing of the third rail to pass the class and this did not occur. 2. Retesting occurred simultaneously while the class was being instructed. Participants were required to take the retest assessment unsupervised at tables in the hallway which was disruptive to the learners.  3. Two of the retesting students finished the retest in five minutes. The participants were told by the instructor that completing the test that quickly was not possible since he had designed the assessment. This suggests that cheating is occurring during the CRWP class, and the assessment might be compromised. Mitigations by Metrorail and verification by the WMSC Wednesday July 31, 2024: -Metrorail SAFE Department retrieved the mockup of the third rail and implemented its required used for the practical assessment portion of the Contractor Roadway Worker Protection (CRWP) class Retest assessments were conducted at the conclusion of the class and took place inside of the classroom. This action by Metrorail removed the disruptive classroom environment and allowed for more effective and efficient vetting of re-testers. Additionally, removal of classroom related activities in																
conducted on Wednesday July 10, 2024 Industry Safe Report 7520. METHOD: The inspection used observations and discussion via questioning to obtain the information to substantiate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, 2024, inspection that required mitigation and verification: 1. The participants did not demonstrate the required proficiency or knowledge to safely cross over the third rail. Although there is an inside and outside track setup available for RWP testing at the Carmen Turner Training Facility (CTF), students completed the class without performing the required practical assessment. The practical for CRWP requires successful crossing of the third rail to pass the class and this did not occur. 2. Retesting occurred simultaneously while the class was being instructed. Participants were required to take the retest assessment unsupervised at tables in the hallway which was disruptive to the learners.  3. Two of the retesting students finished the retest in five minutes. The participants were told by the instructor that completing the test that quickly was not possible since he had designed the assessment. This suggests that cheating is occurring during the CRWP class, and the assessment might be compromised. Mitigations by Metrorail and verification by the WMSC Wednesday July 31,2024: -Metrorail SAFE Department retrieved the mockup of the third rail and implemented its required used for the practical assessment portion of the Contractor Roadway Worker Protection (CRWP) class Retest assessments were conducted at the conclusion of the class and took place inside of the classroom. This action by Metrorail removed the disruptive classroom environment and allowed for more effective and efficient vetting of re-testers. Additionally, removal of classroom related activities in		conducted a	at the Carm	en Turner T	raining Fa	cility (CTF)	and was	instructed by	y Metrorail							
used observations and discussion via questioning to obtain the information to substantiate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, 2024, inspection that required mitigation and verification: 1. The participants did not demonstrate the required proficiency or knowledge to safely cross over the third rail. Although there is an inside and outside track setup available for RWP testing at the Carmen Turner Training Facility (CTF), students completed the class without performing the required practical assessment. The practical for CRWP requires successful crossing of the third rail to pass the class and this did not occur. 2. Retesting occurred simultaneously while the class was being instructed. Participants were required to take the retest assessment unsupervised at tables in the hallway which was disruptive to the learners.  3. Two of the retesting students finished the retest in five minutes. The participants were told by the instructor that completing the test that quickly was not possible since he had designed the assessment. This suggests that cheating is occurring during the CRWP class, and the assessment might be compromised. Mitigations by Metrorail and verification by the WMSC Wednesday July 31,2024: -Metrorail SAFE Department retrieved the mockup of the third rail and implemented its required used for the practical assessment portion of the Contractor Roadway Worker Protection (CRWP) class Retest assessments were conducted at the conclusion of the class and took place inside of the classroom. This action by Metrorail removed the disruptive classroom environment and allowed for more effective and efficient vetting of re-testers. Additionally, removal of classroom related activities in		•							•	Kemediai	Action Re	quirear			I I	10
		used observables and observabl	iate all findings. Observations (Issues/Concerns) from initial Wednesday July 10, pection that required mitigation and verification: 1. The participants did not rate the required proficiency or knowledge to safely cross over the third rail. There is an inside and outside track setup available for RWP testing at the Furner Training Facility (CTF), students completed the class without performing the practical assessment. The practical for CRWP requires successful crossing of the to pass the class and this did not occur. 2. Retesting occurred simultaneously class was being instructed. Participants were required to take the retest ent unsupervised at tables in the hallway which was disruptive to the learners. If the retesting students finished the retest in five minutes. The participants were instructor that completing the test that quickly was not possible since he had the assessment. This suggests that cheating is occurring during the CRWP class, assessment might be compromised. Mitigations by Metrorail and verification by C Wednesday July 31,2024: -Metrorail SAFE Department retrieved the mockup of rail and implemented its required used for the practical assessment portion of the or Roadway Worker Protection (CRWP) class Retest assessments were conducted inclusion of the class and took place inside of the classroom. This action by I removed the disruptive classroom environment and allowed for more effective ient vetting of re-testers. Additionally, removal of classroom related activities in					Yes								
Remedial Action																



# **Inspection Form**

Form WMSC-IR-1
Washington Metrorail Safety Commission

Photos:





The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action. C	Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.							
Inspect	or in Charge's Signature	Date 2024/07/31						
Inspect	or in Charge's Name	Inspection Team						
Darrell	Braxton	Bruce Walker						