

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200116-WMATA-TKS-1					
inspection Date	2020	01	16	Report Number	20200116-WWATA-TK3-1					
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	TRPM	Sub- Dep				
Rail Agency Department Contact Information		Name		Email	Office Phone	Office Phone		Mobile Phone		
Inspection Location	K-Line. Track	1. between K	1 326+00 and F	ast Falls Church (K05)						

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-WI-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summary

Inspection Activity #	1	Inspec	ction Sub	ject	Cable Inspection Observation			Activity Co	Code TP		P	WI	OBS				
Job Briefing Employee Name/Title	WMATA RWIC				Accompanied Inspector?		Yes	Out Brief Conducted	Yes	Time	100 140	-	Outside Shift	No			
Related Reports	N/A				R	Related CAPS / Findings N/A											
	Ref Rule or			or SOP	SOP Standard			Other / Title		Checklis		klist Refe	list Reference				
Related Rules, SOPs, Standards, or Other	RWPM R-17-			-02			DD-TP-SSI-013										
Standards, or Guile.	MSRF	PH			R-17	-03											
Inspection Location	Mai Trac		Yard	Sta	tion	occ	;	RTA Facility	WMSC Office	Track Type	At-grade	e Tu	Tunnel		vated	N/A	
inspection Location	X									тгаск туре	х						
Line(s)	K-Line	e	Track		1			hain Ma			From				То		
(-7			Numb	er	and/or Station(s) K1 326+00				East Falls Church (K05)				5)				
Vehicles	Head Car Number Number of Cars					N/A											
venicies	N/A N/A Equipment N/A																
	WMSC inspector received a job safety briefing from the roadway worker in charge							Number of Defects					0				
	•	(RWIC) at Ballston (KO4) prior to entering the roadway. The briefing covered the type of on-track protection, the working limits, where to clear, known hazards and hotspots, the safety rule of the day, the location of the nearest hospital, and								Recommended Finding?					No		
										Remedial Action Required?					No		
Description	a check of personal protective equipment (PPE) and roadway worker protection (RWP) ID. The WMSC inspector did not note any defects with the Job Safety Briefing. Recommended Reinspection?								No								

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	WMSC inspector observed WMATA employees perform a cable inspection on track 1 of K-Line, between K1 326+00 and East Falls Church (K05). Inspector also inspected cable, third rail, and track infrastructure conditions. The WMSC inspector did not note any defects.	
Remedial Action	N/A	

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature		Date
Inspector in Charge — Name Tino Sahoo	Inspection Team Tino Sahoo	

Form WMSC-IR-1 Version date: 10/5/18

2