



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20202301-WMATA-JMW		
	2020	01	23				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	WMATA	Sub- Department	TRST
Rail Agency Department Contact Information	Name		Email	Office Phone		Mobile Phone	
	██████████ ██████████		██████████ ██████████	██████████		██████████ ██████████	
Inspection Location	A Line track #1 between CM A1 304+00+/- to CM A1 389+00+/-.						

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TRK-OBS-WI					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	NO					
Remedial Action Required¹	NO					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1	Inspection Subject	Insulator/Tunnel Leak Inspection				Activity Code		TRK	OBS	WI
Job Briefing Employee Name/Title	WMATA RWIC/Compliance Group			Accompanied Inspector?	YES	Out Brief Conducted	YES	Time	2200-0400	Outside Shift	YES
Related Reports	N/A			Related CAPS / Findings		FTA 17-1-12 (Track Bed Cleaning) FTA 17-1-17 (Insulator Cleaning/Installation)					
Related Rules, SOPs, Standards, or Other	Ref		Rule or SOP		Standard		Other / Title		Checklist Reference		
	RWPM		SR 4.59								
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
	X								X		
Line(s)	A	Track Number	1	Chain Marker and/or Station(s)		From		To			
Vehicles	Head Car Number		Number of Cars		Equipment		N/A				
	N/A		N/A								
Description								Number of Defects	0		



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	<p>WMSC personnel under the protection of a WMATA RWIC, continued a series of track inspections in regards to arcing insulators, CAP FTA 17-1-12 and CAP FTA 17-1-17. The inspection performed on January 23rd, 2020, took place on the A Line track #1 between CM A1 304+00+/- to CM A1 389+00+/-.</p> <p>Notable Observations:</p> <ol style="list-style-type: none"> 1. Due to a scheduled radio outage, passenger trains, personnel, and crews working underground work expedited or permitted from working on the right of way. 2. Metrorail stated this activity was planned for weeks and that all departments were aware of this activity taken place. 	Recommended Finding?	NO
		Remedial Action Required?	NO
		Recommended Reinspection?	NO
Remedial Action			
Effective Practices			

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature Jemayne M Walker		Date
		1/23/2020
Inspector in Charge – Name	Inspection Team	
Jemayne M Walker	Jemayne M Walker WMATA Inspections	



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission
