

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20202901-WMATA-JMW				
Inspection Date	2020	29	01	Report Number	ZUZUZJUI-VVIVIATA-JIVIVV				
Rail Agency Name	Washington Metropolitan Area Transi Authority			Rail Agency Department WMATA Sub- Department		partment	TRST		
		Name		Email	Office Phone	e	N	Mobile Phone	
Rail Agency Department Contact Information									
Inspection Location	A Line track #2 between CM A2 443+00+/- to CM A2 395+07+/								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TRK-OBS-WI					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	YES					
Remedial Action Required ¹	NO					
Recommended Reinspection	NO					

Activity Summaries

Inspection Activity #	1	Inspection Sul	oject	Insulator/Tunnel Leak Inspection			Activity Co	ode TR		K	OBS	WI		
Job Briefing Employee Name/Title	WMATA RWIC/Compliance Group				mpanied ector?	· YES		YES	Time	220 040		Outside Shift	YES	
Related Reports	N/A				Related CAPS / Findings FTA 17-1-12 (Cleaning/Insta			Track Bed Cleaning) FTA 17-1-17 (Insulator allation)						
	Ref Rule or			Rule or	SOP Standard			Other / Title			Checklist Reference			
Related Rules, SOPs,	RWPM SR 4			SR 4.70	70 "plugs"									
Standards, or Other	TRST 1000 OPS 1			OPS 1	1									
	Main Track	I Yard	Station		осс	RTA Facility	WMSC Office	- 1-	At-grade	e Tu	nnel	Ele	vated	N/A
Inspection Location	х							Track Type			х			
12	,	Track			2 Chain Marker and/or Station(s)		From			То				
Line(s)	Α	Numb	er	2			ation(s)	A2 443+00+/-	-	A2 395+07+/-		· / -		
	Head Car Number			Number of Cars										
Vehicles	N/A			N/A				N/A						
Description									Number	of Defect	s			0

Form WMSC-IR-1 Version date: 10/5/18




Form WMSC-IR-1

Washington Metrorail Safety Commission

	WMSC personnel under the protection of a WMATA RWIC, continued a series of	Recommended Finding?						
	track inspections in regards to arcing insulators, CAP FTA 17-1-12 and CAP FTA 17- 1-17. The inspection performed on January 29 th , 2020, took place on the A Line	Remedial Action Required?	NO					
	track #2 between CM A2 443+00+/- to CM A2 395+07+/ Notable Observations: 1. Various leaks around the switches, debris and mud around CM A2 443+70+/-	Recommended Reinspection?	NO					
Remedial Action	After inspection there were a few noticeable leaks on the switch at CM A2 443+70+/-							
Effective Practices								

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature Jer	Date	
		2/18/2020
Inspector in Charge – Name	Inspection Team Jemayne M Walker	
Jemayne M Walker	WMATA Inspections	



Form WMSC-IR-1 Version date: 10/5/18



Form WMSC-IR-1

Washington Metrorail Safety Commission



Form WMSC-IR-1 Version date: 10/5/18

3



Form WMSC-IR-1

Washington Metrorail Safety Commission



Form WMSC-IR-1 Version date: 10/5/18

4



Form WMSC-IR-1

Washington Metrorail Safety Commission



Form WMSC-IR-1 Version date: 10/5/18

5