

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200E17 WMATA TVS 1					
inspection Date	2020	05	17	Report Number	20200517-WMATA-TKS-1					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRPM	Sub- Dep				
	ı	Name		Email Office Phone		e	Mobile Phone			
Rail Agency Department Contact Information]								
Inspection Location	E-Line, Gree	nbelt Yard (E9	9)							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-GEN-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summary

Inspection Activity #	1	Inspec	tion Sub	ject	Virtual Inspection – Battery Room PMI					Activity Co	de	TP		GEN	OBS	
Job Briefing Employee Name/Title	WMATA TRPM Personnel				Accompanied Inspector?		N/A	Out Brief Conducted	N/A	Time	100 140	-	Outside Shift	No		
Related Reports	N/A				Rela	Related CAPS / Findings N/A										
	Ref			Rule or SOP				Standard	Other / Title			Checklist Reference				
Related Rules, SOPs, Standards, or Other																
	MSRPI	Н														
Inspection Location	Main Track	1	Yard	Stati	ion	осс	RTA Facility		WMSC Office	Track Type	At-grade Tunne		nnel	nel Elevate		N/A
			x							тгаск туре						х
Line(s)	E-Line		Track		N/A		Cha	ain Maı	ker		From			То		
Line(s)	Number		er	14/7	•	and/or St		ation(s)	Greenbelt Yar	rd AC Room (E100) Green			nbelt Y	nbelt Yard AC Room (E100)		
Vehicles	Head Car Number			ı	Number of Cars		Equipment		A1/A							
Vehicles	N/A				N/A				nent	N/A						
Description	WMSC inspector performed a virtu									iefing via	Number of Defects					0
	Traction Power Maintenance's (TRP					RPM) job s	И) job safety briefing forms.				Recommended Finding?					No
	The W	MSC in	spector	did no	ot note	any defe	ects v	with the	Job Safety	Briefing.	Remedial Action Required			ed?		No
		The WMSC inspector did not note any defects with the Job Safety Briefing. Remedial Recomme								ended Re	ided Reinspection?			No		

Form WMSC-IR-1 Version date: 10/5/18

1



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	WMSC inspector performed a virtual inspection of the battery room PMI conducted at Greenbelt Yard AC Room (E100) via test sheets provided by TRPM. The WMSC inspector did not note any defects.	
Remedial Action	N/A	

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

are sufficient and effective.							
Inspector in Charge - Signature	Date						
Inspector in Charge – Name	Inspection Team						
Tino Sahoo	Tino Sahoo						
1							

Form WMSC-IR-1 Version date: 10/5/18