

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200714-WMATA-LBW-1				
inspection date	2020	07	14	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Operations Sub- Department		Stations		
	1	Name		Email	Office Phone		Mobile Phone		
Rail Agency Department Contact Information									
Contact Information									
Inspection Location	Grosvenor - Strathmore (A011)								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	RTRA-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	4					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1 Inspection Statio			on Assessment - Grosvenor - Strathmore				Activity Code		RTRA		GEN	RR	
Job Briefing Employee Name/Title	NA				ompanied ector?	NA	Out Brief Conducted	NA	Time	N	NA Outsid		NA	
Related Reports	N/A					Related CAPS / NA Findings								
Related Rules,	Ref I			Rule	Rule or SOP			Standard		Other / Title		Checklist Reference		ence
SOPs, Standards, or Other														
or other				Ш,										
Inspection Location	Ma Tra	··· I Ya	rd S	tation	осс	RTA Facility	WMSC Office	Track Type	At-grad	e Tu	Tunnel		/ated	N/A
Location				X			X		Х					
Line(s)	AI PI	4 Δ	rack		1	Chain M		F	From			То		
Line(s)	ALIT	''` I	lumber		-	and/or S	tation(s)							
	Hea	d Car Nun	nber	Numbe	er of Car									
Vehicles						Equip	pment							
Description	The WMSC Inspector conducted an inspection of the Service Restoration Station Condition Rollup Report. In preparation for the return to service of Grosvenor - Strathmore (A11), QICO and SAFE assessed station							4						
	read	liness. Ad	ditional	y, Maxir	no main	Recommended Finding?								

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

QICO to identify documented and outstanding items. A risk rating was assigned for all discrepancies identified during field assessments. Remedial Action Required? No Due to COVID-19 and social distancing, this inspection was completed without entering Grosvenor - Strathmore (A011) and without interacting with any Metrorail personnel. Discrepancies Identified for further review and follow up: Multiple platform edge warning ADA bumpy tiles sticking up, missing grout between quarry tiles (Multiple locations track 1 and track 2) Risk – Moderate (4,3) – PLNT Third rail coverboards missing Track 1 - 550+00 - 568+00 Risk - Elevated (5,3) - TRPM Recommended Reinspection? Yes Furniture/supplies stored in customer restroom Risk – Moderate (3,3) – PLNT

Form WMSC-IR-1 Version date: 10/5/18

2



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date 07/14/20
Inspector in Charge – Name Bruce Walker	Inspection Team Bruce Walker	

Form WMSC-IR-1 Version date: 10/5/18