

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Increation Date	YYYY MM		DD	Damant Number	20200715-WMATA-LBW-1					
Inspection Date	2020	07	15	Report Number	20200713-0010	VIATA-L	AIA-LDVV-I			
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Operations Sub- Department		Stations			
	1	Name		Email	Office Phone		Mobile Phone			
Rail Agency Department Contact Information										
Contact Information										
Inspection Location	Judiciary Sc	quare (B02)			l					

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	RTRA-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	2					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1	Insp Subj	ection ject		Station	n Assessment – Judiciary Square (B02)				Activity Code		RTRA		GEN	RR
Job Briefing Employee Name/Title	NA					Accompanied Inspector?		NA	Out Brief Conducted	NA	Time NA		NA Outside Shift		NA
Related Reports	N/A					Related CAPS / Findings			NA						
Related Rules,	Ref			Rule or SOP			Standard		Other / Title			Checklist Reference		ence	
SOPs, Standards, or Other															
Inspection Location	Ma Tra		Yard	Stat	tion OCC		RTA Facility	WMSC Office	Track Type	At-grad	e Tur	Tunnel		vated	N/A
Location			X		(X		Х					
Line(s)	BRAVO Track Number 18			1 &	Chain Marker and/or Station(s)			From			То				
Vehicles	Head Car Number Number of Cars Equipment							•							
Description	The WMSC Inspector conducted an inspection of the Service Restoration Station Condition Rollup Report. In preparation for the return to service of Judiciary Square (B02), QICO and SAFE assessed station readiness. Additionally, Maximo maintenance records were queried by QICO to identify documented and outstanding items. A risk rating was assigned for all Recommended Finding? No.								2						
					_		risk rating sessments.	_	Reco	Recommended Finding? No				No	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Due to COVID-19 and social distancing, this inspection was completed **Remedial Action Required?** No without entering Judiciary Square (B02) and without interacting with any Metrorail personnel. Discrepancies Identified for further review and follow up: Concrete wall cracked/leaking (east entrance tunnel Mezzanine Risk - Moderate (3,3) - TRST 6/24/20, 8:56 AM Recommended Yes Reinspection? Elevator (B02N02) camera not displaying in Kiosk (Mezz #22) Risk - Moderate (3,3) - COMM 6/24/20, 9:31 AM The Inspector recommends reinspection of Judiciary Square (B02) to reassess the discrepancies identified in this report and open work orders.

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature	Date 07/15/20		
Inspector in Charge — Name Bruce Walker	Inspection Team Bruce Walker		

Form WMSC-IR-1 Version date: 10/5/18

Remedial Action

N/A

2