

# **Inspection Form**

### Form WMSC-IR-1

# Washington Metrorail Safety Commission

#### Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200721-WMATA-TKS-1				
	2020	07	21	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRPM Sub- Department				
Rail Agency Department Contact Information	Name			Email	Office Phone		Mobile Phone		
Inspection Location	D-Line, New	Carrollton (D1	3)						

#### **Inspection Summary**

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-GEN-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required <sup>1</sup>	No					
Recommended Reinspection	No					

#### **Activity Summary**

Inspection Activity #	1 I	Inspection Sub	ject	Virtual In	spectio	n – Batter	y Room PMI	I	Activity Code		TP		GEN	OBS
Job Briefing Employee Name/Title	WMATA TRPM Personnel				Accompanied Inspector?		N/A	Out Brief Conducted	N/A	Time	1800 220		utside Shift	No
Related Reports	N/A				Related CAPS / Findings N//			N/A						
	Ref		R	tule or SC	OP		Standard		Other / T	itle		Checkl	ist Refer	ence
Related Rules, SOPs, Standards, or Other	"PREVENTIVE MAINTENANCE INSPECTION FOR BATTERY MAINTENANCE 84 DAY INSPECTION" REVISION 1, AUGUST 22, 2011 MSRPH													
	Main			tion OCC		RTA Facility	WMSC Office		At-grade	e Tu	nnel	Eleva	ted	N/A
Inspection Location			х					Track Type						х
Line(s)	D-Line	Track		N/A	Chain Marker			From			То			
Line(s)	D-Line	Number		IN/A		and/or Station(s)		New Carrollton TPSS (D13)		New Carrollton TPSS (D13)				
Vehicles	Head Car Number		Nu	Number of Cars		Equipment Equipment		NI/A						
venicies	N/A			N/A				N/A						
					inspection of the job safety briefing via			iefing via	Number of Defects			0		0
Description	Traction Power Maintenance's (TRP				1) job safety briefing forms.				Recommended Finding?				No	
									Remedia	Remedial Action Required?				No

Form WMSC-IR-1 Version date: 10/5/18

1



## **Inspection Form**

### Form WMSC-IR-1

## Washington Metrorail Safety Commission

	The WMSC inspector did not note any defects with the Job Safety Briefing.  WMSC inspector performed a virtual inspection of the battery room PMI conducted at New Carrollton Yard Traction Power Substation (TPSS) (D13) via test sheets provided by TRPM.  The WMSC inspector did not note any defects.	Recommended Reinspection?	No
Remedial Action	N/A		

<sup>&</sup>lt;sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

are sufficient and effective.							
Inspector in Charge - Signature		Date					
		ļ					
Inspector in Charge – Name	Inspection Team						
Tino Sahoo	Tino Sahoo						

Form WMSC-IR-1 Version date: 10/5/18