

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200728-WMATA-KEK-10					
mapection bate	2020	07	28	Report Number	20200728-WWATA-KEK-10					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Signals & ATC	Sub- Department ATCIN		ATCIN		
Rail Agency Department	ı	Name		Email	Office Phone		Mobile Phone			
Contact Information										
Inspection Location A99 Shady Grove Yard – ATCS-TSSM - Location #1136										

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-RR-QAI					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	3					
Recommended Finding	YES					
Remedial Action Required ¹	YES					
Recommended Reinspection	YES					

Activity Summaries

Inspection Activity #	1	Inspection Subject Records			s Reviev	Review – Q&A for Compliance				Activity Code		C	RR	QAI	
Job Briefing Employee Name/Title	None Required			Accompanied Inspector?		N/A	Out Brief Conducted	N/A	Time	N/	'A	Outside Shift	N/A		
Related Reports	Tri State Oversight – Final Report				Related CAPS / Findings FTA Finding T			OC-ATC-15-002 & FTA Finding TOC-ATC-15-007							
	Ref Rule or S			ОР		Standard			Other / Title			Checklist Reference			
Related Rules, SOPs, Standards, or Other	RWPN	WPM ATCM - 1			1000				MAXIMO			TCR Records			
otaliaaras, or other			ATCM - 3			3000			SAMs Shops						
	Maii Trac		Yard	rd Station		осс	RTA Facility	WMSC Office	Track Type	At-grade	e Tui	nnel	Ele	evated	N/A
Inspection Location			X				X		тгаск туре	x					Interlock
Line/a)	Track			Chain Marker			From			То					
Line(s)	N/A		Numbe	er	r N/A		and/or Station(s)		A99 - CM: 4 + 42 A99			A99 -	- CM: 4 + 42		
			lumber of Cars												
Vehicles	N/A			N/A		Equipment		Test Equipment Inventory							

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY ELAENE KENDRICK		JULY 28, 2020
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	WMSC	

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	Records Review Inspection – TCR, MAXIMO, & SAMs Shop for consistency	Number of Defects	3						
	throughout.	Recommended Finding?	YES						
	This inspection is an attempt to follow-up with respect to the TOC Triennial								
	Audit of Automatic Train Control (ATC) and Signals Final Report: September 20,	Remedial Action Required?	YES						
	2018. Audit Finding - Control of Precision Measuring and Test Equipment								
	Calibration. TOC reviewed May 14, 2018, which found several pieces of								
	equipment were out of compliance with respect to proper Calibration Control.								
	PURPOSE:		YES						
	To verify that ATCM tools (not to include radios) are calibrated in a timely matter.								
	Assuring that inventory is serviceable, and available according to the TOC's 2015								
	triennial review report. Also assuring that ATCM and Production continue an								
Description	ongoing effort to eliminate unused equipment from inventory.								
	Findings & Deficiency's								
	The 3 department record reports received for inspection differ significantly and	P							
	are not consistent with one another. This gives the appearance that the three	Recommended Reinspection?							
	departments are not in sync with one another with respect to accountability and								
	or scheduling.								
	I am advocating for all 3 departments' (ATCM, FSVT/SAMs Shop, and MAXIMO)								
	assigned personnel to perform (immediately) a physical inspection of all WMATA								
	company assets (Test Equipment) systemwide.								
	All equipment and documentation reports should be thoroughly checked and								
	cross checked across all 3 departments for better accountability. This is extremely								
	important for both accuracy and proper scheduling for calibration of that								
	equipment.								
	1. Instruct the ATCM and Production to perform an immediate asset assess	ment of work equipment at all work	locations, and						
	update MAXIMO and FSVT/SMNT/SAMS Shop of the same.								
Remedial Action	Instruct MAXIMO to correctly update the equipment at all locations for proper identification of current equipment assigned in the field.								
	3. Inform Kenneth Qualls, of the SAMS group to coordinate with managers, supervisors of TCR groups for better accuracy.								

Form WMSC-IR-1 Version date: 10/5/18