



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200803-WMATA-TKS-2			
	2020	08	03					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRPM	Sub- Department		
Rail Agency Department Contact Information	Name		Email		Office Phone		Mobile Phone	
	[REDACTED]		[REDACTED]		[REDACTED]		[REDACTED]	
Inspection Location	E-Line, Prince George's Plaza (E08)							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-GEN-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required¹	No					
Recommended Reinspection	No					

Activity Summary

Inspection Activity #	1	Inspection Subject	Virtual Inspection – AC Switchboard Visual Inspection				Activity Code		TP	GEN	OBS
Job Briefing Employee Name/Title	WMATA TRPM Personnel		Accompanied Inspector?	N/A	Out Brief Conducted	N/A	Time	1000 – 1400	Outside Shift	No	
Related Reports	N/A		Related CAPS / Findings		N/A						
Related Rules, SOPs, Standards, or Other	Ref	Rule or SOP		Standard		Other / Title		Checklist Reference			
	"PREVENTIVE MAINTENANCE INSPECTION FOR AC OR DC ELECTRICAL FACILITIES AC UNIT SUBSTATIONS AUXILIARY ELECTRICAL ROOMS TRACTION POWER SUBSTATIONS DC TIE BREAKER SUBSTATIONS 14- Day Inspection" REVISION 3, AUGUST 05, 2011										
	MSRPH										
Inspection Location	Main Track	Yard	Station	OCC	RTA Facility	WMSC Office	Track Type	At-grade	Tunnel	Elevated	N/A
			X						X		



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Line(s)	E-Line	Track Number	N/A	Chain Marker and/or Station(s)	From	To
					PG Plaza (E08) AC SWBD RM #1 PG Plaza (E08) AC SWBD RM #2	PG Plaza (E08) AC SWBD RM #1 PG Plaza (E08) AC SWBD RM #2
Vehicles	Head Car Number	Number of Cars		Equipment	N/A	
	N/A	N/A				
Description	WMSC inspector performed a virtual inspection of the job safety briefing via Traction Power Maintenance's (TRPM) job safety briefing forms. The WMSC inspector did not note any defects with the Job Safety Briefing.				Number of Defects	0
					Recommended Finding?	No
	WMSC inspector performed a virtual inspection of the AC Switchboard Visual Room Inspection PMI conducted at PG Plaza (E08) AC SWBD RM #1 and #2 via test sheets provided by TRPM. The WMSC inspector did not note any defects.				Remedial Action Required?	No
					Recommended Reinspection?	No
Remedial Action	N/A					

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge - Signature	Date		
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">Inspector in Charge – Name Tino Sahoo</td> <td>Inspection Team Tino Sahoo</td> </tr> </table>	Inspector in Charge – Name Tino Sahoo	Inspection Team Tino Sahoo	
Inspector in Charge – Name Tino Sahoo	Inspection Team Tino Sahoo		