

# **Inspection Form**

### Form WMSC-IR-1

### Washington Metrorail Safety Commission

#### Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200817-WMATA-LBW-1				
inspection Date	2020	08	17	Report Number	20200617-WWATA-LBW-1				
Rail Agency Name				Rail Agency Department	Operations	Sub- Department		Stations	
	1	Name		Email	Office Phone		Mobile Phone		
Rail Agency Department									
Contact Information									
Inspection Location	Archives (F02)								

#### **Inspection Summary**

Inspection Activity #	1	2	3	4	5	6
Activity Code	RTRA-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	3					
Recommended Finding	No					
Remedial Action Required <sup>1</sup>	No					
Recommended Reinspection	Yes					

#### **Activity Summaries**

Inspection Activity #	1 Inspection Station			n Asses	Assessment – Archives (F02)				Activity Code		RA	GEN	RR	
Job Briefing Employee Name/Title	NA				Accompanied Inspector?		NA	Out Brief Conducted	NA	Time	N/	4	Outside Shift	NA
Related Reports	N/A	N/A				Related CAPS / NA Findings								
Related Rules,	Ref			Rule o	r SOP	SOP Standard			Other / Title			Checklist Reference		
SOPs, Standards, or Other														
Inspection Location	Ma Tra	Var	d Sta	ation	осс	RTA Facility	WMSC Office	Track Type	At-grad	e Tui	nnel	Eleva	ted	N/A
Location				X			Х		Х					
Line(s)	Delta	a lii	ack umber			Chain Ma and/or St		F	rom				То	
Vehicles	Hea	d Car Num	per	Number	of Cars		ment							
	Stati		n Rollu	p Report	. In pre	paration f	or the retu	ce Restoration curn to service Number of Defects 3					3	
Description	iden	tionally, M tify docum II discrepa	ented a	nd outst	anding i	tems. A ri	sk rating w	QICO to as assigned	Recommended Finding? No			No		

Form WMSC-IR-1 Version date: 10/5/18



## **Inspection Form**

### Form WMSC-IR-1

## Washington Metrorail Safety Commission

	Due to COVID-19 and social distancing, this inspection was completed without entering Archives (F02) and without interacting with any Metrorail personnel.	Remedial Action Required?	No
	Discrepancies Identified for further review and follow up:  1. Multiple electrical covers protruding from the platform (Platform adjacent to multiple benches) Risk – Moderate (3,3) – LVEM  2. Station map glass panel cracked and loose (Adjacent to Kiosk) Risk – Moderate (4,3) – PLNT  3. Sound from the speakers not clear and hard to hear (Multiple speakers throughout the station) Risk – Moderate (3,3) – COMM The Inspector recommends reinspection of Archives (F02) to reassess the discrepancies identified in this report and open work orders.	Recommended Reinspection?	Yes
Remedial Action	N/A		

<sup>&</sup>lt;sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date 08/17/20
Inspector in Charge – Name Bruce Walker	Inspection Team Bruce Walker	

Form WMSC-IR-1 Version date: 10/5/18