

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY MM DD		Report Number	20200818-WMATA-LBW-1					
inspection date	2020	08	18	Report Number	ZUZUUOIO-VVIVIATA-LBVV-I				
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	Operations Sub-Department Sta		Stations		
	1	Name		Email	Office Phone		Mobile Phone		
Rail Agency Department									
Contact Information									
Inspection Location	Cheverly (D11)								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	RTRA-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	7					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1 Inspection Statio			Station	n Assessment – Cheverly (D11)				Activity Code		RTRA		GEN	RR	
Job Briefing Employee Name/Title	NA				Accompanied Inspector?		NA	Out Brief Conducted	NA	Time	N/	A	Outside Shift	NA	
Related Reports	N/A Related CAF Findings						•	1	NA						
Related Rules,	Ref Rule o			Rule or	SOP		Standard	ndard		Other / Title		Checklist Reference			
SOPs, Standards,															
or Other															
Inspection Location	Ma Tra		Yard	Stati	ion C	СС	RTA Facility	WMSC Office	Track Type	At-grad	e Tu	nnel	Eleva	ated	N/A
Location				X				X		X					
Line(s)	Delta Track			Chain Marker F			rom			То					
Line(s)	Number				and/or Station(s)										
Vehicles	Head Car Number Number of Cars Equipment														
Description	The WMSC Inspector conducted an inspection of the Service Restoration Station Condition Rollup Report. In preparation for the return to service of Cheverly (D11), QICO and SAFE assessed station readiness. Number of Defects							7							
	Addi	itiona	ally, Maxin	no ma	intenan	ce reco	ords were	queried by	QICO to	Recommended Finding?				No	

Form WMSC-IR-1 Version date: 10/5/18



Form WMSC-IR-1

Washington Metrorail Safety Commission

identify documented and outstanding items. A risk rating was assigned for all discrepancies identified during field assessments.

Due to COVID-19 and social distancing, this inspection was completed without entering Cheverly (D11) and without interacting with any Metrorail personnel.

Discrepancies Identified for further review and follow up:

 Temporary platform edge supports in place – Track 1 and Track 2 beneath the platform in multiple locations Risk – Elevated (4,3) – TRST



 Multiple Train Approach Warning (TAW) lights out Risk – Low (2,4) – LVEM



 Multiple edge warning ADA (bumpy tiles) missing/broken Track 1 North End

Risk - Low (2,4) - PLNT



 Multiple public address system speakers missing (Platform canopy Track 1 and Track 2) Remedial Action Required? No

Recommended Reinspection?


Yes

Form WMSC-IR-1 Version date: 10/5/18



Form WMSC-IR-1

Washington Metrorail Safety Commission




Form WMSC-IR-1 Version date: 10/5/18 Risk – Elevated (4,3) – LVEM

3



Form WMSC-IR-1

Washington Metrorail Safety Commission



¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

are sufficient and effective.								
Inspector in Charge — Signature		Date 08/18/20						
Inspector in Charge – Name	Inspection Team							
Bruce Walker	Bruce Walker							

Form WMSC-IR-1 Version date: 10/5/18

4