

# **Inspection Form**

### Form WMSC-IR-1

### Washington Metrorail Safety Commission

#### Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20200903-WMATA-LBW-1					
Inspection Date	2020	09	03	Report Number	20200303-WWATA-LBW-1					
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	Operations	Sub- Department		Stations		
	1	Name		Email	Office Phone		Mobile Phone			
Rail Agency Department Contact Information		<u> </u>								
Contact Information										
Inspection Location	McLean (N	01)	·							

#### **Inspection Summary**

Inspection Activity #	1	2	3	4	5	6
Activity Code	RTRA-GEN-RR					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	9					
Recommended Finding	No					
Remedial Action Required <sup>1</sup>	No					
Recommended Reinspection	Yes					

#### **Activity Summaries**

Inspection Activity #	1 Inspection Statio			Station	n Assessment – McLean (N01)				Activity Code		RTRA		GEN	RR	
Job Briefing Employee Name/Title	NA				Accompanied Inspector?		NA	Out Brief Conducted	NA	Time	N/	A	Outside Shift	NA	
Related Reports	N/A					Related CAPS / NA Findings			NA						
Related Rules,	Ref Rule o			Rule or !	SOP Standard				Other / Title			Checklist Reference			
SOPs, Standards,															
or Other															
Inspection Location	Ma Tra		Yard	Statio	on O	СС	RTA Facility	WMSC Office	Track Type	At-grad	e Tu	nnel	Eleva	ated	N/A
Location				X				X			Х				
Line(s)	Nove	mber	Track				Chain Ma	rker	F	rom			То	То	
Line(s)	Nove	ilibei	Numb	er			and/or St	tation(s)							
Vehicles	Hea	d Car I	Number	Nu	umber o	of Cars		ment							
Description	Stati of M	on Co IcLean	ndition R (N01), Q	ollup F ICO an	Report. nd SAFE	In pre assess	paration for ed station	or the retu readiness.	ice Restoration eturn to service Number of Defects 1					1	
Additionally, Maximo maintenance r					ce reco	ords were	queried by	QICO to	Recommended Finding?			-	No		

Form WMSC-IR-1 Version date: 10/5/18



## **Inspection Form**

### Form WMSC-IR-1

### Washington Metrorail Safety Commission

	identify documented and outstanding items. A risk rating was assigned		
	for all discrepancies identified during field assessments.		
	Due to COVID-19 and social distancing, this inspection was completed	Remedial Action Required?	No
	without entering McLean (N01) and without interacting with any		
	Metrorail personnel.		
	Discrepancies Identified for further review and follow up:		
	<ol> <li>Handrail lights out – stairway adjacent to escalator NO1X02</li> </ol>		
	Risk – Low (2,2) – LVEM  C8/07/2020 12:42:12  The Inspector recommends reinspection of McLean (N01) to reassess the discrepancy identified in this report and open work orders.	Recommended Reinspection?	Yes
Pomodial Action	N/A		

<sup>&</sup>lt;sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature	Date 09/03/20	
Inspector in Charge – Name Bruce Walker	Inspection Team Bruce Walker	

Form WMSC-IR-1 Version date: 10/5/18