

## **Inspection Form**

## Form WMSC-IR-1

## Washington Metrorail Safety Commission

#### Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20201106-WMATA-TKS-1				
	2020	11	06	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRPM Sub- Department				
Rail Agency Department Contact Information	Name			Email	Office Phone		Mobile Phone		
Inspection Location	G-Line, Capit	ol Heights (G0	2) Chiller Plant						

#### **Inspection Summary**

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-GEN-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required <sup>1</sup>	No					
Recommended Reinspection	No					

#### **Activity Summary**

Inspection Activity #	1 li	nspection Sub	ject V	Virtual Inspection – AC Syst			stems Chiller	Plant PMI	Activity Code		TP		GEN	OBS
Job Briefing Employee Name/Title	WMATA TRPM Personnel				Accompanied Inspector?		N/A	Out Brief Conducted	N/A	Time	100 140	-	Outside Shift	No
Related Reports	N/A				Related CAPS / Findings N/A			N/A						
	Ref Rule or			le or SOP	SOP Stand		Standard		Other / Title			Checklist Reference		ence
Related Rules, SOPs, Standards, or Other	DISTRIB MOTOR CENTER 364 DAY	NANCE	AS, ERS											
	Main Track	Yard	Station	occ		RTA acility	WMSC Office		At-grade	e Tu	nnel	Elev	vated	N/A
Inspection Location						x		Track Type						х
Line/e)	Clina	Track		1/4	Chain Mark		ker		From		То			
Line(s)	G-Line Number		er	N/A		and/or Station(s)		Capitol Heights (G02) Chiller Plnt Capitol Heights (G02) Chille				Chiller Plant		
	Head (	Car Number	Nur	umber of Cars										
Vehicles		N/A		N/A		Equip	ment	N/A						

Form WMSC-IR-1 Version date: 10/5/18



# **Inspection Form**

## Form WMSC-IR-1

## Washington Metrorail Safety Commission

	WMSC inspector performed a virtual inspection of the job safety briefing via	Number of Defects	0
	Traction Power Maintenance's (TRPM) job safety briefing forms.	Recommended Finding?	No
	The WMSC inspector did not note any defects with the Job Safety Briefing.	Remedial Action Required?	No
Description	WMSC inspector performed a virtual inspection of the chiller plant AC distribution systems, motor control centers (MCCs) and starters PMI conducted at Capitol Heights (G02) Chiller Plant via test sheets provided by TRPM.  The WMSC inspector did not note any defects.	Recommended Reinspection?	No
Remedial Action	N/A		

<sup>&</sup>lt;sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

are sufficient and effective.		
Inspector in Charge - Signature		Date
Inspector in Charge - Name	Inspection Team	
Tino Sahoo	Tino Sahoo	
Tillo Salloo	Tillo Salloo	

Form WMSC-IR-1 Version date: 10/5/18