

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20210117-WMATA-TKS-1				
Inspection Date	2021	01	17	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	TRPM Sub- Department				
		Name		Email	Office Phone		Mobile Phone		
Rail Agency Department Contact Information		L							
Inspection Location	B-Line, Brookland (B05) Tie-Breaker Station (TBS), Brookland								

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	TP-GEN-OBS					
Inspection Units	1					
Inspection Subunits	1					
Defects (Number)	0					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	No					

Activity Summary

Inspection Activity #	1	Inspec	tion Sub	ject	Virtua	Inspect	Inspection – Breaker PMI			Activity C	Activity Code		GEN	OBS
Job Briefing Employee Name/Title	WMATA TRPM Personnel				Accompanied Inspector?		Out Brief Conducted	N/A	Time	1000 1400		- No		
Related Reports	N/A				Related CAPS / Findings N/A			N/A					·	
	Ref R			Rule or SOP			Standard	Standard		Other / Title		Checklist Reference		
Related Rules, SOPs, Standards, or Other	"PREVENTIVE MAINTENANCE INSPECTION FOR NDC HIGH SPEED 750 VDC CIRCUIT BREAKER Annual Inspection" REVISION 2, 06/20/2013 MSRPH		2											
	Main Track		Yard	Stati	on	осс	RTA Facility	WMSC Office	T1-T	At-grad	e Tu	nnel	Elevated	N/A
Inspection Location	Inspection Location						X		Track Type					x
							al				From		То	
Line(s)	B-Line		Track Number	er	N/A	N/A Chain Marker and/or Station(s) Brook		Brookland (E	d (B05) TBS Brook			kland (B05) TBS		
	Head Car Number			1	Number of Cars									
Vehicles		N/A		N/A Equipment N/A		Equ	iipment	N/A						

Form WMSC-IR-1 Version date: 10/5/1

Version date: 10/5/18 1



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	WMSC inspector performed a virtual inspection of the job safety briefing by	Number of Defects	0
	reviewing the Traction Power Maintenance's (TRPM) job safety briefing forms	Recommended Finding?	No
	provided for each inspection.	Remedial Action Required?	No
Description	The WMSC inspector did not note any defects with the Job Safety Briefing. WMSC inspector performed a virtual inspection of the feeder breakers PMI conducted at Brookland (B05) Tie-Breaker station via test sheets provided by TRPM. The WMSC inspector did not note any defects.	Recommended Reinspection?	No
Remedial Action	N/A		

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

are sufficient and effective.							
Inspector in Charge - Signature	Date						
Inspector in Charge - Name	Inspection Team						
Tino Sahoo	Tino Sahoo						
Tino Sanoo	Tino Sanoo						

Form WMSC-IR-1 Version date: 10/5/18