

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20210309-WMSC-RRD-1				
mspection bate	2021	02	02	Report Number	20210309-001	MINISC-KUD-1			
Rail Agency Name	Washing Transit A	ton Metropo uthority	litan Area	Rail Agency Department	WMATA-SAFE Sub- Department Fire marshal			Fire marshal	
	Name			Email	Office Phone		Mobile Phone		
Rail Agency Department Contact Information									
Inspection Location	F05 - Navy Yard-Ballpark Station, 1201 New Jersey Avenue, SE, Washington 20003								

Inspection Summary

		I			ı	
Inspection Activity #	1	2	3	4	5	6
Activity Code	SAFE-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	7					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1 Inspection Subject F05 - Navy Yar				avy Yaro	Yard-Ballpark Station			Activity Code		SAFE		GEN	RR
Job Briefing Employee Name/Title	N/A			Accor Inspe	mpanied ctor?	No	Out Brief Conducted	No	Time	N/	Ά	Outside Shift	No	
Related Reports					Related CAPS / Findings									
	Ref Rule o			Rule or S	e or SOP Standard				Other / Title			Checklist Reference		
Related Rules, SOPs, Standards, or Other	National Fire Protection Association		ion			NFPA, IFC								
						See code sections below								
Inspection Location	Main Track	Yard	Stat	tion (осс	RTA Facility	WMSC Office	Track Type	At-grad	e Tu	nnel	Ele	evated	N/A
inspection Location			Х	(ттаск туре			X			
Lina/a)	N/A	Track		N/A	N/A Chain Ma		rker		From			То		
Line(s)	IV/A	Number N		IN/A	and/or St		station(s) Station limits		Statio		on limits			
	Head Car Number			Number of Cars										
Vehicles		N/A		N/A	N/A Equipme		ment							

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature RR	Date 03/09/2021		
Inspector in Charge – Name	Inspection Team		
Richard R. David	RRD WMSC		

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	-		
	I. Item Found: Fire alarm panel showing trouble Location: Kiosk	Number of Defects	7
	Mezzanines # 84 & 105 (2) Code Reference: IFC 2015, Section 907.6	Recommended Finding?	No
	Corrective Action: Fix issue causing the trouble Date Opened:	Remedial Action Required?	No
	12/2/2021 Date Closed: Open Follow-up Inspection Date: 3/2/2021		
	2. Item Found: Obstructed means of egress Location: Elevator Machine Room Corridor # 503 Code Reference: IFC 2015, Section 1031.3 Corrective Action: Remove obstruction 55-gal drum, ladder etc. Opened: 2/2/2021 Date Closed: Open Follow-up Inspection Date: 03/02/2021		
	3. Item Found: Extension cords as permanent wiring Location: Fire Equipment corridor on mezzanine level Code Reference: IFC 2015, Section 605.5 Corrective Action: Remove cord as permanent wiring Date Opened: 2/2/2021Date Closed: Open Follow-up Inspection Date: 3/2/2021		
	4. Item Found: Obstructed means of egress Location: Mechanical Equipment Room 106 Code Reference: IFC 205, Section 1031.3 Corrective Action: Repair spalling concrete floor, tripping hazard Date Opened: 2/2/2020 Date Closed: Open Follow-up Inspection Date: 3/2/2021		
Description	5. Item Found: Obstruction of Egress Ladder Location: Mechanical Room #106 Code Reference: IFC 2015, Section 1031.3, Corrective Action: Remove ladder Date Opened: 2/2/2021 Date Closed: Open Follow-up Inspection Date: 3/2/2021	Recommended Reinspection?	Yes
	6. Item Found: Knox Box is inside of gate Location: New Jersey & M and M St. and Half St., SE Room # 110 (2) Code Reference: IFC 2015, Section 506 Corrective Action: Box should be on the outside of the gate Date Opened: 2/2/2021 Date Closed: Open Follow-up Inspection Date: 3/2/2021		
	7. Item Found: Junction/Cable Box cover plate is missing Location: Room # 110 <mark>Code Reference: NFPA 70</mark> Corrective Action: Secure cover plate Date Opened: 2/2/2021 Date Closed: Open Follow-up Inspection Date: 3/2/2021		
	Due to Covid-19 social distancing, this inspection was done remotely. I concur with the findings of this complete station inspection. Items assigned to the appropriate departments and should be corrected by 3/2/2021. This inspection status is open and there are critical fire life safety elements that failed and need to be corrected. In this inspection there is a fire alarm panel showing trouble, and the Knox box is mounted in the wrong location.		
Remedial Action	None		

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections

Inspector in Charge – Signature RRD.		Date 03/09/2021
Inspector in Charge – Name	Inspection Team	
Richard R. David	RRD WMSC	

Form WMSC-IR-1 Version date: 10/5/18