

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20210329-WMSC-RRD-2					
mspection bate	2021	02	01	Report Number	20210323-WIVI3C-RRD-2					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	WMATA-SAFE	Sub- Department Fire marshal		Fire marshal		
	Name			Email	Office Phone		Mobile Phone			
Rail Agency Department Contact Information										
Inspection Location	F09 Naylor Road Metro Station 3101 Branch Avenue, Temple Hills, MD 20748									

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	SAFE-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	4					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1	Inspec	tion Subj	ect	F09 Naylor Road Metro Sta			ation		Activity Code		SAFE		GEN	RR
Job Briefing Employee Name/Title	N/A				Accor	mpanied ector?	No	Out Brief Conducted	No	Time	N/	Ά	Outside Shift	No	
Related Reports				Related CAPS / Findings									•		
	Ref			Rule or SOP			Standard		Other / Title			Checklist Reference			
Related Rules, SOPs, Standards, or Other	Nation Fire Protection Agency					NFPA	IFPA								
						See code sections below									
Inspection Location	Mai Trac		Yard	ard Station		осс	RTA Facility	WMSC Office	Track Type	At-grade	e Tui	Tunnel		evated	N/A
inspection Location				X					таск туре					x	
				From			То								
Line(s)	N/A		Track Numbe	er	N/A Chain Mai and/or St			Station limits			Station limits				
Vehicles	Hea	d Car N	umber	1	Number of Cars N/A Equip										
		N/A					Equip	ment							

Form WMSC-IR-1 Version date: 10/5/18



Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

	1. Item Found: Fire alarm panel showing trouble Location: Kiosk Code Reference: NFPA 1, 2015, Section 4.5.8.1 Corrective Action: Fix issue	Number of Defects	4
	that is causing the trouble Assigned To: COMM Work Order #:	Recommended Finding?	No
	16141055 Date Opened: 2/1/2021 Date Closed: Open Follow-up Inspection Date: 3/1/2021	Remedial Action Required?	No
Description	2. Item Found: Exit lights not illuminated properly Location: Throughout the first floor (3) Code Reference: NFPA 1, 2015 Section 4.4.3.2.3 Corrective Action: Re-lamp and/or Repair/Replace the exit lights Assigned To: Low Voltage Work Order #: 16141058 Date Opened: 2/01/2021 Date Closed: Open Follow-up Inspection Date: 3/1/2021 3. Item Found: Egress obstruction-broken/unlevel concrete landing Location: At exterior of rear door, north side Code Reference: NFPA1, 2015, Section 14.4.1 Corrective Action: Repair unlevel loose/broken concrete landing Date Opened: 2/1/2021 Date Closed: Open Follow-up Inspection Date: 03/1/2021 4. Item Found: Knox Box located inside gate Location: Inside of main entrance Corrective Action: Relocate Knox box Date Opened: 2/1/21 Date Closed: Open Follow-up Inspection Date: 3/1/2021 Due to Covid 19 social distancing, this inspection was done remotely. I concur with the finding of this complete inspection of Naylor Road Metro Station. Items were assigned to the appropriate departments	Recommended Reinspection?	Yes
	and should be corrected by 3/1/2021. This inspection status is open and there are critical fire life safety elements that failed and need to be corrected. Noted in this inspection is the failure of a fire alarm system.		
Remedial Action	None		

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections

Inspector in Charge – Signature RRD.		Date 03/29/2021
Inspector in Charge – Name	Inspection Team	
Richard R. David	RRD WMSC	

Photos:

Form WMSC-IR-1 Version date: 10/5/18