

Form WMSC-IR-1

Washington Metrorail Safety Commission

Agency/Department Information

Inspection Date	YYYY MM DD		Report Number	20210408-WMSC-RRD-1				
Inspection Date	2021	03	25	Report Number	20210408-WW3C-RRD-1			
Rail Agency Name	Washington Authority	Metropolitan	Area Transit	Rail Agency Department	SAFF Sub- Department		Fire Marshal's Office	
	Name		Email	Office Phone		Mobile Phone		
Rail Agency Department Contact Information								
Inspection Location	A90 Shady Grove Rail Yard 15903 Somerville Drive, Silver Spring, MD							

Inspection Summary

Inspection Activity #	1	2	3	4	5	6
Activity Code	SAFE-GEN-RR					
Inspection Units	1					
Inspection Subunits	0					
Defects (Number)	27					
Recommended Finding	No					
Remedial Action Required ¹	No					
Recommended Reinspection	Yes					

Activity Summaries

Inspection Activity #	1	Inspec	tion Sub	ject	A90 Shady Grove Rail Yard				Activity Co	ode	SAFE		GEN	RR	
Job Briefing Employee Name/Title	N/A					mpanied ector?	No	Out Brief Conducted	No	Time	N/	Α	Outside Shift	No	
Related Reports						Relat	ted CAPS /	Findings							
	Ref				Rule or SOP		Standard		Other / Title			Checklist Reference			
Related Rules, SOPs,	Interr	nation F	ire Code					IFC							
Standards, or Other								See code s	ections below						
Inspection Location	Mai Trac		Yard	Stati	on (осс	RTA Facility	WMSC Office	Track Type	At-grade	e Tui	nnel	Ele	evated	N/A
inspection Location			x						паск туре	x	х				
								From			То				
Line(s)	N/A		Track Numbe	er	N/A	Chain Marker and/or Station(s) Rail Yard limit			ts		Rail Y	ard lii	mits		
Vehicles	Hea	ıd Car N	lumber	I	lumber	of Cars									
		N/A N/A		A	Equip	ment									

Form WMSC-IR-1 Version date: 10/5/18



Form WMSC-IR-1

Washington Metrorail Safety Commission

1 Item Found: Faults and Troubles shown on Fire Alarm Panel Location: Main	Number of Defects	27
entrance Fire Alarm Control Panel Deficiency: IFC 901.6 Corrective Action:	Recommended Finding?	No
Emimate June and troubles rissigned to Commit Work Grace in 10240123 Bute	Remedial Action Required?	No
open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021 2. Item Found: Missing fire department connection signage Location: Exterior fire department connection Deficiency: IFC 912.5 Corrective Action: Install approved signage Assigned to: PLNT Graphics Work Order #: 16246159 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021 3. Item Found: Open Junction Boxes Location: Fan room adjacent Bay 7S Deficiency: IFC 605.1 Corrective Action: Install junction box covers Assigned to: COMM Work Order #: 16246124 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021 4. Item Found: Incompatible storage Location: 1st floor compressed gas storage area Deficiency: IFC 5003.5 Corrective Action: Provide 20 separation of compressed gas Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021 5. Item Found: Incomplete / faded signage Location: Throughout facility Deficiency: IFC 5003.5 Corrective Action: Re-establish hazard ranking numbers Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021 6. Item Found: Missing protective caps Location: Compressed gas storage area Deficiency: IFC 5303.6 Corrective Action: Replace missing caps Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021	Recommended Reinspection?	Yes

Form WMSC-IR-1 Version date: 10/5/18



Form WMSC-IR-1

Washington Metrorail Safety Commission

- 13. Item Found: Obstructions within the means of egress Location: Stair #2
 Deficiency: IFC 1031.2 Corrective Action: Remove all storage from stairway
 Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open
 Follow Up Inspection Date: 4/25/2021
- 14. Item Found: Incorrect signage Location: Loading dock storage Deficiency: IFC 5003.5 Corrective Action: Provide correct signage for oxygen storage. Remove flammable material signage Assigned to: Stock Room Work Order #: 16246163 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 15. Item Found: Improper use of extension cords Location: Loading dock entrance Deficiency: IFC 605.5 Corrective Action: Remove extension cords Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 16. Item Found: Accumulation of trash and debris Location: Loading dock entrance Deficiency: IFC 304.1 Corrective Action: Relocate all pallet storage to exterior of bldg. Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 17. Item Found: Damaged fire door Location: Stair #5 Deficiency: IFC 703.2
 Corrective Action: Replace broken door closer Assigned to: PLNT Work Order #:
 16246161 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date:
 4/25/2021
- 18. Item Found: Electrical hazard Location: Mechanical Room #1 Deficiency: IFC 605.1 Corrective Action: Replace missing junction box cover Assigned to: POWER Work Order #: 16246138 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 19. Item Found: Accumulation of trash and debris Location: Lower level storage area adjacent to electric panel 5S Deficiency: IFC 304.1 Corrective Action: Remove all storage, trash, and debris Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 20. Item Found: Improperly installed LPG Cylinder Location: Lower-level folk lift Deficiency: IFC 6105.1 Corrective Action: Correctly install cylinder Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 21. Item Found: Missing NFPA 704 warning signage Location: Lower-level cabinet next to Cage #1 Deficiency: IFC 5003.5 Corrective Action: Install approved signage Assigned to: Stock Room Work Order #: 16246163 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 22. Item Found: Missing NFPA 704 warning signage Location: Cage 1 Deficiency: IFC 5003.5 Corrective Action: Install approved signage on entrance gate Assigned to: Stock Room Work Order #: 16246163 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 23. Item Found: Missing NFPA 704 warning signage Location: Cage 2 Deficiency: IFC 5003.5 Corrective Action: Install approved signage on entrance gate Assigned to: Stock Room Work Order #: 16246163 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021
- 24. Item Found: Missing NFPA 704 warning signage Location: Stock Room area Deficiency: IFC 5003.5 Corrective Action: Install approved signage on all cabinets Assigned to: Stock Room Work Order #: 16246163 Date open: 3/25/2021 Date close: Open Follow Up Inspection Date: 4/25/2021

Form WMSC-IR-1 Version date: 10/5/18

3



Form WMSC-IR-1

Washington Metrorail Safety Commission

	25. Item Found: Missing NFPA 704 warning signage Location: Stock Room area	
	Deficiency: IFC 5003.5 Corrective Action: Install approved signage on cage	
	Assigned to: Stock Room Work Order #: 16246163 Date open: 3/25/2021 Date	
	close: Open Follow Up Inspection Date: 4/25/2021	
	26. Item Found: Smoking at or within building Location: Stock Room north exit	
	stairway Deficiency: IFC 310.2 Corrective Action: Remove trash & eliminate	
	smoking area Assigned to: Superintendent Q. Gant Date open: 3/25/2021 Date	
	close: Open Follow Up Inspection Date: 4/25/2021	
	Glose, open rollow op hispeedon bute. 4/23/2021	
	27. Item Found: Exit discharge door hard to open Location: Stair #2 Discharge	
	Door Deficiency: IFC 1031.3 Corrective Action: Repair door to open with less than	
	15 lbs. Assigned to: PLNT Work Order #: 16246161 Date open: 3/25/2021 Date	
	,	
	close: Open Follow Up Inspection Date: 4/25/2021	
	This WMSC inspection was done remotely due to Covid 19. I concur with the	
	results of this complete inspection of Shady Grove Rail Yard. This report was	
	conducted by WMATA's Fire Marshal's office and forwarded to WMSC for	
	documentation. The deficiencies are noted and assigned to the appropriate	
	department and should be corrected by the reinspection date 4/25/21. There are	
	fire life safety items that are critical and need to be investigated i.e., Fire Alarm	
	Panel showing trouble.	
Remedial Action	Listed below	

¹ The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections

Inspector in Charge – Signature RRD		Date 4/8/2021
Inspector in Charge – Richard R. David	Inspection Team	

1.Item Found: Exit Light Inoperable Location: Front Door of Building Deficiency: VSFPC 1011.6.2 - Exit Sign Illumination Corrective Action: Exit sign must always be illuminated Assigned to: PLNT Work Order #: 15743762 Date opened: June 15, 2020 Date closed: Open at this time Follow Up Inspection Date: July 15, 2020.

2. Item Found: Exit Light Inoperable Location: Rear Door of Building Deficiency: VSFPC 1011.6.2 - Exit Sign Illumination Corrective Action: Exit sign must always be illuminated Assigned to: PLNT Work Order 15743762 Date open: June 15, 2020 Date close: Open at this time Follow Up Inspection Date: July 15, 2020

Form WMSC-IR-1 Version date: 10/5/18