

**Inspection Form** 

## Washington Metrorail Safety Commission

#### Agency/Department Information

Inspection Data	YYYY/MM/DD	Report Number	20210504-WMATA-LBW-2					
Inspection Date	2021/05/20	Report Number	20210504-WWATA-LBW-2					
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name					
Rail Agency Department	Roadway Worker Protection	Contact Information						
Inspection Location	Rail Operations Control Center 3500 Pennsy Drive Landover, Maryland							
Inspection Summary								
Inspection Activity #		1						
Activity Code		RTRA-GEN-OBS						
Inspection Units		1						
Inspection Subunits	0							
Defects (Number)		0						
Recommended Finding		No						
Remedial Action Required <sup>1</sup>		No						
Recommended Reinspection		No						

## Activity Summaries

Inspection Activity #	1	Insp	ection Sub	ject	Implementation of the RWP Checklist			Activity Code			RTRA-GEN-OBS				
Job Briefing Employee Name/Title				Accompan	ied Inspecto	ır?	Yes	Out Brief Conducted	Yes	<b>Time</b> 0		01:00 PM		Outside Shift	No
Related Reports	NA			Related CAPS / Findings WMSC-CC			WMSC-C0040	•						_	
	Ref Rul			ule or SOP		Standard		Other / Title				Checklist Reference			
Related Rules, SOPs, Standards, or Other	NA TR			DADWAY WORKER PROTECTION ANNING STANDARD OPERATING ROCEDURES Revision 15, Dated: bruary 1, 2021		NA		NA				RWP Student Track Safety Equipment Familiarization Sheet			
Inspection Location	Main Track	Yard	Station	OCC	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunnel			Eleva	ited	N/A	
Line(s) & Track Number	Rail Operations Control Center 3500 Pennsy Drive Landover , Maryland Chain Marker and/o			or Station(s)	From NA			NA	То						
Vehicles	Head Car N/		N	lumber of C NA	Cars	Equipme	ent	NA							
	The WMSC inspector conducted Verification inspection of the Roadway Worker Protection							Number of Defects					(	)	
Description	Level IV class (class code RWPL2B-20210303BLD). The WMSC received a closure request for corrective action C0040. As a final verification prior to closure, the inspector confirmed that the RWP Safety Equipment and Warning Device Familiarization Sheet was being								Recommended Finding?					N	0
									Remedial Action Required?					N	0
	used by the instructor.							Recommended Reinspection?					No		
Remedial Action															




**Inspection Form** 

#### Form WMSC-IR-1

## Washington Metrorail Safety Commission

# Photos:



<sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2021/05/20
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team NA	