

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

- Agental, - Spanning management									
Increation Date	YYYY/MM/DD	Report Number	20210615-WMATA-LBW-01						
Inspection Date	2021/06/15	Report Number							
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name						
Rail Agency Department	RTRA	Contact Information							
Inspection Location	Arlington Cemetery 1000 North Memorial Drive Arlington, Virginia								

Inspection Summary

RR
RR
_

Activity Summaries

Inspection Activity #	1 Inspection Sub			Follow-up Station Readiness Insp			Activity Code			RTRA-GEN-RR					
Job Briefing Employee Name/Title	NA			Accompanied Inspector?			No	Out Brief Conducted	No Time				Outside Shift		
Related Reports	WASHINGTON METROPOLITAN AREA TRANSIT AUTHORITY Department of Safety and Environmental Management Rail Station Inspection Checklist						NA						·		
Related Rules, SOPs, Standards, or Other	Ref NA				Standard NA	Other / Title NA			Rai Ins	Checklist Reference Rail Station Inspection Checklist					
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	acility	WMSC Office	Track Type		t-grade Tunnel		el Ele	vated	N/A	
			Х					X							
Line(s) & Track Number	Arlington Cemetery 1000 North Memorial Drive Arlington, Virginia Chain M			Chain Ma	arker and/	er and/or Station(s)			From NA			То			
Vehicles	Head Car		N	Number of Cars NA Equipment NA											
	Prior to returning the Arlington Cemetery Station to regular operations, a station							Number of Defects					1		
	readiness inspection was conducted by the Department of Safety and Environmental									Recommended Finding?				No	
	Management (SAFE). The WMSC inspector conducted a record review of the inspection. All elevators and escalators are working and in service, all tools, equipment and trash has								Remedial Action Required?					No	
Description	been removed, the Fire Alarm System in operational, and the platform is of all tools and equipment. There was one ADA defect noted on the rail station inspection checklist. The bathrooms at Arlington Cemetery Station will not be functional for the Station reopening. WMATA will keep the ADA compliant Portaâ¿Johns that are located by to Station entrance until the bathrooms are complete. There was no discrepancies identified that would impact revenue service and station re-opening.								Recommended Reinspection?					No	
Remedial Action	iiipact reve	iiue sei vill	. anu statit	on re-open	mg.										

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge's Signature		Date 2021/06/15
Inspector in Charge's Name LeBon Bruce Walker	Inspection Team	

Form WMSC-IR-1 Version date: 1/14/2022