

Inspection Form

Form WMSC-IR-1

Washington Metrorail Safety Commission

Inspection Date	YYYY/MM/DD	Report Number	20220204-WMSC-RRD-1		
	2022/02/07	Report Number			
Rail Agency Name	Washington Metropolitan Area Transit Authority	Rail Agency Department	Name		
Rail Agency Department	SAFE-WI-PI	Contact Information			
Inspection Location	New Carrollton S&I Shop New Carrollton Rail Yard				

Inspection Summary

Inspection Activity #	1
Activity Code	
Inspection Units	
Inspection Subunits	
Defects (Number)	8
Recommended Finding	No
Remedial Action Required ¹	Yes
Recommended Reinspection	Yes

Activity Summaries

Inspection Activity #	1	Insp	ection Subj	ect	New Carr	ollton Ra	ail Yard	Yard Activity Code							
Job Briefing Employee Name/Title	Michael Bru superintend		t	Accompan	ied Inspecto	or? No Out Brief Yes Time					tside hift	No			
Related Reports	Previous S& FLS inspecti		ections	Related CAPS / Findings					•	•		•	•		
Related Rules,	lated Rules.		Rule or SOP				Standard		Other / Title				Checklist Reference		
SOPs, Standards, or Other															
Inspection Location	Main Track	Yard	Station	occ	RTA Fa	acility	WMSC Office	Track Type	At-grade Tunne		el	l Elevated		/A	
		Х												Х	į.
Line(s) & Track Number	New Carrollt Rail Yard	ton S&I Sho	New Car	rollton	Chain Ma	rker and/	or Station(s)	N/A	From T N/A T				То		
William.	Head Car Number N			Number of Cars				Builder of	F						
Vehicles	N/	Ά		N/A		Equipm	ent	Kall Cars Shop	Shop Equipment FLS as:		sets				
Description	WMSC inspectors conducted a combined Railcar/FLS inspection. Covid 19 Safety protocol							Number of Defects					8		
	in place. Good JSB, WMSC inspectors signed in. Fire Alarm system normal. First Aid Kit had inventory sheet and secured. Flammable liquids stored correctly. Proper spill kit								Recommended Finding?					No	
	usage. Blue flags and accountability tags in use. Vehicles were properly chocked. A								Remedial Action Required?					Yes	
	compliance check was in progress during the WMSC visit. S&I shop, and the basement area was clean and well maintained.							Recommended Reinspection?					Yes		
Remedial Action	AED alarm restored to working condition. Fall protection set up for use. Floors in railcars cleaned to prevent slips/falls. Fire extinguisher service tag replaced, and extinguisher checked. Scaffolding sign corrected and door sign ordered. Affix corrected sign appropriately. Fill eye wash stations.														

The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Action. Closeout of Remedial Actions may also	be subject to ongoing winst verification inspections to ensure corrections are sufficient and effective		
Inspector in Charge's Signature	Date 2022/02/07		
Inspector in Charge's Name Richard David	Inspection Team Manny Lopez		